



Photo 11: Driver side floor board as inspected, all weather mat installed



Photo 12: Drivers outboard mat retention hole without retaining hook engaged