

5. Description of Problem

In certain Toyota Highlander and Lexus RX330 vehicles produced at Toyota Kyushu plant, due to the improper installation of the retaining clips for the floor carpet cover, located in front of the center console, there is a possibility that the clips may become loose. If both clips separate from the floor carpet cover, the cover may lean toward the accelerator pedal, causing interference with the accelerator pedal rod. In the worst case, the accelerator pedal may temporarily become stuck in a partially depressed position when returning to the idle position.