

FIELD TECHNICAL REPORT



TQCN DOC# FTR-JTK112971		Affiliate TMS	Dept. QA-Powertrain	Source FTS	Location TMS-CIN	Ref 40179-1	Date 6/18/2007
Problem Area Base Vehicle	Primary Model Camry		Model Year 2007	Production Date 13-Oct-2006	Odometer 3359 mi	VIN (confirm 17 characters): 4T1BE46K47U [REDACTED]	
Condition Title Accelerator Pedal Concern							

Do not type in YELLOW shaded fields - Input data from Web page or RDM:

Repair Date 22-MAR-2007	Optional Ref.	Optional Approval
-----------------------------------	---------------	-------------------

Condition Description

- Customer states accelerator pedal has stuck to the floor two times.
- Technician could not duplicate condition.
- Technician states has cold weather matt installed over carpeted matt.

Diagnostic Steps:

- Technician replaced pedal assembly.

Probable Cause

- Unknown, possible interference with floor matt.

Part # 1: 7811006010	Part # 2:	Part # 3:	Parts Disposition: Have part / will ship	Parts Shipping Destination: 2410
-------------------------	-----------	-----------	---	-------------------------------------

Repair Process

- Pedal assembly replaced, and cold weather matt remove, condition has not reoccurred.

	Part # 1:	Part Description	Qty.	Used Part Value
1	7811006010	SENSOR ASSY, ACCELERATOR PEDAL	1	\$ 23 .00
Comments:				