

From: Gary Heine/=TMS/Toyota.

Sent:5/15/2008 3:27 PM.

To: [-] Tom Steger/=TMS/Toyota@Toyota; Clayton Meyer/=TMS/Toyota@Toyota; Cole Stutz/=TMS/Toyota@Toyota; Andrew Curtin/=TMS/Toyota@Toyota; Mike Robinson/=Mobile/Toyota@Toyota; Jaime Angulo/=TMS/Toyota@Toyota; Craig Parker/=TMS/Toyota@Toyota; John Stover/=TMS/Toyota@Toyota; Tim Davis/=TMS/Toyota; Nobu Takeda/=TMS/Toyota@Toyota; Scott Stewart/=TMS/Toyota.

Cc: [-]

Bcc: [-]

Subject: Fw: Toyota PQSS Executive Summary through May 10, 2008.

Regards,

Gary Heine

Quality Assurance Powertrain Manager

Toyota Customer Services Division

O- 310 468 2521

C- 310 977 0860

F- 310 381 7783

----- Forwarded by Gary Heine/TMS/Toyota on 05/15/2008 03:26 PM -----

"Colacurcio, Joe" <Joe.Colacurcio@nielsen.com>

05/15/2008 03:16 PM

To <greg_bryan@toyota.com>, <gordon_rush@toyota.com>

cc "Randy_Wagner@toyota.com" <'Randy_Wagner@toyota.com'>, "Jeff_Northrup@toyota.com"

<'Jeff_Northrup@toyota.com'>, "craig_erickson@toyota.com" <'craig_erickson@toyota.com'>,

"matt_allen@toyota.com" <'matt_allen@toyota.com'>, "brian_lyons@toyota.com" <'brian_lyons@toyota.com'>,

"Randy_Reida@toyota.com" <'Randy_Reida@toyota.com'>, "Howard_Abrahams@toyota.com"

<'Howard_Abrahams@toyota.com'>, "Russell_Suzuki@toyota.com" <'Russell_Suzuki@toyota.com'>,

"Mike_Robinson@toyota.com" <'Mike_Robinson@toyota.com'>, "Gary_Heine@toyota.com"

<'Gary_Heine@toyota.com'>, "Bob_Nagai@toyota.com" <'Bob_Nagai@toyota.com'>, "Tom_Krembs@toyota.com"

<'Tom_Krembs@toyota.com'>, "michael_jarboe@toyota.com" <'michael_jarboe@toyota.com'>,

<Tom_Kim@toyota.com>, <Charles_Lee@Toyota.com>, "Enzweiler, Julie" <Julie.Enzweiler@nielsen.com>,

"Stephenson, Bill" <Bill.Stephenson@nielsen.com>, "Black, Larry" <Larry.Black@nielsen.com>, "Patak, Elizabeth"

<Elizabeth.Patak@nielsen.com>, "Hamm, Scott" <Scott.Hamm@nielsen.com>

Subject RE: Toyota PQSS Executive Summary through May 10, 2008

Hello,

Attached please find the Toyota Quality Executive Summary report reflecting data from April 27th – May 10th, 2008.

The reporting site (<http://toyota.reports.buzzmetrics.com/main.asp>) has also been updated with the latest information.

Toyota

4Runner Current Generation

Liftgate Problems

Intrusive VSC

4Runner Previous Generation

Engine Drivability Issues

Camry Current Generation

Excessive Rattles

Transmission Vibration

Transmission Hesitation

Car Alarm, Hood Sensor

A/C Smell From Mold

Rear Suspension Noise

Camry Hybrid Current Generation

Excessive Heat with CD Player

Dashboard Rattle

Camry Previous Generation
Steering Noise
Celica Most Recent Generation
Engine Sensors/Drivability Issues
Corolla Current Generation
Poor OEM (Firestone) Tires
Manual Transmission Idle
Difficulty Starting
Clicking Clutch Pedal
Corolla Previous Generation
Potential Transmission Trouble
Difficulty Starting
Highlander Current Generation
Engine Noise/Valve Clatter
Matrix Previous Generation
Door Rust
Prius Current Generation
Traction Control Impedes Travel Up Gravel Hill
Six-Disc CD Changer Is Inoperable
Bad Odor When Using A/C
Static Noise with iPod, iPod Inoperable
Navigation System Interrupts Bluetooth Phone Calls
RAV4 Current Generation
Airbag Deployment
Transmission "Clunk"
RAV4 Previous Generation
"Frame Rust"
Sequoia Previous Generation
Transmission Failures
Tacoma Current Generation
Rear Suspension Bottoming Out
Vehicle Surges Forward
Tacoma Previous Generation
Frame Rust/Buy-Backs
Tundra Current Generation
Paint Problems
Tailgate Weakness
Driveshaft Recall
Lexus
Lexus ES 350 Overall
3.5L V6 Piston Slap
Transmission Issues, Wants Buy-Back
Lexus GS 400 Overall
Noise When Coming to Stop
Lexus IS-F Overall
Auto Downshifting While in Manual Mode
Lexus IS 350 Overall
Interior Rattles
Windshield Crack
TSIB For Auxiliary Audio Input Noise
Lexus LS 460 Overall
Excessive Wind Noise
Brake Hold Does Not Disengage
Gray Spots After Window Tint Removal
Lexus LX 470 Overall
Vibrating Noise While Driving
Lexus RX 300 Overall
Transmission Needs Replacement
Transmission Problem, Solenoid
Lexus RX 400h Overall
Excessive Rattles

Scion
Scion xB Current Generation
O2 Sensor Needs Replacement
Clunk While Slowing Down
Side Pillar Creak

Please feel free to contact us if you have any questions.

Thanks,
Joe Colacurcio
Automotive Industry Analyst
Nielsen Online

The Nielsen Company
50 West RiverCenter Blvd.
Third Floor
Covington, KY 41011

859.905.4936 voice
610.462.3048 mobile
joe.colacurcio@nielsen.com
www.nielsen-online.com