

From: "Colacurcio, Joe" <Joe.Colacurcio@nielsen.com>

Sent: 5/15/2008 3:16 PM.

To: [-] <greg_bryan@toyota.com>; <gordon_rush@toyota.com>

Cc: [-] "Randy_Wagner@toyota.com" <'Randy_Wagner@toyota.com'>; "Jeff_Northrup@toyota.com" <'Jeff_Northrup@toyota.com'>; "craig_erickson@toyota.com" <'craig_erickson@toyota.com'>; "matt_allen@toyota.com" <'matt_allen@toyota.com'>; "brian_lyons@toyota.com" <'brian_lyons@toyota.com'>; "Randy_Reida@toyota.com" <'Randy_Reida@toyota.com'>; "Howard_Abrahams@toyota.com" <'Howard_Abrahams@toyota.com'>; "Russell_Suzuki@toyota.com" <'Russell_Suzuki@toyota.com'>; "Mike_Robinson@toyota.com" <'Mike_Robinson@toyota.com'>; "Gary_Heine@toyota.com" <'Gary_Heine@toyota.com'>; "Bob_Nagai@toyota.com" <'Bob_Nagai@toyota.com'>; "Tom_Krembs@toyota.com" <'Tom_Krembs@toyota.com'>; "michael_jarboe@toyota.com" <'michael_jarboe@toyota.com'>; <Tom_Kim@toyota.com>; <Charles_Lee@Toyota.com>; "Enzweiler, Julie" <Julie.Enzweiler@nielsen.com>; "Stephenson, Bill" <Bill.Stephenson@nielsen.com>; "Black, Larry" <Larry.Black@nielsen.com>; "Patak, Elizabeth" <Elizabeth.Patak@nielsen.com>; "Hamm, Scott" <Scott.Hamm@nielsen.com>

Bcc: [-]

Subject: RE: Toyota PQSS Executive Summary through May 10, 2008.

Hello,

Attached please find the Toyota Quality Executive Summary report reflecting data from April 27th – May 10th, 2008. The reporting site (<http://toyota.reports.buzzmetrics.com/main.asp>) has also been updated with the latest information.

Toyota

4Runner Current Generation

Liftgate Problems
Intrusive VSC

4Runner Previous Generation

Engine Drivability Issues

Camry Current Generation

Excessive Rattles
Transmission Vibration
Transmission Hesitation
Car Alarm, Hood Sensor
A/C Smell From Mold
Rear Suspension Noise

Camry Hybrid Current Generation

Excessive Heat with CD Player
Dashboard Rattle

Camry Previous Generation

Steering Noise

Celica Most Recent Generation

Engine Sensors/Drivability Issues

Corolla Current Generation

Poor OEM (Firestone) Tires

Manual Transmission Idle
Difficulty Starting
Clicking Clutch Pedal

Corolla Previous Generation

Potential Transmission Trouble
Difficulty Starting

Highlander Current Generation

Engine Noise/Valve Clatter

Matrix Previous Generation

Door Rust

Prius Current Generation

Traction Control Impedes Travel Up Gravel Hill
Six-Disc CD Changer Is Inoperable
Bad Odor When Using A/C
Static Noise with iPod, iPod Inoperable
Navigation System Interrupts Bluetooth Phone Calls

RAV4 Current Generation

Airbag Deployment
Transmission "Clunk"

RAV4 Previous Generation

"Frame Rust"

Sequoia Previous Generation

Transmission Failures

Tacoma Current Generation

Rear Suspension Bottoming Out
Vehicle Surges Forward

Tacoma Previous Generation

Frame Rust/Buy-Backs

Tundra Current Generation

Paint Problems
Tailgate Weakness
Driveshaft Recall

Lexus

Lexus ES 350 Overall

3.5L V6 Piston Slap
Transmission Issues, Wants Buy-Back

Lexus GS 400 Overall

Noise When Coming to Stop

Lexus IS-F Overall

Auto Downshifting While in Manual Mode

Lexus IS 350 Overall

Interior Rattles

Windshield Crack

TSIB For Auxiliary Audio Input Noise

Lexus LS 460 Overall

Excessive Wind Noise

Brake Hold Does Not Disengage

Gray Spots After Window Tint Removal

Lexus LX 470 Overall

Vibrating Noise While Driving

Lexus RX 300 Overall

Transmission Needs Replacement

Transmission Problem, Solenoid

Lexus RX 400h Overall

Excessive Rattles

Scion

Scion xB Current Generation

O2 Sensor Needs Replacement

Clunk While Slowing Down

Side Pillar Creak

Please feel free to contact us if you have any questions.

Thanks,

Joe Colacurcio

Automotive Industry Analyst

Nielsen Online

The Nielsen Company

50 West RiverCenter Blvd.

Third Floor

Covington, KY41011

859.905.4936 voice

610.462.3048 mobile

joe.colacurcio@nielsen.com

www.nielsen-online.com