

**FIELD TECHNICAL REPORT**

TQCN DOC# TQCN_FTR-082340025	Affiliate TMS	Dept. Vehicle & A	Source FTS	Location AREA-CENTRAL	Ref 82473575	Date 09/03/2008
Problem Area PPO/DIO-TMS	Primary Model IS F	Model Year 2008	Production Date 2008-02-08	Odometer 3723	VIN (confirm 17 characters): JTHBP262885 [REDACTED]	
Condition Title Gas pedal gets stuck on winter floor mat						

Do not type in YELLOW shaded fields – This data is auto-populated from the TQCN system:

Repair Date 8/1/2008	Optional Ref.	Optional Approval
-------------------------	---------------	-------------------

**Condition Description**

Customer states that his IS-F had an unintended acceleration.

**Diagnostic Steps:**

The technician confirmed that the gas pedal got caught by the floor mat on hard acceleration. **The winter floor mat was not attached to the hold down clips.**


**Probable Cause**

The winter floor mat was not clipped in position and so physically interfered with the pedals arc of return.


Part # 1:	Part # 2:	Part # 3:	Parts Disposition:	Parts Shipping Destination:
-----------	-----------	-----------	--------------------	-----------------------------

**Repair Process**

The technician repositioned and clipped the mat down with the factory hold down clips.



Pedal is in the up position



The pedal is held down by the out of position winter floor mat.

**FIELD TECHNICAL REPORT**



TQCN DOC# TQCN_FTR-082340025	Affiliate TMS	Dept. Vehicle &	Source FTS	Location AREA-CENTRAL	Ref 82473575	Date 09/03/2008
Problem Area PPO/DIO-TMS	Primary Model IS F	Model Year 2008	Production Date 2008-02-08	Odometer 3723	VIN (confirm 17 characters): JTHBP262885 [REDACTED]	
Condition Title Gas pedal gets stuck on winter floor mat						