


[Print](#)

Recalls - Search Results

1 Record(s) Displayed.

Report Date : **July 2, 2012 at 11:47 AM**

NHTSA CAMPAIGN ID Number: **10V190000**

Vehicle Make / Model:

VOLVO / XC70

Model Year(s):

2008-2010

Manufacturer: VOLVO CARS OF N.A. LLC.

Mfr's Report Date: MAY 04, 2010

NHTSA CAMPAIGN ID Number: 10V190000

NHTSA Action Number: N/A

Component: EQUIPMENT:OTHER:LABELS

Potential Number of Units Affected: 679

Summary:

VOLVO IS RECALLING CERTAIN MODEL YEAR 2010 XC70 VEHICLES MANUFACTURED FROM DECEMBER 5, 2006 THROUGH OCTOBER 1, 2009 FOR FAILING TO COMPLY WITH THE REQUIREMENTS OF FEDERAL MOTOR VEHICLE SAFETY STANDARD NO. 110, "TIRE SELECTION AND RIMS." THE FMVSS LABEL, TIRE AND LOADING INFORMATION LABEL AND A PAGE IN THE OWNER'S MANUAL CONTAIN INCORRECT MAXIMUM PERMISSIBLE INFLATION PRESSURE ACCORDING TO FMVSS 110.

Consequence:

THIS DOES NOT MEET THE REQUIREMENTS OF THE STANDARD.

Remedy:

THE CORRECTIVE ACTION IS TO UPDATE THE VEHICLES WITH A NEW FMVSS LABEL, TIRE AND LOADING INFORMATION LABEL AND TPMS SOFTWARE. VOLVO RETAILERS WILL ALSO APPLY A LABEL WITH CORRECT MAXIMUM TIRE PRESSURE INFORMATION TO THE OWNER'S MANUAL. THIS SERVICE WILL BE PERFORMED FREE OF CHARGE. THE RECALL BEGAN ON JUNE 14, 2010. OWNERS MAY CONTACT VOLVO AT 1-800-458-1552.

Notes:

VOLVO SAFETY RECALL NO. R226. OWNERS MAY ALSO CONTACT THE NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION'S VEHICLE SAFETY HOTLINE AT 1-888-327-4236 (TTY 1-800-424-9153), OR GO TO [HTTP://WWW.SAFERCAR.GOV](http://www.safercar.gov) .

Check to Request Research. Submit below.

1200 New Jersey Avenue, SE, West Building Washington DC 20590 USA
1.888.327.4236 TTY 1.800.424.9153




[Print](#)

Recalls - Search Results

1 Record(s) Displayed.

Report Date : **July 2, 2012 at 01:49 PM**

NHTSA CAMPAIGN ID Number: **10V255000**

Vehicle Make / Model:

VOLVO / C30
VOLVO / S40N
VOLVO / V50

Model Year(s):

2010-2011
2010
2010

Manufacturer: VOLVO CARS OF N.A. LLC.

NHTSA CAMPAIGN ID Number: 10V255000

Mfr's Report Date: JUN 10, 2010

NHTSA Action Number: N/A

Component: STEERING:GEAR BOX:SHAFT SECTOR

Potential Number of Units Affected: 536

Summary:

VOLVO IS RECALLING CERTAIN MODEL YEAR 2010-2011 C30, MODEL YEAR 2010 S40 AND V50 VEHICLES EQUIPPED WITH 6 SPEED MANUAL TRANSMISSIONS. THE GEARSHIFT LEVER STUD ASSEMBLY MAY NOT HAVE BEEN TIGHTENED TO THE CORRECT SPECIFICATION DURING ASSEMBLY. IF THE GEARSHIFT LEVER CABLE OR STUD ASSEMBLY BECOMES LOOSE, IT MAY NOT BE POSSIBLE TO ENGAGE, DISENGAGE OR SHIFT GEARS.

Consequence:

THIS CONDITION CAN INCREASE THE RISK OF A VEHICLE CRASH.

Remedy:

DEALERS WILL TORQUE THE GEARSHIFT LEVER STUD ASSEMBLY TO THE CORRECT SPECIFICATION FREE OF CHARGE. THE SAFETY RECALL BEGAN ON JUNE 14, 2010. OWNERS MAY CONTACT VOLVO AT 1-800-458-1552 OR CUSTOMERCARE@VOLVOFORLIFE.COM .

Notes:

VOLVO SAFETY RECALL NO. R227. OWNERS MAY ALSO CONTACT THE NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION'S VEHICLE SAFETY HOTLINE AT 1-888-327-4236 (TTY 1-800-424-9153), OR GO TO [HTTP://WWW.SAFERCAR.GOV](http://www.safercar.gov) .

Check to Request Research. Submit below.

1200 New Jersey Avenue, SE, West Building Washington DC 20590 USA
1.888.327.4236 TTY 1.800.424.9153




[Print](#)

Recalls - Search Results

1 Record(s) Displayed.

Report Date : **July 2, 2012 at 11:47 AM**

NHTSA CAMPAIGN ID Number: **10V335000**

Vehicle Make / Model:

VOLVO / S80

Model Year(s):

2007-2010

Manufacturer: VOLVO CARS OF N.A. LLC.

Mfr's Report Date: JUL 21, 2010

NHTSA CAMPAIGN ID Number: 10V335000

NHTSA Action Number: N/A

Component: TIRES:PRESSURE MONITORING AND REGULATING SYSTEMS

Potential Number of Units Affected: 3,635

Summary:

VOLVO IS RECALLING CERTAIN MODEL YEAR 2007-2010 S80 VEHICLES FOR FAILING TO COMPLY WITH THE REQUIREMENTS OF FEDERAL MOTOR VEHICLE SAFETY STANDARD NO. 110, "TIRE SELECTION AND RIMS." THE TIRE AND LOADING INFORMATION LABEL AND A PAGE IN THE OWNER'S MANUAL CONTAIN INCORRECT MAXIMUM PERMISSIBLE INFLATION PRESSURE AND THE TIRE PRESSURE MONITORING SYSTEM (TPMS) SOFTWARE HAS AN INCORRECT TRIGGER LEVEL.

Consequence:

THESE VEHICLES DO NOT MEET THE REQUIRED SAFETY STANDARDS.

Remedy:

DEALERS WILL UPDATE THE VEHICLES WITH A NEW TIRE AND LOADING INFORMATION LABEL, OWNER'S MANUAL LABEL AND TPMS SOFTWARE. THIS SERVICE WILL BE PERFORMED FREE OF CHARGE. THE SAFETY RECALL IS EXPECTED TO BEGIN ON OR ABOUT AUGUST 27, 2010. OWNERS MAY CONTACT VOLVO AT 1-800-458-1552 OR CUSTOMERCARE@VOLVOFORLIFE.COM .

Notes:

VOLVO SAFETY RECALL NO. R228. OWNERS MAY ALSO CONTACT THE NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION'S VEHICLE SAFETY HOTLINE AT 1-888-327-4236 (TTY 1-800-424-9153), OR GO TO [HTTP://WWW.SAFERCAR.GOV](http://www.safercar.gov) .

Check to Request Research. Submit below.

1200 New Jersey Avenue, SE, West Building Washington DC 20590 USA
1.888.327.4236 TTY 1.800.424.9153




[Print](#)

Recalls - Search Results

1 Record(s) Displayed.

Report Date : **July 2, 2012 at 11:49 AM**

NHTSA CAMPAIGN ID Number: **10V489000**

Vehicle Make / Model:

VOLVO / S80
VOLVO / V70
VOLVO / XC60
VOLVO / XC70

Model Year(s):

2010-2011
2010
2011
2010-2011

Manufacturer: VOLVO CARS OF N.A. LLC.
NHTSA CAMPAIGN ID Number: 10V489000

Mfr's Report Date: OCT 13, 2010
NHTSA Action Number: N/A

Component: AIR BAGS:FRONTAL

Potential Number of Units Affected: 9,746

Summary:

VOLVO IS RECALLING CERTAIN MODEL YEAR 2010-2011 S80, XC70, MODEL YEAR 2011 XC60 AND MODEL YEAR 2010 V70 VEHICLES. THERE MAY BE AN INTERMITTENT FAULT IN THE DRIVER'S AIRBAG CLOCKSPRING WIRING CONNECTOR FOR THE SUPPLEMENTAL RESTRAINT SYSTEM.

Consequence:

IN THE EVENT OF A CRASH, THE DRIVER'S FRONTAL AIRBAG MAY NOT DEPLOY AS INTENDED OR AT ALL, AND THEREFORE WILL NOT BE ABLE TO PROPERLY PROTECT THE DRIVER, INCREASING THE RISK OF INJURIES.

Remedy:

DEALERS WILL INSTALL A METAL SHIM IN THE DRIVER'S AIR BAG CLOCKSPRING WIRING CONNECTOR. THIS SERVICE WILL BE PERFORMED FREE OF CHARGE. THE SAFETY RECALL BEGAN ON OCTOBER 20, 2010. OWNERS MAY CONTACT VOLVO AT 1-800-458-1552.

Notes:

VOLVO SAFETY RECALL NO. R229. OWNERS MAY ALSO CONTACT THE NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION'S VEHICLE SAFETY HOTLINE AT 1-888-327-4236 (TTY 1-800-424-9153), OR GO TO [HTTP://WWW.SAFERCAR.GOV](http://www.safercar.gov) .

Check to Request Research. Submit below.

1200 New Jersey Avenue, SE, West Building Washington DC 20590 USA
1.888.327.4236 TTY 1.800.424.9153




[Print](#)

Recalls - Search Results

1 Record(s) Displayed.

Report Date : **July 2, 2012 at 11:49 AM**

NHTSA CAMPAIGN ID Number: **10V566000**

Vehicle Make / Model:

VOLVO / C30
 VOLVO / C70
 VOLVO / S40
 VOLVO / S60
 VOLVO / S80
 VOLVO / V50
 VOLVO / V70
 VOLVO / XC70
 VOLVO / XC90

Model Year(s):

2007-2010
 2006-2010
 2004-2010
 2001-2009
 2000-2010
 2005-2010
 2001-2010
 2001-2010
 2003-2010

Manufacturer: VOLVO CARS OF N.A. LLC.

NHTSA CAMPAIGN ID Number: 10V566000

Mfr's Report Date: NOV 05, 2010

NHTSA Action Number: N/A

Component: EQUIPMENT:ELECTRICAL:NAVIGATIONAL SYSTEM(GLOBAL POSITIONING SYSTEM)

Potential Number of Units Affected: 416

Summary:

VOLVO IS RECALLING CERTAIN VEHICLES EQUIPPED WITH GARMIN 760 PORTABLE GLOBAL POSITIONING SYSTEM (GPS) UNITS BECAUSE THE BATTERIES ON THOSE UNITS MAY OVERHEAT.

Consequence:

AN OVERHEATED BATTERY COULD LEAD TO A FIRE.

Remedy:

VOLVO ADVISES OWNERS TO PLEASE STOP USING THE GARMIN PORTABLE GPS DEVICE IMMEDIATELY, AND VISIT THE GARMIN WEBSITE TO DETERMINE IF THEIR UNIT IS AFFECTED. THE UNIT'S BATTERY WILL BE REPLACED WITH A NEW BATTERY AND A SPACER WILL BE INSERTED ON TOP OF THE BATTERY NEXT TO THE PCB. THIS SERVICE WILL BE PERFORMED FREE OF CHARGE. THE SAFETY RECALL BEGAN ON NOVEMBER 18, 2010. OWNERS MAY CONTACT GARMIN AT 866-957-1981 OR VISIT GARMIN'S WEBSITE AT WWW.GARMIN.COM/NUVIBATTERYPCBRECALL.

Notes:

VOLVO SAFETY RECALL NO. R231. OWNERS MAY ALSO CONTACT THE NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION'S VEHICLE SAFETY HOTLINE AT 1-888-327-4236 (TTY 1-800-424-9153), OR GO TO [HTTP://WWW.SAFERCAR.GOV](http://WWW.SAFERCAR.GOV).

Check to Request Research. Submit below.


[Print](#)

Recalls - Search Results

1 Record(s) Displayed.

Report Date : **July 2, 2012 at 11:50 AM**

NHTSA CAMPAIGN ID Number: **10V579000**

Vehicle Make / Model:

VOLVO / S60
VOLVO / S80
VOLVO / XC60
VOLVO / XC70

Model Year(s):

2011
2011
2011
2011

Manufacturer: VOLVO CARS OF N.A. LLC.
NHTSA CAMPAIGN ID Number: 10V579000

Mfr's Report Date: NOV 17, 2010
NHTSA Action Number: N/A

Component: ENGINE AND ENGINE COOLING

Potential Number of Units Affected: 6,046

Summary:

VOLVO IS RECALLING CERTAIN MODEL YEAR 2011, S80, S60, XC70 AND XC60 VEHICLES. THE SOFTWARE CALIBRATION FOR THE FUEL CUT-OFF FUNCTIONALITY IN THE ENGINE CONTROL MODULE (ECM) IS TOO SENSITIVE.

Consequence:

SUDDEN ENGINE STALL COULD OCCUR INCREASING THE RISK OF A CRASH.

Remedy:

DEALERS WILL UPDATE THE ECM AND TCM WITH NEW SOFTWARE FREE OF CHARGE. THE SAFETY RECALL IS EXPECTED TO BEGIN ON OR BEFORE DECEMBER 10, 2010. OWNERS MAY CONTACT VOLVO AT 1-800-458-1552 OR AT CUSTOMERCARE@VOLVOFORLIFE.COM.

Notes:

VOLVO SAFETY RECALL NO. R234. OWNERS MAY ALSO CONTACT THE NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION'S VEHICLE SAFETY HOTLINE AT 1-888-327-4236 (TTY 1-800-424-9153), OR GO TO [HTTP://WWW.SAFERCAR.GOV](http://www.safercar.gov) .

Check to Request Research. Submit below.

1200 New Jersey Avenue, SE, West Building Washington DC 20590 USA
1.888.327.4236 TTY 1.800.424.9153




[Print](#)

Recalls - Search Results

1 Record(s) Displayed.

Report Date : **July 2, 2012 at 11:50 AM**

NHTSA CAMPAIGN ID Number: **12V075000**

Vehicle Make / Model:

VOLVO / S60
VOLVO / S80
VOLVO / XC60
VOLVO / XC70

Model Year(s):

2012
2012
2012
2012

Manufacturer: VOLVO CARS OF N.A. LLC.
NHTSA CAMPAIGN ID Number: 12V075000

Mfr's Report Date: FEB 27, 2012
NHTSA Action Number: N/A

Component: ELECTRICAL SYSTEM:WIRING

Potential Number of Units Affected: 11,168

Summary:

VOLVO IS RECALLING CERTAIN MODEL YEAR 2012 S60, XC60, S80 AND XC70 VEHICLES MANUFACTURED FROM MAY 16, 2011, THROUGH OCTOBER 6, 2011. IN THESE VEHICLES, THE WIRE HARNESS UNDER THE FRONT SEATS MAY HAVE NOT BEEN ATTACHED PROPERLY TO THE SEAT FRAME. AS A RESULT, WHEN THE SEATS ARE MOVED TO ADJUST THE SEATING POSITION, THE WIRE HARNESS MAY GET PULLED, CAUSING IT TO DISCONNECT.

Consequence:

IN THE EVENT OF CRASH, THE FRONT AND/OR SIDE IMPACT AIR BAGS MAY DEPLOY IMPROPERLY OR NOT AT ALL, INCREASING THE RISK OF INJURY. ALSO, THE LAP BELT PRETENSIONER MAY NOT DEPLOY.

Remedy:

VOLVO WILL NOTIFY OWNERS, AND DEALERS WILL INSPECT AND, IF NECESSARY, SECURE THE SEAT WIRE HARNESS. THIS SERVICE WILL BE PERFORMED FREE OF CHARGE. THE SAFETY RECALL BEGAN ON APRIL 12, 2012. OWNERS MAY CONTACT VOLVO CARS AT 1-800-458-1552.

Notes:

THE VOLVO RECALL CAMPAIGN NUMBER IS 250. CUSTOMERS MAY CONTACT THE NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION'S VEHICLE SAFETY HOTLINE AT 1-888-327-4236 (TTY: 1-800-424-9153); OR GO TO [HTTP://WWW.SAFERCAR.GOV](http://www.safercar.gov).

Check to Request Research. Submit below.

1200 New Jersey Avenue, SE, West Building Washington DC 20590 USA
1.888.327.4236 TTY 1.800.424.9153

