From: t3_tqcn_admin@toyota.com. Sent:9/3/2008 1:57 PM.

To: [-] cole_stutz@toyota.com.

Cc: [-] .

Bcc: [-] .

Subject: Subscription TQCN_DPR-082330007 Corolla 2009 Vehicle surges and lacks power - Engine wiring harness.

This is a Subscription email message generated for this document.

You may view this document directly by clicking on the appropriate hyperlink below:

To download the Word format of the document use:

http://t3.tms.toyota.com/tqcnWebtop/action/view?objectId=097b2b468024dd3f

To see the documents properties use:

http://t3.tms.toyota.com/tqcnWebtop/action/properties?objectId=097b2b468024dd3f

To download the Word format of the document (as a PD user) use:

http://t3.tmsnet.toyota.com/tqcnWebtop/action/view?objectId=097b2b468024dd3f

To see the documents properties (as a PD user) use:

http://t3.tmsnet.toyota.com/tqcnWebtop/action/properties?objectId=097b2b468024dd3f

If there are any problems, please contact
Tom Trisdale at 310-468-3316, by email: tom_trisdale@toyota.com
Scott Limbrock at 310-468-5358, by email: scott_limbrock@toyota.com.