ENTIRE PAGE CONFIDENTIAL BUSINESS INFORMATION

Technical Service Bulletin Summary Report for July 2009

Monthly Department Summary	Quality Assurance					Service Technology				Accessory Quality	Tech Coord / Tech Compliance	Totals
	Body	Chassis	Electrical	Hybrid*	Powertrain	Service Tech	Tech Info	Tool & Equip	AFV			
P.E. Draft	1	1	2	0	0	0	1	0	0	1	0	6
DTP Layout	4	5	8	0	6	1	16	3	0	0	0	43
Initial Routing	3	5	6	0	7	2	4	0	0	0	0	27
Final Routing	4	4	3	0	4	1	41	1	0	2	0	60
Final Approval	11	5	18	0	7	0	16	0	0	3	0	60
TSBs On Hold	3	1	7	0	4	0	0	0	0	0	0	15
Translation	41	23	29	0	57	0	81	0	0	2	0	233
Total TSBs in the System	23	20	37	0	24	4	78	4	0	6	0	196
TSBs Published												
Current Month	7	6	3	0	8	0	69	0	0	0	0	93
Year to Date	48	27	41	9	82	0	213	0	0	4	0	424
Days to Publish (YTD Avg)	71	53	100	105	53	0	22	0	0	28	0	46

Summary	2008												2009											
	Jan	Feb	Mar	Apr	May	Jun	July	Aug	Sep	Oct	Nov	Dec	Jan	Feb	Mar	Apr	May	Jun	July	Aug	Sep	Oct	Nov	Dec
Total by Month	28	15	21	44	38	56	41	149	87	68	58	36	65	41	55	77	47	46	93					
Lexus	4	9	6	10	4	6	10	37	36	36	7	17	6	13	17	12	21	13	17					
Toyota de Mexico	12	42	24	27	21	21	5	37	14	12	20	3	18	6	8	23	5	3	24					
						YTD: 243												YTD: 424						
Avg Days to Publish																								
Monthly Total	66	57	81	69	53	59	68	37	52	58	44	54	44	66	60	31	35	70	30					
YTD Total	66	63	69	69	65	63	64	53	53	54	53	53	44	53	55	48	46	49	45					

* Hybrid in process and published starting with the month of May has been combined with Powertrain

8/3/2009

TOY-TQ001-00040455

ENTIRE PAGE CONFIDENTIAL BUSINESS INFORMATION

Technical Service Bulletins Published in January 2009

PRIORITY	PE	REF#	TITLE	DIVISION	MARKET	DEPT	TOTAL DAYS	RELEASED	PUBLICATION #
GR 3	Fujita, Glen	08-TMS-0198-L	Front Window Popping Noise	Lexus	US	BO	81	1/26/2009	L-SB-0003-09
GR 3	Wenninghoff, T.	08-TMS-0454-T	Body Cowl and Fender Creak	Toyota	US	BO	99	1/30/2009	T-SB-0055-09
N/A	Herm, Steven	08-TMS-0179-L	Seat Belt Extenders	Lexus	US	BO	125	1/27/2009	L-SB-0004-09
N/A	Herm, Steven	08-TMS-0477-T	Seat Belt Extenders	Toyota	US	BO	48	1/27/2009	T-SB-0053-09
N/A	Wenninghoff, T.	08-TMS-0462-T	Shifter Trim Squeak Noise	Toyota	US	BO	85	1/29/2009	T-SB-0054-09
						Avg Days	88		
GR 4	Jaramillo, Phillip	07-TMS-0013-L	Vehicle Pulling to One Side	Lexus	US	CH	49	1/13/2009	L-SB-0035-08 Rev1
GR 5	Molgren, Nathaniel	08-TMS-0474-T	Repair Manual Supplement: Vehicle Pulling to One Side	Toyota	Mexico	CH	40	1/13/2009	T-SB-0026-09
N/A	Sasaki, Mark	08-TMS-0339-T	Rear Spring Harsh Ride	Toyota	US	CH	26	1/12/2009	T-SB-0305-08 Rev1
						Avg Days	38		
GR 3	Saunders, Jill	08-TMS-0463-T	IG1 Relay Freezing	Toyota	US	EL	81	1/6/2009	T-SB-0002-09
GR 3	Saunders, Jill	08-TMS-0061-S	IG1 Relay Freezing	Scion	US	EL	34	1/19/2009	S-SB-0001-09
GR 3	Saunders, Jill	08-TMS-0479-T	IG1 Relay Freezing	Toyota	US	EL	38	1/19/2009	T-SB-0047-09
GR 3	Jones, Justin	08-TMS-0380-T	Overhead Digital Compass & Temperature Display Inoperative	Toyota	US	EL	156	1/22/2009	T-SB-0051-09
GR 3	Saunders, Jill	08-TMS-0463-T	IG1 Relay Freezing	Toyota	US	EL	13	1/27/2009	T-SB-0002-09 Rev1
GR 4	Koelsch, Robert	08-TMS-0405-T	Smart Key Intermittent No Crank / No Start	Toyota	US	EL	106	1/7/2009	T-SB-0003-09
N/A	Saunders, Jill	08-TMS-0010-LT	Moon Roof Auto Close Function is Inoperative	Lexus	US	EL	89	1/20/2009	L-SB-0001-09
N/A	Saunders, Jill	08-TMS-0453-T	Moon Roof Auto Close Function Inoperative	Toyota	US	EL	90	1/21/2009	T-SB-0049-09
						Avg Days	76		
GR 2	Davis, Timothy	08-TMS-0391-T	Fuel Pump Resistor Assembly & Installation Procedure	Toyota	US	PT	128	1/14/2009	T-SB-0027-09
GR 2	Davis, Timothy	08-TMS-0401-T	Fuel Pump Resistor Assembly and Installation Procedure Repair Manual Supplement	Toyota	Mexico	PT	119	1/14/2009	T-SB-0028-09
GR 3	Steger, Tom	08-TMS-0468-T	Torque Converter Flex Lockup Shudder	Toyota	US	PT	63	1/20/2009	T-SB-0048-09
GR 3	Steger, Tom	08-TMS-0471-T	Front Differential Growl/Howl/Rumble Noise at 15-30 MPH	Toyota	US	PT	65	1/23/2009	T-SB-0052-09
GR 4	Stutz, Cole	08-TMS-0467-T	M.I.L. "ON" DTC P0171, P0441, and/or P0455	Toyota	US	PT	50	1/6/2009	T-SB-0001-09
GR 4	Curtin, Andy	08-TMS-0213-L	TCM Calibration: Enhancement to Shifting Performance & Smoothness	Lexus	US	PT	58	1/21/2009	L-SB-0002-09
GR 4	Curtin, Andy	08-TMS-0473-T	TCM Calibration: Enhancement to Shifting Performance & Smoothness	Toyota	US	PT	63	1/22/2009	T-SB-0050-09
						Avg Days	78		
N/A	Buetzer, Ryan	08-TMS-0180-L	Tire Positioning Before New Vehicle Delivery	Lexus	US	TI	20	1/12/2009	L-SB-0139-08 Rev1
N/A	Buetzer, Ryan	08-TMS-0487-T	Smart Key System Check During PDS	Toyota	US	TI	28	1/12/2009	T-SB-0008-09
N/A	Buetzer, Ryan	08-TMS-0488-T	Smart Key System Check During PDS	Toyota	Mexico	TI	28	1/12/2009	T-SB-0009-09
N/A	Buetzer, Ryan	08-TMS-0489-T	Front License Plate & Mounting Bracket Installation	Toyota	US	TI	28	1/12/2009	T-SB-0011-09
N/A	Buetzer, Ryan	08-TMS-0490-T	Front License Plate & Mounting Bracket Installation	Toyota	Mexico	TI	28	1/12/2009	T-SB-0010-09
N/A	Buetzer, Ryan	08-TMS-0493-T	Initial Calibration of Compass During PDS	Toyota	US	TI	28	1/12/2009	T-SB-0007-09
N/A	Buetzer, Ryan	08-TMS-0494-T	Initial Calibration of Compass During PDS	Toyota	Mexico	TI	28	1/12/2009	T-SB-0006-09
N/A	Buetzer, Ryan	08-TMS-0495-T	Short Pin Installation During PDS	Toyota	US	TI	28	1/12/2009	T-SB-0004-09
N/A	Buetzer, Ryan	08-TMS-0496-T	Short Pin Installation During PDS	Toyota	Mexico	TI	28	1/12/2009	T-SB-0005-09
N/A	Buetzer, Ryan	08-TMS-0497-T	Tire Pressure Warning System Activation & Initialization	Toyota	US	TI	29	1/12/2009	T-SB-0013-09
N/A	Buetzer, Ryan	08-TMS-0498-T	Tire Pressure Warning System Initialization	Toyota	Mexico	TI	28	1/12/2009	T-SB-0012-09
N/A	Buetzer, Ryan	08-TMS-0485-T	Installation of Rubber Body Plugs During PDS	Toyota	US	TI	29	1/13/2009	T-SB-0014-09
N/A	Buetzer, Ryan	08-TMS-0486-T	Installation of Rubber Body Plugs During PDS	Toyota	Mexico	TI	29	1/13/2009	T-SB-0016-09
N/A	Buetzer, Ryan	08-TMS-0491-T	Front Wheel Opening Extension Pad Installation During PDS	Toyota	US	TI	29	1/13/2009	T-SB-0017-09
N/A	Buetzer, Ryan	08-TMS-0492-T	Front Wheel Opening Extension Pad Installation During PDS	Toyota	Mexico	TI	29	1/13/2009	T-SB-0015-09
N/A	Buetzer, Ryan	08-TMS-0501-T	Installation of Rubber Body Plugs During PDS	Toyota	US	TI	28	1/13/2009	T-SB-0020-09
N/A	Buetzer, Ryan	08-TMS-0502-T	Front Wheel Opening Extension Pad Installation During PDS	Toyota	US	TI	28	1/13/2009	T-SB-0022-09
N/A	Buetzer, Ryan	08-TMS-0503-T	Front License Plate & Mounting Bracket Installation	Toyota	US	TI	28	1/13/2009	T-SB-0018-09
N/A	Buetzer, Ryan	08-TMS-0504-T	Short Pin Installation During PDS	Toyota	US	TI	28	1/13/2009	T-SB-0023-09
N/A	Buetzer, Ryan	08-TMS-0505-T	Initial Calibration of Compass During PDS	Toyota	US	TI	28	1/13/2009	T-SB-0019-09
N/A	Buetzer, Ryan	08-TMS-0506-T	Tire Pressure Warning System Activation & Initialization	Toyota	US	TI	28	1/13/2009	T-SB-0021-09
N/A	Buetzer, Ryan	08-TMS-0508-T	Floor Mat Installation During PDS	Toyota	US	TI	28	1/13/2009	T-SB-0024-09
N/A	Buetzer, Ryan	08-TMS-0518-T	Floor Mat Installation During PDS	Toyota	Mexico	TI	26	1/13/2009	T-SB-0025-09

ENTIRE PAGE CONFIDENTIAL BUSINESS INFORMATION

Technical Service Bulletins Published in January 2009

PRIORITY	PE	REF#	TITLE	DIVISION	MARKET	DEPT	TOTAL DAYS	RELEASED	PUBLICATION #
N/A	Buetzer, Ryan	08-TMS-0483-T	2010 MY Camry Pre-Delivery Service Check Sheet	Toyota	US	TI	30	1/14/2009	T-SB-0029-09
N/A	Buetzer, Ryan	08-TMS-0484-T	2010 MY Camry Pre-Delivery Service Check Sheet	Toyota	Mexico	TI	30	1/14/2009	T-SB-0030-09
N/A	Buetzer, Ryan	08-TMS-0500-T	2010 Camry HV PDS Check Sheet	Toyota	US	TI	29	1/14/2009	T-SB-0031-09
N/A	Buetzer, Ryan	08-TMS-0514-T	Front License Plate & Mounting Bracket Installation	Toyota	US	TI	28	1/15/2009	T-SB-0033-09
N/A	Buetzer, Ryan	08-TMS-0515-T	Front License Plate & Mounting Bracket Installation	Toyota	Mexico	TI	28	1/15/2009	T-SB-0032-09
N/A	Buetzer, Ryan	08-TMS-0516-T	Short Pin Installation During PDS	Toyota	US	TI	28	1/15/2009	T-SB-0036-09
N/A	Buetzer, Ryan	08-TMS-0517-T	Short Pin Installation During PDS	Toyota	Mexico	TI	28	1/15/2009	T-SB-0037-09
N/A	Buetzer, Ryan	08-TMS-0519-T	Initial Calibration of Compass During PDS	Toyota	US	TI	28	1/15/2009	T-SB-0039-09
N/A	Buetzer, Ryan	08-TMS-0520-T	Initial Calibration of Compass During PDS	Toyota	Mexico	TI	28	1/15/2009	T-SB-0038-09
N/A	Buetzer, Ryan	08-TMS-0521-T	Tire Pressure Warning System Activation & Initialization	Toyota	US	TI	28	1/15/2009	T-SB-0034-09
N/A	Buetzer, Ryan	08-TMS-0522-T	Tire Pressure Warning System Activation & Initialization	Toyota	Mexico	TI	28	1/15/2009	T-SB-0035-09
N/A	Buetzer, Ryan	08-TMS-0016-T	Maintenance for HV & Auxiliary Batteries	Toyota	US	TI	8	1/16/2009	T-SB-0007-08 Rev1
N/A	Buetzer, Ryan	08-TMS-0481-T	2010 MY Camry Pre-Delivery Service (PDS)	Toyota	US	TI	32	1/16/2009	T-SB-0040-09
N/A	Buetzer, Ryan	08-TMS-0482-T	2010 MY Camry Pre-Delivery Service (PDS)	Toyota	Mexico	TI	32	1/16/2009	T-SB-0041-09
N/A	Buetzer, Ryan	08-TMS-0499-T	2010 MY Camry HV Pre-Delivery Service (PDS)	Toyota	US	TI	31	1/16/2009	T-SB-0046-09
N/A	Buetzer, Ryan	08-TMS-0510-T	2010 MY Corolla Pre-Delivery Service (PDS)	Toyota	US	TI	29	1/16/2009	T-SB-0045-09
N/A	Buetzer, Ryan	08-TMS-0511-T	2010 MY Corolla Pre-Delivery Service (PDS)	Toyota	Mexico	TI	29	1/16/2009	T-SB-0044-09
N/A	Buetzer, Ryan	08-TMS-0512-T	2010 Corolla PDS Check Sheet	Toyota	US	TI	29	1/16/2009	T-SB-0042-09
N/A	Buetzer, Ryan	08-TMS-0513-T	2010 Corolla PDS Check Sheet	Toyota	Mexico	TI	29	1/16/2009	T-SB-0043-09
					Avg Days		28		

Total Average Days	44
Total YTD Average	44

TOY-TQ001-00040457

ENTIRE PAGE CONFIDENTIAL BUSINESS INFORMATION

Technical Service Bulletins Published in February 2009

PRIORITY	PE	REF#	TITLE	DIVISION	MARKET	DEPT	TOTAL DAYS	RELEASED	PUBLICATION #
GR 3	Cocores, Christophe	08-TMS-0210-L	Exterior Key Cylinder Difficult to Operate	Lexus	US	BO	93	2/20/2009	L-SB-0016-09
GR 3	Maulhardt, Terence	08-TMS-0392-T	Instrument Panel Rattle Noise	Toyota	US	BO	71	2/25/2009	T-SB-0333-08 Rev1
GR 4	Cocores, Christophe	08-TMS-0378-T	Front Seat Squeak Noise	Toyota	US	BO	26	2/23/2009	T-SB-0390-08 Rev1
GR 5	Wenninghoff, Thoma	08-TMS-0059-S	Front Seat Back Will Not Return From Reclined Position	Scion	US	BO	97	2/25/2009	S-SB-0005-09
N/A	Maulhardt, Terence	08-TMS-0190-T	Upper/Lower Windshield/Rear Glass Tick Noise	Toyota	US	BO	82	2/2/2009	T-SB-0142-08 Rev1
N/A	Maulhardt, Terence	08-TMS-0215-L	Water Leak At Back Door Hatch	Lexus	US	BO	82	2/23/2009	L-SB-0019-09
N/A	Fujita, Glen	09-TMS-0004-S	Long Term Vehicle Storage Guidelines	Scion	US	BO	32	2/23/2009	S-SB-0004-09
N/A	Fujita, Glen	09-TMS-0006-L	Long Term Vehicle Storage Guidelines	Lexus	US	BO	32	2/23/2009	L-SB-0018-09
						Avg Days	64		
GR 3	Jaramillo, Phillip	09-TMS-0003-L	Front Brake Squeak	Lexus	US	CH	37	2/13/2009	L-SB-0015-09
						Avg Days	37		
GR 4	Jewell, Travis	08-TMS-0098-L	HVAC Odor	Lexus	US	EL	200	2/6/2009	L-SB-0011-09
GR 4	Jewell, Travis	08-TMS-0509-T	Decreased Air Volume from HVAC Vents	Toyota	US	EL	71	2/26/2009	T-SB-0072-09
N/A	Quirk, Eddie	08-TMS-0218-L	No Picture Displayed from Backup Camera	Lexus	US	EL	61	2/10/2009	L-SB-0013-09
N/A	Jones, Justin	08-TMS-0195-L	Moon Roof Auto Close Function is Inoperative	Lexus	US	EL	114	2/20/2009	L-SB-0017-09
						Avg Days	112		
GR 2	Sessions, Dereck	08-TMS-0065-L	M.I.L. "ON" DTC P0867/P0990	Lexus	US	HPT	224	2/4/2009	L-SB-0006-09
GR 3	Sessions, Dereck	08-TMS-0199-L	M.I.L. "ON" DTC P0731/P0732	Lexus	US	HPT	86	2/5/2009	L-SB-0009-09
GR 4	Campbell, Don	08-TMS-0212-L	Oil Leak from Engine Bell Housing - Oil Galley Plug	Lexus	US	HPT	83	2/11/2009	L-SB-0014-09
GR 4	Campbell, Don	08-TMS-0472-T	Oil Leak from Engine Bell Housing - Oil Galley Plug	Toyota	US	HPT	83	2/11/2009	T-SB-0062-09
						Avg Days	119		
GR 2	Steger, Tom	09-TMS-0003-T	Clunk Noise at Low Speeds when Stopping or Turning	Toyota	US	PT	44	2/19/2009	T-SB-0067-09
GR 3	Davis, Timothy	08-TMS-0131-T	Engine "Pinging" or "Knocking" Noise	Toyota	US	PT	204	2/20/2009	T-SB-0124-08 Rev1
GR 3	Stewart, Scott	09-TMS-0006-T	1700 - 2100 RPM Steering Wheel and/or Accelerator Pedal Vibration	Toyota	US	PT	43	2/20/2009	T-SB-0071-09
GR 4	Davis, Timothy	08-TMS-0459-T	2GR-FE No. 2 Idler Pulley Noise	Toyota	US	PT	92	2/3/2009	T-SB-0056-09
GR 4	Davis, Timothy	08-TMS-0190-L	2GR-FE No. 2 Idler Pulley Noise	Lexus	US	PT	106	2/4/2009	L-SB-0010-09
GR 4	Stutz, Cole	09-TMS-0002-S	Transverse Engine Mount - Abnormal Noise and Vibration on Acceleration	Scion	US	PT	40	2/19/2009	S-SB-0003-09
GR 4	Stutz, Cole	09-TMS-0007-T	Transverse Engine Mount - Abnormal Noise and Vibration on Acceleration	Toyota	US	PT	40	2/19/2009	T-SB-0068-09
N/A	Steger, Tom	09-TMS-0014-L	A750 Transmission Solenoid Identification	Lexus	US	PT	16	2/27/2009	L-SB-0021-09
N/A	Steger, Tom	09-TMS-0016-L	AB60F Transmission Solenoid Identification	Lexus	US	PT	15	2/27/2009	L-SB-0020-09
N/A	Steger, Tom	09-TMS-0024-T	A750 Transmission Solenoid Identification	Toyota	US	PT	16	2/27/2009	T-SB-0076-09
N/A	Steger, Tom	09-TMS-0025-T	AB60 Transmission Solenoid Identification	Toyota	US	PT	15	2/27/2009	T-SB-0073-09
N/A	Steger, Tom	09-TMS-0026-T	A340E Transmission Solenoid Identification	Toyota	US	PT	15	2/27/2009	T-SB-0075-09
N/A	Steger, Tom	09-TMS-0029-T	AB60F Transmission Solenoid Identification	Toyota	Mexico	PT	14	2/27/2009	T-SB-0074-09
						Avg Days	51		
N/A	Buetzer, Ryan	08-TMS-0531-T	Initial Calibration of Compass During PDS	Toyota	US	TI	50	2/10/2009	T-SB-0058-09
N/A	Buetzer, Ryan	08-TMS-0532-T	Initial Calibration of Compass During PDS	Toyota	Mexico	TI	50	2/10/2009	T-SB-0059-09
N/A	Buetzer, Ryan	08-TMS-0527-T	Front License Plate & Bracket Installation	Toyota	US	TI	51	2/11/2009	T-SB-0063-09
N/A	Buetzer, Ryan	08-TMS-0528-T	Front License Plate & Bracket Installation	Toyota	Mexico	TI	51	2/11/2009	T-SB-0064-09
N/A	Buetzer, Ryan	08-TMS-0529-T	Tire Pressure Warning System Initialization	Toyota	US	TI	51	2/11/2009	T-SB-0061-09
N/A	Buetzer, Ryan	08-TMS-0530-T	Tire Pressure Warning System Initialization	Toyota	Mexico	TI	51	2/11/2009	T-SB-0060-09
N/A	Buetzer, Ryan	08-TMS-0320-T	Floor Mat Retaining Clip Installation During PDS	Toyota	US	TI	23	2/12/2009	T-SB-0182-08 Rev1
N/A	Buetzer, Ryan	08-TMS-0526-T	2010 Matrix PDS Check Sheet	Toyota	Mexico	TI	52	2/12/2009	T-SB-0065-09
N/A	Buetzer, Ryan	08-TMS-0525-T	2010 Matrix PDS Check Sheet	Toyota	US	TI	57	2/13/2009	T-SB-0066-09
N/A	Buetzer, Ryan	08-TMS-0523-T	2010 MY Matrix Pre-Delivery Service (PDS)	Toyota	US	TI	60	2/20/2009	T-SB-0069-09
N/A	Buetzer, Ryan	08-TMS-0524-T	2010 MY Matrix Pre-Delivery Service (PDS)	Toyota	Mexico	TI	60	2/20/2009	T-SB-0070-09
						Avg Days	51		

Total Average Days	66
Total YTD Average	53

TOY-TQ001-00040458

ENTIRE PAGE CONFIDENTIAL BUSINESS INFORMATION

Technical Service Bulletins Published in March 2009

PRIORITY	PE	REF#	TITLE	DIVISION	MARKET	DEPT	TOTAL DAYS	RELEASED	PUBLICATION #
GR 3	Wenninghoff, T.	08-TMS-0417-T	Sunvisor - Removal & Installation Procedures	Toyota	US	BO	160	3/18/2009	T-SB-0093-09
GR 3	Cocores, C.	08-TMS-0211-L	Rattle Noise From Third Row Seats	Lexus	US	BO	120	3/20/2009	L-SB-0029-09
GR 4	Fujita, Glen	09-TMS-0007-L	Rear Wheel Rocker Panel Protector Loose	Lexus	US	BO	42	3/11/2009	L-SB-0024-09
GR 5	Wenninghoff, T.	08-TMS-0057-S	Moonroof Rattle in the Full Open Position	Scion	US	BO	108	3/5/2009	S-SB-0006-09
N/A	Fujita, Glen	09-TMS-0013-T	Long Term Vehicle Storage Guidelines	Toyota	US	BO	41	3/4/2009	T-SB-0079-09
N/A	Maulhardt, T.	08-TMS-0215-L	Water Leak At Back Door Hatch	Lexus	US	BO	5	3/10/2009	L-SB-0019-09 Rev1
N/A	Fujita, Glen	09-TMS-0004-S	Long Term Vehicle Storage Guidelines	Scion	US	BO	6	3/10/2009	S-SB-0004-09 Rev1
N/A	Fujita, Glen	09-TMS-0006-L	Long Term Vehicle Storage Guidelines	Lexus	US	BO	6	3/10/2009	L-SB-0018-09 Rev1
					Average Days		61		
GR 3	Jaramillo, Phillip	08-TMS-0177-L	Front Brake Squeak	Lexus	US	CH	11	3/9/2009	L-SB-0124-08 Rev2
GR 4	Casado, Robert	08-TMS-0060-S	Tire Pressure Monitoring System (TPMS) Tire Registration & "Lost Communication With	Scion	US	CH	93	3/12/2009	S-SB-0013-09
GR 4	Casado, Robert	08-TMS-0214-L	Tire Pressure Monitoring System (TPMS) Tire Registration and "Lost Communication wi	Lexus	US	CH	106	3/12/2009	L-SB-0025-09
GR 4	Casado, Robert	08-TMS-0475-T	Tire Pressure Monitoring System (TPMS) Tire Registration "Lost Communication With	Toyota	US	CH	93	3/12/2009	T-SB-0084-09
N/A	Jaramillo, Phillip	08-TMS-0130-L	Alternative Front Brake Pads	Lexus	US	CH	13	3/3/2009	L-SB-0121-08 Rev2
					Average Days		63		
GR 3	Pricer, Michael	08-TMS-0399-T	Repair Manual Supplement: SRS Light "ON" - DTC B0111/B0116 - Open Side Squib Ci	Toyota	US	EL	179	3/13/2009	T-SB-0086-09
GR 4	Brand, Stefan	08-TMS-0393-T	"No Start" DTC B2799	Toyota	US	EL	175	3/2/2009	T-SB-0078-09
GR 5	Pricer, Michael	09-TMS-0001-T	Repair Manual Supplement: Laser Cruise Control Beam Adjustment	Toyota	US	EL	8	3/12/2009	T-SB-0077-09 Rev1
N/A	Brand, Stefan	08-TMS-0071-T	Power Function of Sliding Door Inoperative	Toyota	US	EL	363	3/13/2009	T-SB-0085-09
N/A	Quirk, Eddie	09-TMS-0005-L	Audio Bluetooth System Outgoing Call Volume Adjustment	Lexus	US	EL	62	3/24/2009	L-SB-0030-09
N/A	Quirk, Eddie	09-TMS-0012-T	Audio Bluetooth System Outgoing Call Volume Adjustment	Toyota	US	EL	61	3/24/2009	T-SB-0097-09
					Average Days		141		
GR 3	Stewart, Scott	09-TMS-0001-L	1700 - 2100 RPM Steering Wheel and/or Accelerator Pedal Vibration	Lexus	US	PT	57	3/3/2009	L-SB-0022-09
GR 3	Curtin, Andy	09-TMS-0014-T	Harsh Downshift When Coming to a Stop	Toyota	US	PT	44	3/11/2009	T-SB-0082-09
GR 3	Curtin, Andy	09-TMS-0020-T	Harsh Downshift When Coming to a Stop	Toyota	Mexico	PT	35	3/11/2009	T-SB-0083-09
GR 3	Steger, Tom	09-TMS-0012-L	M.I.L. "ON" DTC P0751	Lexus	US	PT	34	3/13/2009	L-SB-0026-09
GR 3	Stutz, Cole	09-TMS-0016-T	Brief Engine Knock/Rattle Noise at Cold Startup	Toyota	US	PT	45	3/13/2009	T-SB-0087-09
GR 3	Stutz, Cole	09-TMS-0019-T	Brief Engine Knock/Rattle Noise at Cold Startup	Toyota	Mexico	PT	39	3/13/2009	T-SB-0088-09
GR 3	Davis, Timothy	08-TMS-0200-L	Engine Ticking Noise and / or MIL ON P0014, P0015, P0024, P0025, P0017, or P0018	Lexus	US	PT	125	3/19/2009	L-SB-0028-09
GR 3	Davis, Timothy	08-TMS-0465-T	2GR-FE Engine Ticking Noise and / or MIL ON P0014, P0015, P0024, P0025, P0017, o	Toyota	US	PT	125	3/19/2009	T-SB-0094-09
GR 3	Davis, Timothy	08-TMS-0469-T	2GR-FE Engine Ticking Noise and / or MIL ON P0014, P0015, P0024, P0025, P0017, o	Toyota	Mexico	PT	121	3/19/2009	T-SB-0095-09
GR 3	Steger, Tom	09-TMS-0015-T	Torque Converter Flex Lockup Shudder	Toyota	US	PT	51	3/20/2009	T-SB-0096-09
GR 3	Steger, Tom	08-TMS-0468-T	Torque Converter Flex Lockup Shudder	Toyota	US	PT	0	3/23/2009	T-SB-0048-09 Rev1
GR 3	Stutz, Cole	09-TMS-0018-T	M.I.L. "ON" DTC P043E, P043F, P2401, P2402, and P2419	Toyota	US	PT	49	3/24/2009	T-SB-0098-09
GR 3	Stutz, Cole	09-TMS-0008-L	M.I.L. "ON" DTC P0172 & P0175	Lexus	US	PT	57	3/26/2009	L-SB-0032-09
GR 4	Stewart, Scott	08-TMS-0480-T	3UR-FE Accessory Drive Belt Noise	Toyota	US	PT	79	3/4/2009	T-SB-0081-09
GR 4	Curtin, Andy	08-TMS-0213-L	TCM Calibration: Enhancement to Shifting Performance & Smoothness	Lexus	US	PT	8	3/6/2009	L-SB-0002-09 Rev1
GR 4	Curtin, Andy	08-TMS-0473-T	TCM Calibration: Enhancement to Shifting Performance & Smoothness	Toyota	US	PT	8	3/10/2009	T-SB-0050-09 Rev1
GR 4	Curtin, Andy	09-TMS-0005-T	TCM Calibration: Enhancement to Shifting Performance & Smoothness	Toyota	US	PT	69	3/17/2009	T-SB-0090-09
GR 4	Curtin, Andy	09-TMS-0009-L	TCM Calibration: Enhancement to Shifting Performance & Smoothness	Lexus	US	PT	43	3/17/2009	L-SB-0027-09
GR 4	Curtin, Andy	09-TMS-0017-T	TCM Calibration: Enhancement to Shifting Performance & Smoothness	Toyota	US	PT	43	3/17/2009	T-SB-0089-09
GR 4	Stewart, Scott	08-TMS-0331-T	Engine Oil Leak	Toyota	US	PT	12	3/31/2009	T-SB-0320-08 Rev1
GR 5	Stutz, Cole	09-TMS-0030-T	Creak Noise from Right Front Body Structure - RH Engine Mount	Toyota	Mexico	PT	41	3/31/2009	T-SB-0099-09
N/A	Curtin, Andy	08-TMS-0039-L	Automatic Transmission/Transaxle Fluid Level Inspection Temperature Ranges	Lexus	US	PT	322	3/4/2009	L-SB-0023-09
N/A	Steger, Tom	09-TMS-0028-T	A750 Transmission Solenoid Identification	Toyota	Mexico	PT	19	3/4/2009	T-SB-0080-09
N/A	Steger, Tom	09-TMS-0032-T	A340 Transmission Solenoid Identification	Toyota	US	PT	19	3/18/2009	T-SB-0091-09
N/A	Steger, Tom	09-TMS-0034-T	A340 Transmission Solenoid Identification	Toyota	US	PT	15	3/18/2009	T-SB-0092-09
					Average Days		58		
N/A	Buetzer, Ryan	09-TMS-0010-S	Tire Pressure Warning System Activation & Initialization	Scion	US	TI	24	3/6/2009	S-SB-0008-09
N/A	Buetzer, Ryan	08-TMS-0530-T	Tire Pressure Warning System Initialization	Toyota	Mexico	TI	8	3/10/2009	T-SB-0060-09 Rev1
N/A	Buetzer, Ryan	09-TMS-0008-S	2010 MY Scion xB Pre-Delivery Service (PDS)	Scion	US	TI	29	3/11/2009	S-SB-0012-09

ENTIRE PAGE CONFIDENTIAL BUSINESS INFORMATION

Technical Service Bulletins Published in March 2009

PRIORITY	PE	REF#	TITLE	DIVISION	MARKET	DEPT	TOTAL DAYS	RELEASED	PUBLICATION #
N/A	Buetzer, Ryan	08-TMS-0209-L	Floor Mat Installation During PDS	Lexus	US	TI	20	3/23/2009	L-SB-0173-08 Rev1
N/A	Buetzer, Ryan	08-TMS-0439-T	2009 MY Sequoia Pre-Delivery Service (PDS)	Toyota	US	TI	12	3/23/2009	T-SB-0372-08 Rev1
N/A	Buetzer, Ryan	08-TMS-0440-T	2009 MY Sequoia Pre-Delivery Service (PDS)	Toyota	Mexico	TI	12	3/23/2009	T-SB-0373-08 Rev1
N/A	Buetzer, Ryan	08-TMS-0441-T	2009 MY Sequoia PDS Check Sheet	Toyota	US	TI	12	3/23/2009	T-SB-0370-08 Rev1
N/A	Buetzer, Ryan	08-TMS-0442-T	2009 MY Sequoia PDS Check Sheet	Toyota	Mexico	TI	12	3/23/2009	T-SB-0371-08 Rev1
							16		
N/A	Bartrom, Craig	09-TMS-0013-S	Remote Engine Starter (RES) Cold Temperature Operation Diagnostic Tips	Scion	US	VAQ	25	3/24/2009	S-SB-0014-09
N/A	Bartrom, Craig	09-TMS-0022-L	Remote Engine Starter (RES) Cold Temperature Operation Diagnostic Tips	Lexus	US	VAQ	25	3/24/2009	L-SB-0031-09
N/A	Bartrom, Craig	09-TMS-0033-T	Remote Engine Starter (RES) Cold Temperature Operation Diagnostic Tips	Toyota	US	VAQ	32	3/31/2009	T-SB-0100-09
						Average Days	27		

Total Average Days	60
Total YTD Average	55

TOY-TQ001-00040460

ENTIRE PAGE CONFIDENTIAL BUSINESS INFORMATION

Technical Service Bulletins Published in April 2009

PRIORITY	PE	REF#	TITLE	DIVISION	MARKET	DEPT	TOTAL DAYS	RELEASED	PUBLICATION #
GR 3	Mcvea, Seth	09-TMS-0013-L	Crosswind Turbulence Noise at Highway Speeds	Lexus	US	BO	50	4/1/2009	L-SB-0033-09
GR 3	Wenninghoff, T.	09-TMS-0052-T	Sunvisor - Removal & Installation Procedures	Toyota	Mexico	BO	35	4/27/2009	T-SB-0134-09
GR 3	Wenninghoff, T.	08-TMS-0192-T	Upper Instrument Panel Rattle	Toyota	US	BO	35	4/29/2009	T-SB-0304-08 Rev1
GR 5	Mcvea, Seth	09-TMS-0018-L	Rattle/Itch Noise from Driver's Door	Lexus	US	BO	47	4/8/2009	L-SB-0035-09
N/A	Herm, Steven	09-TMS-0003-S	Sunvisor - Removal & Installation Procedure	Scion	US	BO	84	4/6/2009	S-SB-0015-09
N/A	Martin, Ryan	08-TMS-0174-T	Water Leak at Headliner	Toyota	US	BO	15	4/15/2009	T-SB-0141-08 Rev1
					Average Days		44		
GR 2	Jaramillo, Phillip	09-TMS-0040-L	Front Brake Squeak (AWD)	Lexus	US	CH	9	4/17/2009	T-SB-0040-09
GR 4	Casado, Robert	08-TMS-0364-T	Brake Actuator Noise	Toyota	US	CH	9	4/3/2009	T-SB-0307-08 Rev1
N/A	Jaramillo, Phillip	09-TMS-0003-L	Front Brake Squeak (2WD)	Lexus	US	CH	12	4/20/2009	L-SB-0015-09 Rev1
					Average Days		10		
GR 3	Jones, Justin	08-TMS-0380-T	Overhead Digital Compass & Temperature Display Inoperative	Toyota	US	EL	21	4/27/2009	T-SB-0051-09
GR 4	Jewell, Travis	08-TMS-0327-T	HVAC Odor	Toyota	US	EL	260	4/7/2009	T-SB-0103-09
GR 4	Stout, Jim	08-TMS-0184-T	Static Noise from Radio with Rear Defroster On	Toyota	Mexico	EL	42	4/16/2009	T-SB-0148-08 Rev1
GR 4	Jewell, Travis	08-TMS-0020-L	Excessive Dust from HVAC Vents	Lexus	US	EL	38	4/23/2009	L-SB-0032-08 Rev
GR 5	Quirk, Eddie	09-TMS-0019-L	Navigation System Abnormal Operation	Lexus	US	EL	51	4/15/2009	L-SB-0039-09
					Average Days		82		
GR 4	Campbell, Don	09-TMS-0010-T	M.I.L. "ON" DTC P0351, P0352, P0353, and/or P0354	Toyota	US	HPT	81	4/6/2009	T-SB-0101-09
GR 4	Sessions, Dereck	09-TMS-0004-L	M.I.L. "ON" DTC P0351, P0352, P0353, P0354, P0355, and/or P0356	Lexus	US	HPT	96	4/22/2009	L-SB-0043-09
GR 4	Sessions, Dereck	09-TMS-0011-T	M.I.L. "ON" DTC P0351, P0352, P0353, P0354, P0355, and/or P0356	Toyota	US	HPT	96	4/22/2009	T-SB-0131-09
GR 4	Sessions, Dereck	08-TMS-0219-L	M.I.L. "ON" DTC P0AA6 with Information Code 612, Water Leak at Back Door Hatch	Lexus	US	HPT	139	4/29/2009	L-SB-0045-09
N/A	Campbell, Don	09-TMS-0023-T	M.I.L. "ON" DTC P0A84	Toyota	US	HPT	54	4/6/2009	T-SB-0102-09
					Average Days		93		
GR 3	Steger, Tom	09-TMS-0020-L	M.I.L. "ON" DTC P0751	Lexus	US	PT	40	4/7/2009	L-SB-0034-09
GR 3	Stutz, Cole	09-TMS-0023-L	M.I.L. "ON" DTC P0172 & P0175	Lexus	US	PT	49	4/20/2009	L-SB-0041-09
GR 4	Steger, Tom	09-TMS-0026-L	M.I.L. "ON" DTC P0751	Lexus	US	PT	42	4/24/2009	L-SB-0044-09
GR 5	Stover, John	09-TMS-0026-S	Oil Filter Cap Assembly Precautions	Scion	US	PT	22	4/10/2009	S-SB-0024-09
GR 5	Stover, John	09-TMS-0028-L	Oil Filter Cap Assembly Precautions	Lexus	US	PT	22	4/10/2009	L-SB-0036-09
GR 5	Stover, John	09-TMS-0049-T	Oil Filter Cap Assembly Precautions	Toyota	US	PT	23	4/10/2009	T-SB-0104-09
					Average Days		33		
N/A	Buetzer, Ryan	09-TMS-0018-S	2010 tC Pre-Delivery Service Check Sheet	Scion	US	TI	21	4/6/2009	S-SB-0022-09
N/A	Buetzer, Ryan	09-TMS-0019-S	Initialization of Moon Roof During PDS	Scion	US	TI	21	4/6/2009	S-SB-0019-09
N/A	Buetzer, Ryan	09-TMS-0020-S	Initialization of Power Window During PDS	Scion	US	TI	21	4/6/2009	S-SB-0020-09
N/A	Buetzer, Ryan	09-TMS-0021-S	Tire Pressure Warning System Activation & Initialization	Scion	US	TI	21	4/6/2009	S-SB-0016-09
N/A	Buetzer, Ryan	09-TMS-0022-S	Rear Marine Tie-down Hook Removal	Scion	US	TI	21	4/6/2009	S-SB-0018-09
N/A	Buetzer, Ryan	09-TMS-0023-S	DCC Fuse Installation During PDS	Scion	US	TI	21	4/6/2009	S-SB-0017-09
N/A	Buetzer, Ryan	09-TMS-0024-S	Installation of Outside Rear View Mirrors During PDS	Scion	US	TI	21	4/6/2009	S-SB-0021-09
N/A	Buetzer, Ryan	09-TMS-0017-S	2010 MY Scion tC Pre-Delivery Service (PDS)	Scion	US	TI	22	4/7/2009	S-SB-0023-09
N/A	Buetzer, Ryan	09-TMS-0072-T	Initial Calibration of Compass During PDS	Toyota	US	TI	14	4/14/2009	T-SB-0114-09
N/A	Buetzer, Ryan	09-TMS-0073-T	Initial Calibration of Compass During PDS	Toyota	Mexico	TI	14	4/14/2009	T-SB-0113-09
N/A	Buetzer, Ryan	09-TMS-0074-T	Short Pin Installation During PDS	Toyota	US	TI	14	4/14/2009	T-SB-0110-09
N/A	Buetzer, Ryan	09-TMS-0075-T	Short Pin Installation During PDS	Toyota	Mexico	TI	14	4/14/2009	T-SB-0109-09
N/A	Buetzer, Ryan	09-TMS-0076-T	Tire Pressure Warning System Initialization	Toyota	US	TI	14	4/14/2009	T-SB-0108-09
N/A	Buetzer, Ryan	09-TMS-0077-T	Tire Pressure Warning System Initialization	Toyota	Mexico	TI	14	4/14/2009	T-SB-0107-09
N/A	Buetzer, Ryan	09-TMS-0078-T	Front License Plate & Mounting Bracket Installation	Toyota	US	TI	14	4/14/2009	T-SB-0112-09
N/A	Buetzer, Ryan	09-TMS-0079-T	Front License Plate & Mounting Bracket Installation	Toyota	Mexico	TI	14	4/14/2009	T-SB-0111-09
N/A	Buetzer, Ryan	09-TMS-0058-T	Short Pin Installation During PDS	Toyota	US	TI	17	4/16/2009	T-SB-0115-09
N/A	Buetzer, Ryan	09-TMS-0059-T	Short Pin Installation During PDS	Toyota	Mexico	TI	17	4/16/2009	T-SB-0117-09
N/A	Buetzer, Ryan	09-TMS-0064-T	Tire Pressure Warning System Initialization	Toyota	US	TI	17	4/16/2009	T-SB-0116-09
N/A	Buetzer, Ryan	09-TMS-0065-T	Tire Pressure Warning System Initialization	Toyota	Mexico	TI	17	4/16/2009	T-SB-0118-09

ENTIRE PAGE CONFIDENTIAL BUSINESS INFORMATION

Technical Service Bulletins Published in April 2009

PRIORITY	PE	REF#	TITLE	DIVISION	MARKET	DEPT	TOTAL DAYS	RELEASED	PUBLICATION #
N/A	Buetzer, Ryan	09-TMS-0066-T	Initial Calibration of Compass During PDS	Toyota	US	TI	17	4/16/2009	T-SB-0119-09
N/A	Buetzer, Ryan	09-TMS-0067-T	Initial Calibration of Compass During PDS	Toyota	Mexico	TI	17	4/16/2009	T-SB-0120-09
N/A	Buetzer, Ryan	09-TMS-0068-T	2010 MY Sequoia Pre-Delivery Service (PDS)	Toyota	US	TI	17	4/16/2009	T-SB-0125-09
N/A	Buetzer, Ryan	09-TMS-0070-T	2010 MY Sequoia PDS Check Sheet	Toyota	US	TI	16	4/16/2009	T-SB-0124-09
N/A	Buetzer, Ryan	09-TMS-0071-T	2010 MY Sequoia PDS Check Sheet	Toyota	Mexico	TI	16	4/16/2009	T-SB-0123-09
N/A	Buetzer, Ryan	09-TMS-0062-T	Front License Plate Installation During PDS	Toyota	US	TI	18	4/16/2009	T-SB-0121-09
N/A	Buetzer, Ryan	09-TMS-0063-T	Front License Plate Installation During PDS	Toyota	Mexico	TI	18	4/16/2009	T-SB-0122-09
N/A	Buetzer, Ryan	09-TMS-0060-T	2010 MY Tundra PDS Check Sheet	Toyota	US	TI	21	4/20/2009	T-SB-0126-09
N/A	Buetzer, Ryan	09-TMS-0056-T	2010 MY Tundra Pre-Delivery Service (PDS)	Toyota	US	TI	22	4/21/2009	T-SB-0129-09
N/A	Buetzer, Ryan	09-TMS-0057-T	2010 MY Tundra Pre-Delivery Service (PDS)	Toyota	Mexico	TI	22	4/21/2009	T-SB-0130-09
N/A	Buetzer, Ryan	09-TMS-0061-T	2010 MY Tundra PDS Check Sheet	Toyota	Mexico	TI	22	4/21/2009	T-SB-0127-09
N/A	Buetzer, Ryan	09-TMS-0069-T	2010 MY Sequoia Pre-Delivery Service (PDS)	Toyota	Mexico	TI	22	4/21/2009	T-SB-0128-09
N/A	Merryman, James	09-TMS-0104-T	Short Pin Installation During PDS	Toyota	Mexico	TI	14	4/23/2009	T-SB-0133-09
N/A	Merryman, James	09-TMS-0103-T	Short Pin Installation During PDS	Toyota	US	TI	15	4/23/2009	T-SB-0132-09
N/A	Merryman, James	09-TMS-0099-T	Initialization of Power Back Door During PDS	Toyota	US	TI	19	4/28/2009	T-SB-0135-09
N/A	Merryman, James	09-TMS-0100-T	Initialization of Power Back Door During PDS	Toyota	Mexico	TI	19	4/28/2009	T-SB-0136-09
N/A	Merryman, James	09-TMS-0102-T	Front License Plate Installation During PDS	Toyota	Mexico	TI	19	4/28/2009	T-SB-0137-09
N/A	Merryman, James	09-TMS-0097-T	2010 MY Sienna Pre-Delivery Service Check Sheet	Toyota	US	TI	20	4/29/2009	T-SB-0148-09
N/A	Merryman, James	09-TMS-0101-T	Front License Plate Installation During PDS	Toyota	US	TI	20	4/29/2009	T-SB-0145-09
N/A	Merryman, James	09-TMS-0105-T	Initialization of Moon Roof During PDS	Toyota	US	TI	20	4/29/2009	T-SB-0139-09
N/A	Merryman, James	09-TMS-0106-T	Initialization of Moon Roof During PDS	Toyota	Mexico	TI	20	4/29/2009	T-SB-0138-09
N/A	Merryman, James	09-TMS-0109-T	Initialization of Driver's Door Power Window During PDS	Toyota	US	TI	20	4/29/2009	T-SB-0143-09
N/A	Merryman, James	09-TMS-0110-T	Initialization of Driver's Door Power Window During PDS	Toyota	Mexico	TI	20	4/29/2009	T-SB-0142-09
N/A	Merryman, James	09-TMS-0111-T	Tire Pressure Warning System Initialization	Toyota	US	TI	20	4/29/2009	T-SB-0146-09
N/A	Merryman, James	09-TMS-0112-T	Tire Pressure Warning System Initialization	Toyota	Mexico	TI	20	4/29/2009	T-SB-0147-09
N/A	Merryman, James	09-TMS-0113-T	Initialization of Power Sliding Door During PDS	Toyota	US	TI	20	4/29/2009	T-SB-0141-09
N/A	Merryman, James	09-TMS-0114-T	Initialization of Power Sliding Door During PDS	Toyota	Mexico	TI	20	4/29/2009	T-SB-0140-09
N/A	Merryman, James	09-TMS-0108-T	Initial Calibration of Compass During PDS	Toyota	Mexico	TI	20	4/29/2009	T-SB-0144-09
N/A	Merryman, James	09-TMS-0090-T	Initialization of Advanced Parking Guidance System	Toyota	US	TI	21	4/30/2009	T-SB-0150-09
N/A	Merryman, James	09-TMS-0091-T	Tire Pressure Warning System Activation and Initialization	Toyota	US	TI	21	4/30/2009	T-SB-0151-09
N/A	Merryman, James	09-TMS-0094-T	Maintenance for HV & Auxiliary Batteries	Toyota	US	TI	21	4/30/2009	T-SB-0152-09
N/A	Merryman, James	09-TMS-0098-T	2010 MY Sienna Pre-Delivery Service Check Sheet	Toyota	Mexico	TI	21	4/30/2009	T-SB-0149-09
					Average Days		19		

Total Average Days	31
Total YTD Average	48

TOY-TQ001-00040462

ENTIRE PAGE CONFIDENTIAL BUSINESS INFORMATION

Technical Service Bulletins Published in May 2009

PRIORITY	PE	REF#	TITLE	DIVISION	MARKET	DEPT	TOTAL DAYS	RELEASED	PUBLICATION #
GR 3	Cocores, C.	09-TMS-0054-T	Driver's Door Key Cylinder Difficult to Operate	Toyota	US	BO	39	5/4/2009	T-SB-0159-09
GR 4	Fujita, Glen	09-TMS-0021-L	Panoramic Moonroof Glass/Deflector Noise	Lexus	US	BO	91	5/29/2009	L-SB-0065-09
N/A	Herm, Steven	09-TMS-0051-L	Wiper Blade Maintenance and Cleaning	Lexus	US	BO	22	5/14/2009	L-SB-0060-09
N/A	Maulhardt, T.	09-TMS-0050-T	Rear Seat Belt Orientation	Toyota	US	BO	44	5/1/2009	T-SB-0154-09
N/A	Maulhardt, T.	09-TMS-0082-T	Rear Seat Belt Orientation	Toyota	Mexico	BO	29	5/1/2009	T-SB-0153-09
					Average Days		45		
GR 3	Jaramillo, Phillip	09-TMS-0044-L	Rear Strut Supports - Rattle/Knock Noise	Lexus	US	CH	30	5/13/2009	L-SB-0058-09
GR 5	Casado, Robert	08-TMS-0068-L	Tire Inflation Pressure Compensation and Adjustment	Lexus	US	CH	10	5/14/2009	L-SB-0154-08 Rev1
GR 5	Casado, Robert	08-TMS-0148-T	Tire Inflation Pressure Compensation and Adjustment	Toyota	US	CH	11	5/15/2009	T-SB-0345-08 Rev1
					Average Days		17		
GR 1	Jones, Justin	09-TMS-0029-L	Exterior Mirrors Will Not Automatically Return When Shifting from Reverse to Drive	Lexus	US	EL	66	5/29/2009	L-SB-0064-09
GR 3	Fadel, Austin	08-TMS-0220-L	IG1 Relay Freezing	Lexus	US	EL	148	5/13/2009	L-SB-0057-09
GR 4	Koelsch, Robert	08-TMS-0405-T	Smart Key Intermittent No Crank / No Start	Toyota	US	EL	61	5/1/2009	T-SB-0003-09 Rev1
GR 4	Stout, Jim	09-TMS-0009-T	Abnormal Sound from JBL Subwoofer	Toyota	US	EL	121	5/14/2009	T-SB-0164-09
GR3	Charles Lee	08-TMS-0479-T	IG1 Relay Freezing	Toyota	US	EL	33	5/8/2009	T-SB-0047-09 Rev1
					Average Days		86		
GR 2	Stutz, Cole	09-TMS-0034-S	2ZR-FE Engine Oil Consumption	Scion	US	PT	36	5/28/2009	S-SB-0029-09
GR 3	Steger, Tom	09-TMS-0031-L	M.I.L. "ON" DTC P0751	Lexus	US	PT	56	5/29/2009	L-SB-0063-09
GR 3	Stutz, Cole	09-TMS-0032-L	M.I.L. "ON" DTC P0172 & P0175	Lexus	US	PT	55	5/28/2009	L-SB-0061-09
GR 4	Steger, Tom	09-TMS-0030-L	M.I.L. "ON" DTC P0751	Lexus	US	PT	56	5/29/2009	L-SB-0062-09
GR 4	Curtin, Andy	09-TMS-0029-S	M.I.L. "ON" DTC P0351, P0352, P0353 and/or P0354	Scion	US	PT	42	5/21/2009	S-SB-0028-09
GR 4	Stutz, Cole	09-TMS-0008-T	Transverse Engine Mount - Abnormal Noise and Vibration on Acceleration	Toyota	Mexico	PT	122	5/14/2009	T-SB-0165-09
GR 4	Sessions, Dereck	09-TMS-0085-T	M.I.L. "ON" DTC P0AC0, P0A1F, P0A7F, and/or P0AFA	Toyota	US	PT	51	5/28/2009	T-SB-0166-09
GR 5	Curtin, Andy	08-TMS-0033-T	Intake Manifold Noise	Toyota	US	PT	15	5/6/2009	T-SB-0034-08 Rev1
					Average Days		54		
N/A	Buetzer, Ryan	09-TMS-0033-L	Front License Plate & Mounting Bracket Installation	Lexus	US	TI	28	5/5/2009	L-SB-0050-09
N/A	Buetzer, Ryan	09-TMS-0034-L	Tire Pressure Warning System Activation & Initialization	Lexus	US	TI	28	5/5/2009	L-SB-0046-09
N/A	Buetzer, Ryan	09-TMS-0035-L	Front Wheel Opening Extension Pad Installation During PDS	Lexus	US	TI	28	5/5/2009	L-SB-0048-09
N/A	Buetzer, Ryan	09-TMS-0036-L	DCC Fuse Installation During PDS	Lexus	US	TI	28	5/5/2009	L-SB-0047-09
N/A	Buetzer, Ryan	09-TMS-0037-L	Initial Calibration of Compass During PDS	Lexus	US	TI	28	5/5/2009	L-SB-0051-09
N/A	Buetzer, Ryan	09-TMS-0038-L	Initialization of Front Seat Memory ECU	Lexus	US	TI	28	5/5/2009	L-SB-0049-09
N/A	Buetzer, Ryan	09-TMS-0046-L	Short Pin Installation During PDS	Lexus	US	TI	20	5/6/2009	L-SB-0054-09
N/A	Buetzer, Ryan	09-TMS-0047-L	Maintenance for HV & Auxiliary Batteries	Lexus	US	TI	20	5/6/2009	L-SB-0053-09
N/A	Buetzer, Ryan	09-TMS-0047-L	Maintenance for HV & Auxiliary Batteries	Lexus	US	TI	13	5/27/2009	L-SB-0053-09 Rev1
N/A	Buetzer, Ryan	09-TMS-0048-L	Front License Plate & Mounting Bracket Installation	Lexus	US	TI	20	5/6/2009	L-SB-0055-09
N/A	Buetzer, Ryan	09-TMS-0049-L	Tire Pressure Warning System Activation & Initialization	Lexus	US	TI	27	5/13/2009	L-SB-0059-09
N/A	Buetzer, Ryan	09-TMS-0050-L	Initial Calibration of Compass During PDS	Lexus	US	TI	20	5/6/2009	L-SB-0052-09
N/A	Buetzer, Ryan	08-TMS-0481-T	2010 MY Camry Pre-Delivery Service (PDS)	Toyota	US	TI	6	5/20/2009	T-SB-0040-09 Rev1
N/A	Buetzer, Ryan	08-TMS-0489-T	Front License Plate & Mounting Bracket Installation	Toyota	US	TI	14	5/12/2009	T-SB-0011-09 Rev1
N/A	Buetzer, Ryan	08-TMS-0499-T	2010 MY Camry HV Pre-Delivery Service (PDS)	Toyota	US	TI	6	5/20/2009	T-SB-0046-09 Rev1
N/A	Buetzer, Ryan	09-TMS-0062-T	Front License Plate Installation During PDS	Toyota	US	TI	8	5/20/2009	T-SB-0121-09 Rev1
N/A	Buetzer, Ryan	09-TMS-0063-T	Front License Plate Installation During PDS	Toyota	Mexico	TI	8	5/20/2009	T-SB-0122-09 Rev1
N/A	Merryman, James	09-TMS-0088-T	2010 Prius Pre Delivery Service (PDS)	Toyota	US	TI	27	5/6/2009	T-SB-0161-09
N/A	Merryman, James	09-TMS-0089-T	2010 Prius PDS Checksheet	Toyota	US	TI	26	5/5/2009	T-SB-0160-09
N/A	Merryman, James	09-TMS-0092-T	Short Pin Installation During PDS	Toyota	US	TI	23	5/1/2009	T-SB-0156-09
N/A	Merryman, James	09-TMS-0093-T	Front License Plate & Mounting Bracket Installation	Toyota	US	TI	23	5/1/2009	T-SB-0157-09
N/A	Merryman, James	09-TMS-0095-T	2010 MY Sienna Pre-Delivery Service (PDS)	Toyota	US	TI	23	5/1/2009	T-SB-0155-09

TOY-TQ001-00040463

ENTIRE PAGE CONFIDENTIAL BUSINESS INFORMATION

Technical Service Bulletins Published in May 2009

PRIORITY	PE	REF#	TITLE	DIVISION	MARKET	DEPT	TOTAL DAYS	RELEASED	PUBLICATION #
N/A	Merryman, James	09-TMS-0096-T	2010 MY Sienna Pre-Delivery Service (PDS)	Toyota	Mexico	TI	25	5/4/2009	T-SB-0158-09
N/A	Merryman, James	09-TMS-0103-T	Short Pin Installation During PDS	Toyota	US	TI	7	5/4/2009	T-SB-0132-09 Rev1
N/A	Merryman, James	09-TMS-0107-T	Initial Calibration of Compass During PDS	Toyota	US	TI	34	5/13/2009	T-SB-0163-09
N/A	Merryman, James	09-TMS-0108-T	Initial Calibration of Compass During PDS	Toyota	Mexico	TI	3	5/15/2009	T-SB-0144-09 Rev1
					Average Days		20		

Total Average Days	35
Total YTD Average	46

TOY-TQ001-00040464

ENTIRE PAGE CONFIDENTIAL BUSINESS INFORMATION

Technical Service Bulletins Published in June 2009

PRIORITY	PE	REF#	TITLE	DIVISION	MARKET	DEPT	TOTAL DAYS	RELEASED	PUBLICATION #
GR 3	Hitt, Christopher	09-TMS-0036-T	Jack Band Separation (Double Cab Models)	Toyota	US	BO	96	6/9/2009	T-SB-0171-09
GR 3	Mcvea, Seth	09-TMS-0027-L	Inner Rear View Mirror Vibration	Lexus	US	BO	92	6/19/2009	L-SB-0072-09
GR 3	Wenninghoff, T.	09-TMS-0125-T	Limited Driver's Seat Cushion Cover Side Vinyl Cracking	Toyota	US	BO	59	6/26/2009	T-SB-0188-09
GR 4	Cocores, C.	08-TMS-0187-L	Lower Seat Cushion Uncomfortable	Lexus	US	BO	242	6/9/2009	L-SB-0071-09
GR 4	Maulhardt, T.	09-TMS-0053-T	Wind Noise From Antenna	Toyota	US	BO	93	6/25/2009	T-SB-0186-09
GR 4	Maulhardt, T.	09-TMS-0081-T	Wind Noise From Antenna	Toyota	Mexico	BO	83	6/25/2009	T-SB-0185-09
N/A	Herm, Steven	08-TMS-0191-T	Front Seat Squeak Noise	Toyota	US	BO	110	6/10/2009	T-SB-0288-08 Rev1
N/A	Wenninghoff, T.	09-TMS-0084-T	LH or RH A-Pillar Garnish Loose or Dropping Down	Toyota	US	BO	70	6/16/2009	T-SB-0178-09
N/A	Herm, Steven	08-TMS-0009-ST	Toyota Seat Belt Extender	Toyota	US	BO	64	6/24/2009	T-SB-0315-08 Rev1
						Average Days	101		
GR 3	Jaramillo, Phillip	09-TMS-0044-L	Rear Strut Supports - Rattle/Knock Noise	Lexus	US	CH	13	6/15/2009	L-SB-0058-09 Rev1
GR 4	Wagner, Randy	09-TMS-0024-L	Squawk/Bark Type Noise from Brake Actuator	Lexus	US	CH	89	6/2/2009	L-SB-0069-09
GR 4	Casado, Robert	09-TMS-0027-S	Tire Inflation Pressure Compensation and Adjustment	Scion	US	CH	93	6/26/2009	S-SB-0033-09
GR 4	Wagner, Randy	09-TMS-0056-L	Brake Booster Vacuum Check Valve Rattle/Buzz Noise	Lexus	US	CH	43	6/26/2009	L-SB-0074-09
GR4	Kim, Tom	09-TMS-0041-T	Brake Vibration	Toyota	US	CH	84	6/4/2009	T-SB-0169-09
GR4	Kim, Tom	09-TMS-0025-L	Brake Vibration	Lexus	US	CH	84	6/4/2009	L-SB-0070-09
						Average Days	68		
GR 1	Stout, Jim	09-TMS-0047-T	No Sound From Audio System or Trunk Lid Noise	Toyota	US	EL	77	6/2/2009	T-SB-0168-09
GR 1	Jones, Justin	09-TMS-0055-T	Combination Meter - Intermittent Display	Toyota	US	EL	77	6/11/2009	T-SB-0172-09
GR 3	Lee, Charles	08-TMS-0507-T	IG1 Relay Freezing	Toyota	US	EL	168	6/2/2009	T-SB-0167-09
GR 3	Koelsch, Robert	07-TMS-0005-L	Smart Key Intermittent No Crank/No Start	Lexus	US	EL	94	6/4/2009	L-SB-0161-08 Rev1
GR 3	Lee, Charles	09-TMS-0035-T	IG1 Relay Freezing	Toyota	US	EL	100	6/12/2009	T-SB-0176-09
GR 3	Lee, Charles	09-TMS-0036-S	IG1 Relay Freezing	Scion	US	EL	30	6/12/2009	S-SB-0031-09
GR 3	Lee, Charles	09-TMS-0037-T	IG1 Relay Freezing	Toyota	US	EL	98	6/12/2009	T-SB-0177-09
GR 4	Jewell, Travis	08-TMS-0099-L	HVAC Odor	Lexus	US	EL	316	6/2/2009	L-SB-0068-09
GR 4	Quirk, Eddie	09-TMS-0039-L	Navigation Map Update Error	Lexus	US	EL	56	6/2/2009	L-SB-0067-09
GR 5	Jones, Justin	09-TMS-0123-T	Third Row Power Seat Inoperative	Toyota	US	EL	62	6/23/2009	T-SB-0183-09
						Average Days	108		
GR 2	Steger, Tom	09-TMS-0040-T	AB60 Transmission C1 Clutch Damage	Toyota	US	PT	86	6/4/2009	T-SB-0170-09
GR 2	Stutz, Cole	09-TMS-0033-S	No Start or Extended Crank and/or MIL "ON" DTC P030# or P0015	Scion	US	PT	59	6/19/2009	S-SB-0032-09
GR 2	Stutz, Cole	09-TMS-0122-T	No Start or Extended Crank and/or MIL "ON" DTC P030# or P0015	Toyota	US	PT	59	6/19/2009	T-SB-0182-09
GR 3	Davis, Timothy	09-TMS-0045-L	Exhaust Drone Noise at Operating Temperature While Stationary in Drive	Lexus	US	PT	48	6/1/2009	L-SB-0066-09
GR 3	Steger, Tom	09-TMS-0080-T	A750E Transmission Extension Housing Seal Service Tip	Toyota	US	PT	69	6/11/2009	T-SB-0173-09
GR 3	Stutz, Cole	09-TMS-0137-T	M.I.L. "ON" DTC P0456	Toyota	US	PT	28	6/11/2009	T-SB-0175-09
GR 3	Steger, Tom	08-TMS-0078-T	Transmission Fluid Leak through Driveshaft Yoke	Toyota	US	PT	35	6/15/2009	T-SB-0055-08 Rev1
GR 3	Davis, Timothy	08-TMS-0200-L	Engine Ticking Noise and/or MIL "ON" P0014, P0015, P0024, P0025, P0017, or P0018	Lexus	US	PT	41	6/15/2009	L-SB-0028-09 Rev1
GR 3	Sessions, Dereck	09-TMS-0120-T	MIL "ON" DTC P3101, P3190 and/or P3191	Toyota	US	PT	57	6/17/2009	T-SB-0180-09
GR 3	Davis, Timothy	08-TMS-0465-T	2GR-FE Engine Ticking Noise and/or MIL "ON" P0014, P0015, P0024, P0025, P0017, c	Toyota	US	PT	44	6/18/2009	T-SB-0094-09 Rev1
GR 3	Davis, Timothy	09-TMS-0053-L	MIL "ON" DTC P0505	Lexus	US	PT	47	6/23/2009	L-SB-0073-09
GR 3	Davis, Timothy	09-TMS-0130-T	2GR-FE MIL "ON" DTC P0505	Toyota	US	PT	49	6/24/2009	T-SB-0184-09
GR 5	Stutz, Cole	09-TMS-0028-S	M.I.L. "ON" DTC P0455 & P0441 or P0456	Scion	US	PT	54	6/2/2009	S-SB-0030-09
GR 5	Stover, John	09-TMS-0144-T	Oil Filter Cap Assembly Precautions	Toyota	Mexico	PT	20	6/11/2009	T-SB-0174-09
N/A	Curtin, Andy	09-TMS-0048-T	MIL "ON" DTC P2103, P2111 and/or P2112	Toyota	US	PT	99	6/25/2009	T-SB-0187-09
						Average Days	53		

TOY-TQ001-00040465

ENTIRE PAGE CONFIDENTIAL BUSINESS INFORMATION

Technical Service Bulletins Published in June 2009

PRIORITY	PE	REF#	TITLE	DIVISION	MARKET	DEPT	TOTAL DAYS	RELEASED	PUBLICATION #
GR 1	Merryman, James	09-TMS-0145-T	Front Spoiler Under Cover & Rear Side Spoiler Installation During PDS	Toyota	US	TI	22	6/17/2009	T-SB-0179-09
N/A	Buetzer, Ryan	09-TMS-0058-T	Short Pin Installation & VSC light Clearance during PDS	Toyota	US	TI	19	6/16/2009	T-SB-0115-09 Rev1
N/A	Buetzer, Ryan	09-TMS-0059-T	Short Pin Installation & VCS light Clearance During PDS	Toyota	Mexico	TI	19	6/16/2009	T-SB-0117-09 Rev1
N/A	Merryman, James	09-TMS-0092-T	Short Pin Installation During PDS	Toyota	US	TI	10	6/18/2009	T-SB-0156-09 Rev1
N/A	Merryman, James	08-TMS-0054-L	HDD Navigation Map Update Process	Lexus	US	TI	13	6/24/2009	L-SB-0049-08 Rev1
						Average Days	17		
N/A	Peterson, Lonnie	09-TMS-0138-T	Cross Bar Wind Noise	Toyota	US	VAQ	31	6/18/2009	T-SB-0181-09
						Average Days	31		

Total Average Days	70
Total YTD Average	49

TOY-TQ001-00040466

ENTIRE PAGE CONFIDENTIAL BUSINESS INFORMATION

Technical Service Bulletins Published in July 2009

PRIORITY	PE	REF#	TITLE	DIVISION	MARKET	DEPT	TOTAL DAYS	RELEASED	PUBLICATION #
GR 3	Maulhardt, T	09-TMS-0127-T	Water Condensation Dripping From Headliner	Toyota	US	BO	87	7/30/2009	T-SB-0241-09
GR 4	Mcvea, Seth	09-TMS-0015-S	Driver's Seatback Lock Release Lever Inoperative	Scion	US	BO	138	7/21/2009	S-SB-0041-09
GR 4	Wenninghoff, T	09-TMS-0042-T	Body Floor Pan Noise	Toyota	US	BO	111	7/1/2009	T-SB-0190-09
GR 4	Maulhardt, T	09-TMS-0139-T	Rattle Noise From A-Pillar	Toyota	US	BO	65	7/22/2009	T-SB-0214-09
GR 4	Maulhardt, T	09-TMS-0178-T	Wind Noise From Front Door	Toyota	US	BO	35	7/31/2009	T-SB-0247-09
N/A	Herm, Steven	08-TMS-0190-T	Upper/Lower Windshield/Rear Glass Tick Noise	Toyota	US	BO	54	7/13/2009	T-SB-0142-08 Rev2
N/A	Herm, Steven	09-TMS-0003-S	Repair Manual Supplement - Sunvisor Removal & Installation Procedure	Scion	US	BO	54	7/20/2009	S-SB-0015-09 Rev1
						Average Days	78		
GR 3	Casado, Robert	09-TMS-0002-ST	ABS MIL "ON" DTC C0210 or C0215	Toyota	US	CH	130	7/6/2009	T-SB-0205-09
GR 3	Casado, Robert	09-TMS-0014-S	ABS MIL "ON" DTC C0210 or C0215	Scion	US	CH	129	7/6/2009	S-SB-0040-09
GR 4	Kim, Tom	09-TMS-0025-L	Brake Vibration	Lexus	US	CH	14	7/15/2009	L-SB-0070-09 Rev1
GR 4	Wagner, Randy	09-TMS-0041-T	Brake Vibration	Toyota	US	CH	69	7/9/2009	T-SB-0169-09
GR 4	Wagner, Randy	09-TMS-0141-T	Brake Booster Rattle/Buzz Noise	Toyota	US	CH	69	7/27/2009	T-SB-0229-09
GR 4	Casado, Robert	09-TMS-0146-T	Steering Intermediate Shaft Knocking Noise	Toyota	US	CH	59	7/31/2009	T-SB-0243-09
						Average Days	78		
GR 2	Lui, Ted	09-TMS-0022-T	Abnormal Horn Operation	Toyota	US	EL	147	7/7/2009	T-SB-0207-09
GR 3	Lee, Charles	08-TMS-0479-T	IG1 Relay Freezing	Toyota	US	EL	69	7/21/2009	T-SB-0047-09 Rev2
GR 4	Quirk, Eddie	09-TMS-0148-T	Abnormal Radio Faceplate Operation	Toyota	US	EL	51	7/29/2009	T-SB-0238-09
						Average Days	89		
GR 2	Stutz, Cole	09-TMS-0143-T	No Start and/or Extended Crank Condition	Toyota	Mexico	PT	68	7/28/2009	T-SB-0234-09
GR 3	Stewart, Scott	08-TMS-0009-T	Driveshaft "Thunk"	Toyota	US	PT	8	7/22/2009	T-SB-0117-08 Rev1
GR 3	Stewart, Scott	08-TMS-0346-T	Air Injection Pump With Water Intrusion: MIL "ON" DTC P0418, P0419, and/or P244#	Toyota	US	PT	19	7/13/2009	T-SB-0329-08 Rev1
GR 3	Steger, Tom	09-TMS-0060-L	MIL "ON" DTC P0751	Lexus	US	PT	29	7/9/2009	L-SB-0076-09
GR 3	Stutz, Cole	09-TMS-0151-T	MIL "ON" DTC P0456	Toyota	US	PT	36	7/17/2009	T-SB-0213-09
GR 3	Curtin, Andy	09-TMS-0165-T	MIL "ON" DTC P0500	Toyota	US	PT	30	7/15/2009	T-SB-0212-09
GR 3	Stewart, Scott	09-TMS-0176-T	MIL "ON" DTC P0500	Toyota	US	PT	39	7/31/2009	T-SB-0242-09
GR 3	Stutz, Cole	09-TMS-0177-T	MIL "ON" DTC P0456	Toyota	US	PT	32	7/28/2009	T-SB-0235-09
						Average Days	33		
N/A	Buetzer, Ryan	08-TMS-0180-L	Tire Positioning Before New Vehicle Delivery	Lexus	US	TI	20	7/6/2009	L-SB-0139-08 Rev2
N/A	Buetzer, Ryan	08-TMS-0209-L	Floor Mat Installation During PDS	Lexus	US	TI	22	7/8/2009	L-SB-0173-09 Rev2
N/A	Buetzer, Ryan	09-TMS-0038-S	2010 MY Scion xD Pre-Delivery Service (PDS)	Scion	US	TI	19	7/6/2009	S-SB-0039-09
N/A	Buetzer, Ryan	09-TMS-0039-S	2010 MY Scion xD Pre-Delivery Service Check Sheet	Scion	US	TI	19	7/6/2009	S-SB-0038-09
N/A	Buetzer, Ryan	09-TMS-0040-S	Dome Fuse Installation During PDS	Scion	US	TI	19	7/6/2009	S-SB-0037-09
N/A	Buetzer, Ryan	09-TMS-0041-S	Tire Pressure Warning System Activation & Initialization	Scion	US	TI	15	7/2/2009	S-SB-0036-09
N/A	Buetzer, Ryan	09-TMS-0042-S	Front License Plate Installation During PDS	Scion	US	TI	15	7/2/2009	S-SB-0035-09
N/A	Buetzer, Ryan	09-TMS-0062-T	Front License Plate Installation During PDS	Toyota	US	TI	11	7/27/2009	T-SB-0121-09 Rev2
N/A	Buetzer, Ryan	09-TMS-0063-L	Short Pin Installation During PDS	Lexus	US	TI	24	7/10/2009	L-SB-0079-09
N/A	Buetzer, Ryan	09-TMS-0063-T	Front License Plate Installation During PDS	Toyota	Mexico	TI	11	7/27/2009	T-SB-0122-09 Rev2
N/A	Buetzer, Ryan	09-TMS-0064-L	Roof Rack Cross Bar Installation During PDS	Lexus	US	TI	24	7/10/2009	L-SB-0080-09
N/A	Buetzer, Ryan	09-TMS-0065-L	Installation of Towing Wire Harness Connector During PDS	Lexus	US	TI	23	7/9/2009	L-SB-0077-09
N/A	Buetzer, Ryan	09-TMS-0066-L	Tire Pressure Warning System Activation & Initialization	Lexus	US	TI	24	7/10/2009	L-SB-0078-09
N/A	Buetzer, Ryan	09-TMS-0067-L	Front Lincense Plate & Mounting Bracket Installation	Lexus	US	TI	24	7/10/2009	L-SB-0081-09
N/A	Buetzer, Ryan	09-TMS-0068-L	Maintenance for HV & Auxiliary Batteries	Lexus	US	TI	21	7/15/2009	L-SB-0086-09
N/A	Buetzer, Ryan	09-TMS-0069-L	Tire Pressure Warning System Activation & Initialization	Lexus	US	TI	21	7/15/2009	L-SB-0085-09
N/A	Buetzer, Ryan	09-TMS-0070-L	Front Wheel Opening Extension Pad Installation During PDS	Lexus	US	TI	21	7/15/2009	L-SB-0088-09
N/A	Buetzer, Ryan	09-TMS-0071-L	Engine Under Cover Installation During PDS	Lexus	US	TI	21	7/15/2009	L-SB-0087-09
N/A	Buetzer, Ryan	09-TMS-0072-L	Front Mounting Bracket & License Plate Installation	Lexus	US	TI	21	7/15/2009	L-SB-0083-09
N/A	Buetzer, Ryan	09-TMS-0073-L	Short Pin Installation During PDS	Lexus	US	TI	21	7/15/2009	L-SB-0082-09
N/A	Buetzer, Ryan	09-TMS-0074-L	Initial Calibration of Compass During PDS	Lexus	US	TI	21	7/15/2009	L-SB-0084-09
N/A	Buetzer, Ryan	09-TMS-0076-L	Hybrid System Electrical Safety Precautions	Lexus	US	TI	19	7/15/2009	L-SB-0089-09

ENTIRE PAGE CONFIDENTIAL BUSINESS INFORMATION

Technical Service Bulletins Published in July 2009

PRIORITY	PE	REF#	TITLE	DIVISION	MARKET	DEPT	TOTAL DAYS	RELEASED	PUBLICATION #
N/A	Merryman, James	09-TMS-0088-T	2010 Prius Pre Delivery Service (PDS)	Toyota	US	TI	24	7/10/2009	T-SB-0161-09 Rev1
N/A	Merryman, James	09-TMS-0089-T	2010 Prius Pre Delivery Service Check Sheet	Toyota	US	TI	43	7/10/2009	T-SB-0160-09 Rev1
N/A	Merryman, James	09-TMS-0094-T	Maintenance for HV & Auxiliary Batteries	Toyota	US	TI	16	7/2/2009	T-SB-0152-09 Rev1
N/A	Saunders, Jill	09-TMS-0153-T	DCC Fuse Installation During PDS	Toyota	Mexico	TI	17	7/2/2009	T-SB-0194-09
N/A	Saunders, Jill	09-TMS-0154-T	Disc Brake Anti-Rust Cover Removal	Toyota	Mexico	TI	17	7/2/2009	T-SB-0191-09
N/A	Saunders, Jill	09-TMS-0155-T	Initialization of Driver's Door Power Window	Toyota	Mexico	TI	21	7/6/2009	T-SB-0198-09
N/A	Saunders, Jill	09-TMS-0156-T	2010 MY Hiace Pre-Delivery Service (PDS)	Toyota	Mexico	TI	22	7/7/2009	T-SB-0206-09
N/A	Saunders, Jill	09-TMS-0157-T	2010 Hiace Pre-Delivery Service Check Sheet	Toyota	Mexico	TI	21	7/6/2009	T-SB-0201-09
N/A	Saunders, Jill	09-TMS-0159-T	Installation of Towing Wire Harness Connector During PDS	Toyota	Mexico	TI	21	7/6/2009	T-SB-0203-09
N/A	Saunders, Jill	09-TMS-0160-T	Roof Rack Cross Bar Installation During PDS	Toyota	Mexico	TI	21	7/6/2009	T-SB-0199-09
N/A	Saunders, Jill	09-TMS-0161-T	Short Pin Installation During PDS	Toyota	Mexico	TI	21	7/6/2009	T-SB-0202-09
N/A	Saunders, Jill	09-TMS-0162-T	Tire Pressure Warning System Activation & Initialization	Toyota	Mexico	TI	21	7/6/2009	T-SB-0196-09
N/A	Saunders, Jill	09-TMS-0163-T	2010 Land Cruiser PDS Check Sheet	Toyota	Mexico	TI	23	7/8/2009	T-SB-0208-09
N/A	Saunders, Jill	09-TMS-0164-T	2010 MY Land Cruiser Pre-Delivery Service (PDS)	Toyota	Mexico	TI	25	7/10/2009	T-SB-0211-09
N/A	Saunders, Jill	09-TMS-0166-T	Tire Pressure Warning System Activation & Initialization	Toyota	US	TI	20	7/6/2009	T-SB-0197-09
N/A	Saunders, Jill	09-TMS-0167-T	Short Pin Installation During PDS	Toyota	US	TI	20	7/6/2009	T-SB-0195-09
N/A	Saunders, Jill	09-TMS-0168-T	Roof Rack Cross Bar Installation During PDS	Toyota	US	TI	20	7/6/2009	T-SB-0204-09
N/A	Saunders, Jill	09-TMS-0169-T	2010 MY Land Cruiser Pre-Delivery Service (PDS)	Toyota	US	TI	24	7/10/2009	T-SB-0210-09
N/A	Saunders, Jill	09-TMS-0170-T	Installation of Towing Wire Harness Connector During PDS	Toyota	US	TI	20	7/6/2009	T-SB-0200-09
N/A	Saunders, Jill	09-TMS-0171-T	Front License Plate Installation During PDS	Toyota	US	TI	16	7/2/2009	T-SB-0192-09
N/A	Saunders, Jill	09-TMS-0172-T	Front License Plate Installation During PDS	Toyota	Mexico	TI	22	7/2/2009	T-SB-0193-09
N/A	Saunders, Jill	09-TMS-0172-T	Front License Plate Installation During PDS	Toyota	Mexico	TI	22	7/8/2009	T-SB-0193-09
N/A	Saunders, Jill	09-TMS-0194-T	Initial Calibration of Compass During PDS	Toyota	US	TI	9	7/24/2009	T-SB-0217-09
N/A	Merryman, James	09-TMS-0195-T	2010 Avalon PDS Check Sheet	Toyota	US	TI	15	7/30/2009	T-SB-0239-09
N/A	Merryman, James	09-TMS-0197-T	Smart Key System Check During PDS	Toyota	US	TI	12	7/27/2009	T-SB-0225-09
N/A	Merryman, James	09-TMS-0198-T	Initial Calibration of Compass During PDS	Toyota	US	TI	12	7/27/2009	T-SB-0221-09
N/A	Saunders, Jill	09-TMS-0199-T	License Plate Installation During PDS	Toyota	US	TI	12	7/27/2009	T-SB-0224-09
N/A	Merryman, James	09-TMS-0200-T	Tire Pressure Warning System Initialization	Toyota	US	TI	12	7/27/2009	T-SB-0226-09
N/A	Saunders, Jill	09-TMS-0201-T	2010 MY Tacoma Pre-Delivery Service (PDS)	Toyota	US	TI	13	7/28/2009	T-SB-0232-09
N/A	Merryman, James	09-TMS-0202-T	Initialization of Moon Roof During PDS	Toyota	US	TI	12	7/27/2009	T-SB-0223-09
N/A	Saunders, Jill	09-TMS-0203-T	2010 Tacoma PDS Check Sheet	Toyota	US	TI	13	7/28/2009	T-SB-0231-09
N/A	Merryman, James	09-TMS-0204-T	Initialization of Power Window During PDS	Toyota	US	TI	12	7/27/2009	T-SB-0230-09
N/A	Saunders, Jill	09-TMS-0205-T	Tire Pressure Warning System Initialization	Toyota	US	TI	9	7/24/2009	T-SB-0220-09
N/A	Merryman, James	09-TMS-0206-T	Short Pin Installation During PDS	Toyota	US	TI	12	7/27/2009	T-SB-0227-09
N/A	Merryman, James	09-TMS-0207-T	Front License Plate & Mounting Bracket Installation	Toyota	US	TI	12	7/27/2009	T-SB-0222-09
N/A	Merryman, James	09-TMS-0208-T	2010 MY Avalon Pre-Delivery Service (PDS)	Toyota	US	TI	15	7/30/2009	T-SB-0240-09
N/A	Saunders, Jill	09-TMS-0211-T	Initial Calibration of Compass During PDS	Toyota	Mexico	TI	12	7/27/2009	T-SB-0228-09
N/A	Saunders, Jill	09-TMS-0212-T	License Plate Installation During PDS	Toyota	Mexico	TI	9	7/24/2009	T-SB-0218-09
N/A	Merryman, James	09-TMS-0213-T	Protective Film Removal Outside Door Handle Area	Toyota	US	TI	14	7/29/2009	T-SB-0236-09
N/A	Merryman, James	09-TMS-0215-T	2010 Avanza Pre-Delivery Service Check Sheet	Toyota	Mexico	TI	16	7/31/2009	T-SB-0244-09
N/A	Merryman, James	09-TMS-0217-T	Back Up Fuse Installation During PDS	Toyota	Mexico	TI	9	7/24/2009	T-SB-0216-09
N/A	Merryman, James	09-TMS-0218-T	2010 MY Avanza Pre-Delivery Service (PDS)	Toyota	Mexico	TI	16	7/31/2009	T-SB-0245-09
N/A	Merryman, James	09-TMS-0219-T	Front Emergency Towing Eyelet & Eyelet Hole Cover	Toyota	Mexico	TI	9	7/24/2009	T-SB-0215-09
N/A	Saunders, Jill	09-TMS-0220-T	Tire Pressure Warning System Initialization	Toyota	Mexico	TI	9	7/24/2009	T-SB-0219-09
N/A	Saunders, Jill	09-TMS-0221-T	2010 Tacoma PDS Check Sheet	Toyota	Mexico	TI	13	7/28/2009	T-SB-0233-09
N/A	Saunders, Jill	09-TMS-0222-T	2010 MY Tacoma Pre-Delivery Service (PDS)	Toyota	Mexico	TI	14	7/29/2009	T-SB-0237-09
N/A	Saunders, Jill	09-TMS-0224-T	Roof Rack Cross Bar Installation During PDS	Toyota	US	TI	11	7/31/2009	T-SB-0246-09
						Average Days	18		

Total Average Days	32
Total YTD Average Days	45

TOY-TQ001-00040468