Form Approved: O.M.B. No. 2127-0008

U.S. Department of Transportation

National Highway Traffic Safety Administration

DOT Auto Safety Hotline

Vehicle Owner's Questionnaire

To Report Vehicle Safety Defects
1-888-DASH-2-DOT
(1-888-327-4236)
INTERNET:www.nhtsa.dot.gov/hotline

FOR AGENCY USE ONLY 100148

Date Received	Repository ☐
02-MAY-2007	Reference No. 10189487

OWNER INFORMATION (Type or Print)

Name [redacted]		Daytime Telephone Number [redacted]	E-mail Address [redacted]
Address [redacted]		Evening Telephone Number [redacted]	
City CORONA	**State** CA	**Zip Code** [redacted]	

Do you authorize NHTSA to provide a copy of this report to the manufacturer of your vehicle? ☒ *YES* ☐ *NO*
In the absence of an authorization, NHTSA WILL NOT provide your name or address to the vehicle manufacturer.

Signature of Owner _____ Date ___/___/___

VEHICLE INFORMATION

17 digit Vehicle Identification Number Located at bottom of windshield on driver's side	Make	Model	Model Year
JTHBJ46G272[redacted]	LEXUS	ES350	2007

Date Purchased	Dealer's Name and Telephone Number			Engine:	Fuel Type:
01-SEP-06				No: Cylinders	
Original Owner ☒	Dealer's City	State	Zip Code		

Transmission Type			Vehicle Component Code
AUTOMATIC	☒ Antilock Brakes ☐ Cruise Control	Powertrain	180000 VEHICLE SPEED CONTROL Multiple Failure: 1

FAILED COMPONENT(S)/PART(S) INFORMATION

Incident Date(s)	Failure Mileage	Failure Speed
21-DEC-2006	3000	65

ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A TIRE FAILURE

Tire Make	Tire Model (Name or Number)	Tire Size (Example P215/65R15)
DOT No. (Example: DOTMAL9ABC036)	☐ Original Equipment ☐ Prior Repair	Failure Location:
Tire Component Code		Tire Failure Type

ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A CHILD SEAT FAILURE

Make:	Date Manufactured:	Model No./Name:
Seat Type:	Installation System:	
Child Seat Component Code:	Failed Part:	

APPLICABLE INCIDENT INFORMATION

(Please describe in detail the incident(s), Failure(s), Crash(es), and injury(ies).)

Crash	Fire	Number of Persons Iniured	Number of Deaths	Reported to Police
☐ Yes ☒ No	☐ Yes ☒ No	1	0	N

Narrative Description of Incident(S), Crash(es), and Injury(ies).
Please describe (1) events leading up to the failure, (2) failure and its consequences, and (3) what was done to correct the failure; i.e, parts repaired or replaced (and if old part is available).

UNEXPLAINED ACCELERATION / TIMING COVER SEAL TO THE ENGINE BLOCK☐
MY 2007 ES350 ACCELERATED OUT OF CONTROL REACHING THE SPEED OF 95 MILES PER HOUR. THE ONLY WAY I WAS ABLE TO SLOW THE CAR DOWN WAS TO PUT THE CAR IN NEUTRAL. AND THEN IT BEGAN TO SLOW DOWN. I TOOK INTO TO MY LOCAL DEALER AND THEY WHERE NOT ABLE TO DIAGNOSE THE PROBLEM. IN APRIL OF 2207 I NOTICES MY ES350 HAD A SMALL OIL LINK WHEN THE DEALER INSPECTED THE VEHICLE THY FOUND THAT THE TIMING COVER TO THE ENGINE BLOCK WAS POORLY SEALED AND WOULD NEED TO BE REPAIRED. I WAS TOLD THERE WAS A SERVICE BULLETIN OUT ON THE SEALS AND MY CAR WOULD NEED TO BE IN THE SHOP ABOUT A WEEK TO REPAIR. *TR

Include, if available: Police/Fire Department Report, Photos, and Repair Invoice. ATTACH ADDITIONAL SHEETS IF NECESSARY

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond this questionnaire. Your response may be used to assist the NHTSA in determining whether a Manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.