OFFICE OF DEFECTS INVESTIGATION (ODI)

Complaints - Search Results

5 Records Displayed.

Report Date : **October 22, 2007 at *10:47 AM***

ODI Numbers Searched: **10198196,10195294,10182586,10180652**

Make : TOYOTA **Model :** TACOMA **Year :** 2007

Manufacturer : TOYOTA MOTOR CORPORATION

Crash : No **Fire :** No **Number of Injuries:** 0

ODI ID Number : 10195294 **Number of Deaths:** 0

Date of Failure: March 1, 2007

VIN : 5TELU42N77Z...

Component: EQUIPMENT:ELECTRICAL:AIR CONDITIONER

Summary:

MY TRUCK A 2007 TOYOTA TACOMA DOUBLE CAB, LURKS FORWARD A BIT WHEN AIR CONDITIONING (A/C)IS ON. THIS HAPPENS WHEN AT STOP EVEN WITH FOOT ON THE BRAKE. I SUSPECT THIS OCCURS WHEN A/C COMPRESSOR KICKS IN AS IT RECYCLES. COUPLE OF TIMES EITHER I ALMOST BUMPED THE CAR THAT STOPPED IN FRONT OF ME OR HIT A PEDESTRIAN WALKING RIGHT IN FROM OF ME. I NEVER EXPERIENCED ANY OF IT ON OTHER VEHICLES. IT JUST MAKES ME CONCERNED. I THOUGHT I WAS THE ONLY ONE EXPERIENCED THIS ON TACOMA TRUCK, BUT NOTICED ALMOST ALL OF TACOMA OWNERS AGREED WITH THIS PROBLEM(ACCORDING TO INTERNET FORUM, TOYOTANATIONS.COM. I WILL BE VISITING THE DEALER VERY SOON ,BUT HEARD FROM OTHER PEOPLE THAT THEY WERE TOLD BY THE DEALER THAT IT WAS JUST NORMAL. MY SAFETY CONCERN REGARDING THE TRUCK LED ME TO FILE THIS COMPLAINT. PLEASE NOTE THAT THIS PROBLEM IS ONGOING .I CAN'T REMEMBER WHEN I FIRST USED A/C ON MY VEHICLE. THANK YOU. *AK

Make : TOYOTA **Model :** TACOMA **Year :** 2007

Manufacturer : TOYOTA MOTOR CORPORATION

Crash : No **Fire :** No **Number of Injuries:** 0

ODI ID Number : 10182586 **Number of Deaths:** 0

Date of Failure: February 13, 2007

VIN : 5TEUU42NX7Z...

Component: VEHICLE SPEED CONTROL:ACCELERATOR PEDAL

Summary:

I WAS DRIVING ON INTERSTATE 55. I WENT TO PASS A SEMI TRUCK. MY SPEED AT THIS TIME WAS 65 MPH. I STEPPED ON THE ACCELERATOR AND STARTED TO CHANGE LANES, THE TRANSMISSION DOWN SHIFTED TO A PASSING GEAR AND THE THROTTLE WAS WIDE OPEN AND IT STAYED THAT WAY. I SHUT OFF THE IGNITION AND TURNED IT BACK ON, THE THROTTLE WAS STILL WIDE OPEN. I TRIED THIS A TOTAL OF THREE TIMES, NOW I AM GOING WELL OVER 80 MPH. I FINALLY LEFT THE IGNITION OFF AND COASTED OVER TO THE SIDE OF THE ROAD. MY WIFE ASKED WHAT HAD JUST HAPPENED AND I TOLD HER THAT THE THROTTLE WAS STUCK OPEN. I ASKED HER TO LOOK ON THE FLOOR SO SHE COULD SHE NOTHING WAS STUCK ANYWHERE NEAR THE ACCELERATOR PEDAL. I MIGHT ADD THE CRUISE CONTROL WAS NOT ON. I RESTARTED THE TRUCK AND CAUTIOUSLY WENT TO OUR DINNER ENGAGEMENT. AFTER DINNER WE USED EXTREME CAUTION ON OUR WAY BACK HOME. I TRIED SEVERAL TIMES TO REPLICATE THE PROBLEM. IT NEVER DID PRODUCE ITSELF ON OUR RETURN TRIP. I CALLED TOYOTA ON MONDAY MORNING AND AFTER TELLING THEM THE PROBLEM THEY WANTED ME TO DRIVE THE TRUCK BACK TO THE DEALER I REFUSED. I MADE THEM COME TOW IT. IT WAS CHECKED OUT BY THE FIELD ENGINEER AND WAS RETURNED TO ME. THEY SAID NOTHING WAS FOUND TO BE OUT OF ORDER. BUT WENT INTO DETAIL THAT THE FLOOR MATS WERE NOT INSTALLED CORRECTLY. THIS TRUCK HAD 149 MILES ON IT. IT WAS ONLY 4 DAYS OLD. *JB

Make : TOYOTA **Model :** TACOMA **Year :** 2007

Manufacturer : TOYOTA MOTOR CORPORATION

Crash : No **Fire :** No **Number of Injuries:** 0

ODI ID Number : 10180652 **Number of Deaths:** 0

Date of Failure: January 24, 2007

VIN : 5TELU42N17Z...

Component: VEHICLE SPEED CONTROL

Summary:

AT A FULL STOP AT AN INTERSECTION THE TRUCK ACCELERATED BY ITSELF HARD ENOUGH THE BRAKE WOULD NOT HOLD IT. PUSHING THE TRUCK ONTO THE ROAD WITH ONCOMING TRAFFIC. THE CAR MISSED ME. PLEASE DO NOT QUESTION MY ABILITY TO PUSH ON THE BRAKE AND NOT THE GAS AS YOU HAVE IN ALL THE REPORTS I HAVE READ. *NM SEE ALSO 10181486 *DSY

Make : TOYOTA **Model :** TACOMA **Year :** 2007

Manufacturer : TOYOTA MOTOR CORPORATION

Crash : No **Fire :** No **Number of Injuries:** 0

ODI ID Number : 10198196 **Number of Deaths:** 0

Date of Failure: March 10, 2007

VIN : 3TMLU42N37M...

Component: POWER TRAIN:DRIVELINE

Summary:

TRUCK "SURGES" FORWARD WHEN AT A COMPLETE STOP. TRUCK ALSO EXHIBITS VIBRATION IN THE DRIVETRAIN AT LOW SPEEDS/ LOW RPMS THIS IS CONSTANT AND RECURRING SINCE I BOUGHT MY VEHICLE. 2007 TOYOTA TACOMA DOUBLE CAB. *JB

Make : TOYOTA **Model :** TACOMA **Year :** 2007

Manufacturer : TOYOTA MOTOR CORPORATION

Crash : No **Fire :** No **Number of Injuries:** 0

ODI ID Number : 10198196 **Number of Deaths:** 0

Date of Failure: March 10, 2007

VIN : 3TMLU42N37M...

Component: VEHICLE SPEED CONTROL

Summary:

TRUCK "SURGES" FORWARD WHEN AT A COMPLETE STOP. TRUCK ALSO EXHIBITS VIBRATION IN THE DRIVETRAIN AT LOW SPEEDS/ LOW RPMS THIS IS CONSTANT AND RECURRING SINCE I BOUGHT MY VEHICLE. 2007 TOYOTA TACOMA DOUBLE CAB. *JB