TOYOTA

Special Service Campaign (SSC) – 70F (Safety Recall) Q&A
Toyota Camry All Weather Floor Mat for 2007 and Early 2008 Toyota Camry

CONFIDENTIAL DRAFT

Q1: What is the condition?

A1: The optional Toyota Camry All Weather Floor Mat is specifically engineered and manufactured for Camry vehicles. This includes two grommet holes in the All Weather Floor Mat and retaining hooks (clips) to secure the mat to the vehicle's carpet. In recent months, Toyota has received reports regarding the Toyota Camry All Weather Floor Mat accessory slipping forward and interfering with the movement of the accelerator pedal. Toyota has investigated these reports and determined that if the optional Toyota Camry All Weather Floor Mat (either by itself or if it is placed on top of an existing carpeted floor mat) is not secured by the retaining hooks (clips) and the mat moves forward, it may interfere with the accelerator pedal from returning to the idle position. If the mat is properly secured, it will not interfere with the accelerator pedal.

Q2: What is the cause of this condition?

A2: If the optional Toyota Camry All Weather Floor Mat (either by itself or if it is placed on top of an existing carpeted floor mat) is not secured by the retaining hooks (clips) and the mat moves forward, it may interfere with the accelerator pedal from returning to the idle position.

Q3: Are there any warnings that this condition exists?

A3: Yes, customers may verify the floor mat is properly secured using the retaining hooks (clips) provided. If the mat is properly secured, it will not interfere with the accelerator pedal. Good times to check are after filling the vehicle's tank with gasoline, after a carwash and/or vehicle interior cleaning, when another driver is about to drive the vehicle, etc. More than one floor mat should never be used in the driver's seating position, as the retaining hooks (clips) are designed to accommodate only one floor mat at a time. Customers may refer to the floor mat section of their Owner's Manual for further information regarding the retaining hooks (clips).

Q4: Which and how many floor mats are involved?

A4: The *optional* Toyota Camry All Weather Floor Mat specifically designed for the driver's seating position in 2007 and early 2008 Toyota Camry vehicles are involved. There are approximately 30,500 Toyota Camry All Weather Floor Mats involved in this campaign.

Q5: Are there any other Toyota or Lexus All Weather Floor Mats involved?

A5: Yes, this condition also involves the Lexus ES 350 All Weather Floor Mat. There are approximately 38,500 Lexus ES 350 All Weather Floor Mats specifically designed for 2007 and early 2008 model year vehicles involved.

Q6: How many vehicles are involved?

A6: Approximately 30,500 Toyota Camry and 38,500 Lexus ES 350 vehicles are equipped with the All Weather Floor Mats designed for 2007 and early 2008 model year vehicles. To assure over-the-counter accessory sales customers are also notified, approximately 600,000 Toyota Camry and 110,000 Lexus ES 350 vehicle owners will be sent notifications.

Q7: What is the production period of the affected All Weather Floor Mats?

A7: The affected Toyota Camry and Lexus ES 350 All Weather Floor Mats were produced from February, 2006 to mid-September, 2007.

Q8: How many incidents of this condition have been reported?

A8: There have been XXX cases of this condition reported in the affected vehicles.

Q9: Have there been any accidents reported?

A9: There have been XXX accident cases reported in the affected vehicles which may relate to this condition.

Q10: What is Toyota going to do?

A10: In early October, 2007, Toyota will begin sending a preliminary Safety Recall notification to owners of the involved vehicles to inform them of the recall and the timing when the replacement All Weather Floor Mat for the driver's seating position will become available. Once the replacement mat is available, it will be exchanged at no charge to owners. A second owner notification will be sent when the replacement floor mat is available. The original driver's seating position All Weather Floor Mat will be exchanged for the new one at that time.

Q11: When will the replacement All Weather Floor Mat become available?

A11: Toyota is currently developing a design modification to the driver's seating position All Weather Floor Mat. We anticipate the new mat will be ready in two to three months. Toyota will send another notification when the new driver's seating position All Weather Floor Mat is available. The original driver's seating position All Weather Floor Mat will be exchanged for the new one at that time.

Q12: What should an owner do until the replacement Toyota Camry All Weather Floor Mat is available?

A12: Until the replacement All Weather Floor Mat for the driver's seating position is ready, we request the customer's assistance in regularly verifying the floor mat is properly secured using the retaining hooks (clips) provided. If the mat is properly secured, it will not interfere with the accelerator pedal. Good times to check are after filling the vehicle's tank with gasoline, after a carwash and/or vehicle interior cleaning, when another driver is about to drive the vehicle, etc. More than one floor mat should never be used in the driver's seating position, as the retaining hooks (clips) are designed to accommodate only one floor mat at a time.

Q13: What if the customer does not have the Toyota Camry or Lexus ES 350 All Weather Floor Mat?

A13: If the vehicle does not have the Toyota Camry or Lexus ES 350 All Weather Floor Mat designed for 2007 and early 2008 model year vehicles, it is **NOT** involved in this recall. However, during our investigation, it was noted that floor mat interference is possible in any vehicle with any combination of floor mats. Therefore, if you utilize non-Toyota/non-Lexus floor mats, please make sure they are also properly secured using the appropriate retention device and do not place them on top of another floor mat.

Q14: What if you experience accelerator pedal interference prior to your appointment?

A14: Each circumstance may vary, and drivers must use their best judgment, but Toyota is providing the following instructions and warnings if the All Weather Floor Mat should interfere with the accelerator pedal:

- If it is possible and safe to do so, pull back the floor mat as it may dislodge the accelerator pedal from the All Weather Floor Mat.
- If you need to stop the vehicle immediately, firmly step on the brake pedal with both feet. Do not pump the brake pedal as it will deplete the vacuum utilized for the power brake assist.
- In the Lexus ES 350 or Toyota Camry equipped with the Engine Start/Stop button, if you can safely stop the vehicle, firmly hold down the Engine Start/Stop button for at least three seconds to turn off the engine. Do not tap the Engine Start Stop button. However, by turning off the engine, you will lose both power brake assist and power steering assist.
- In a traditional key ignition Toyota Camry, if you can safely stop the vehicle, turn the ignition key to the ACC position. Again, by turning the key to the ACC position, you will lose both power brake assist and power steering. Do not remove the key from the ignition. If you remove the key from the ignition, the steering wheel will lock.

Above all, until the replacement All Weather Floor Mat for the driver's seating position is ready, we request the customer's assistance in regularly verifying the floor mat is properly secured using the

retaining hooks (clips) provided. If the mat is properly secured, it will not interfere with the accelerator pedal.