National Highway Traffic Safety Administration
Our Mission: Save lives, prevent injuries, reduce vehicle-related crashes

For Immediate Release
Wednesday, September 26, 2007

Contact: Rae Tyson
Telephone: (202) 366-9550

NHTSA CONSUMER ADVISORY: Secure Floor Mats in 2007 Lexus ES350, Camry, Other Toyotas; Advisory Also Extended to Other Vehicles

Toyota to Conduct Floor Mat Recall

Owners of 2007 Lexus ES 350 models and certain other Toyota vehicles are being urged to make sure the driver-side, "All Weather" floor mats are properly secured before driving the vehicles, according to the National Highway Traffic Safety Administration and Toyota Motor Company.

Toyota announced it will conduct a recall of all the affected floor mats, which are used in the 2007 Lexus ES 350 as well as the 2007 Camry.

NHTSA and Toyota noted that, if unsecured, the mats being recalled can slip forward and trap the accelerator pedal, causing the vehicle to accelerate uncontrollably.

AAlthough not part of the recall, NHTSA urged drivers of other Toyota models, including Avalons and Prius hybrids, to check the driver-side floor mats to make sure they are properly installed.

While the recall is underway, drivers of these Toyota vehicles are strongly urged to make sure the driver-side floor mat is properly secured to the retention hooks on the floorboard. Also, never overlay two mats on top of each other because the retention hooks cannot secure the top-most mat which can then can slip and trap the accelerator pedal.

Of course, depending on vehicle design, it is possible for unsecured floor mats to interfere with accelerator or brake pedals in a wide range of vehicles. Therefore, NHTSA reminds all drivers of all makes and models to check the driver-side floor mats for secure installation and to follow manufacturer instructions for installing the mats.

For more information, consumers can contact the National Highway Traffic Safety Administration's Hotline at 888-327-423 or their Toyota or Lexus dealer.



Example of an unsecured driver-side floor mat trapping the accelerator pedal in a 2007 Lexus ES350



Always make sure your driver-side floor mat is properly secured by the tabs. Never overlay two mats on top o each other because the top-most mat can not be secured properly by the retention hooks.

To view high resolution versions of the above images, click here and here.

TOY-TQ001-00040673