



Toyota Customer Services

Toyota Motor Sales, U.S.A., Inc.  
19001 South Western Avenue, S207  
Torrance, CA 90509

November 5, 2009

Associate Administrator for Enforcement  
National Highway Traffic Safety Administration  
U.S. Department of Transportation  
1200 New Jersey Avenue S.E.  
Washington, DC 20590

Gentlemen:

Pursuant to Section 579.5, Chapter V, Title 49, enclosed is one copy of each document sent during the month of October 2009:

**TOYOTA TECHNICAL SERVICE BULLETIN**

- |   |  |
|---|--|
| 1 NUMBER: T-SB- 0350-09<br>SECTION: Engine Control<br>DATE: October 1, 2009<br>MODEL: '10 Tundra            | 2 NUMBER: T-SB- 0351-09<br>SECTION: Navigation/Multi Info Display<br>DATE: October 2, 2009<br>MODEL: '08-'09 4Runner   |
| 3 NUMBER: T-SB- 0352-09<br>SECTION: Cooling<br>DATE: October 6, 2009<br>MODEL: '10 Prius                    | 4 NUMBER: T-SB- 0356-09<br>SECTION: Heating/Air Conditioning<br>DATE: October 7, 2009<br>MODEL: '08 Highlander HV  |
| 5 NUMBER: T-SB- 0358-09<br>SECTION: Fuel System<br>DATE: October 12, 2009<br>MODEL: '05-'08 Corolla, Matrix | 6 NUMBER: T-SB- 0200-08 Rev1<br>SECTION: Automatic Transmission/Transaxle<br>DATE: October 14, 2009<br>MODEL: '06-'10 4Runner, Avalon, Camry, Corolla,<br>FJ Cruiser, Highlander, Land<br>Cruiser, Matrix, RAV4, Sequoia,<br>Sienna, Solara, Tacoma, Tundra,<br>Venza, Yaris |
| 7 NUMBER: T-SB- 0362-09<br>SECTION: Cooling<br>DATE: October 14, 2009<br>MODEL: '09-'10 Corolla, Matrix     | 8 NUMBER: T-SB- 0260-08 Rev1<br>SECTION: Automatic Transmission/Transaxle<br>DATE: October 16, 2009<br>MODEL: '06-'10 4Runner, Avalon, Camry, Corolla,<br>FJ Cruiser, Highlander, Land<br>Cruiser, Matrix, RAV4, Sequoia,<br>Sienna, Solara, Tacoma, Tundra,<br>Venza, Yaris |

9 NUMBER: T-SB- 0364-09  
SECTION: Meter/Gauge/Display  
DATE: October 19, 2009  
MODEL: '07-'09 Camry HV

10 NUMBER: T-SB- 0075-08 Rev1  
SECTION: Heating/Air Conditioning  
DATE: October 20, 2009  
MODEL: '06-'09 Avalon  
'07-'10 Camry, Camry HV

11 NUMBER: T-SB- 0301-08 Rev1  
SECTION: Engine Mechanical  
DATE: October 20, 2009  
MODEL: '00-'10 4Runner, Avalon, Camry, Corolla,  
Land Cruiser, RAV4, Sienna,  
Solara, Tacoma, Tundra  
'07-'10 Camry HV, FJ Cruiser, Yaris  
'00-'05 Celica, Echo, MR2 Spyder  
'06-'10 Highlander HV  
'01-'10 Highlander, Prius, Sequoia  
'03-'10 Matrix  
'09-'10 Venza

12 NUMBER: T-SB- 0286-09 Rev1  
SECTION: Pre-Delivery Service  
DATE: October 22, 2009  
MODEL: '10 4Runner

13 NUMBER: T-SB- 0365-09  
SECTION: Pre-Delivery Service  
DATE: October 22, 2009  
MODEL: '10 Venza

14 NUMBER: T-SB- 0366-09  
SECTION: Pre-Delivery Service  
DATE: October 22, 2009  
MODEL: '10 Venza

15 NUMBER: T-SB- 0367-09  
SECTION: Pre-Delivery Service  
DATE: October 22, 2009  
MODEL: '10 Venza

16 NUMBER: T-SB- 0368-09  
SECTION: Pre-Delivery Service  
DATE: October 22, 2009  
MODEL: '10 Venza

17 NUMBER: T-SB- 0369-09  
SECTION: Garage Door Opener  
DATE: October 22, 2009  
MODEL: '09 Venza

18 NUMBER: T-SB- 0370-09  
SECTION: Pre-Delivery Service  
DATE: October 23, 2009  
MODEL: '10 4Runner

19 NUMBER: T-SB- 0371-09  
SECTION: Pre-Delivery Service  
DATE: October 23, 2009  
MODEL: '10 Venza

20 NUMBER: T-SB- 0372-09  
SECTION: Pre-Delivery Service  
DATE: October 26, 2009  
MODEL: '10 Venza

21 NUMBER: T-SB- 0293-09 Rev1  
SECTION: Pre-Delivery Service  
DATE: October 30, 2009  
MODEL: '10 4Runner

**SCION TECHNICAL SERVICE BULLETIN**

1 NUMBER: S-SB- 0042-08 Rev1  
SECTION: Engine Mechanical  
DATE: October 7, 2009  
MODEL: '05-'10 tC  
'04-'06 xA, xB  
'08-'10 xB, xD

2 NUMBER: S-SB- 0041-08 Rev1  
SECTION: Automatic Transmission/Transaxle  
DATE: October 8, 2009  
MODEL: '06-'10 tC  
'06 xA, xB  
'08-'10 xB, xD

3 NUMBER: S-SB- 0048-09  
SECTION: Cooling  
DATE: October 12, 2009  
MODEL: '08-'09 xD

4 NUMBER: S-SB- 0040-08 Rev1  
SECTION: Automatic Transmission/Transaxle  
DATE: October 13, 2009  
MODEL: '06-'10 tC  
'06 xA, xB  
'08-'10 xB, xD

### LEXUS TECHNICAL SERVICE BULLETIN

1 NUMBER: L-SB- 0139-09  
SECTION: Pre-Delivery Service  
DATE: October 6, 2009  
MODEL: '10 LS460

2 NUMBER: L-SB- 0140-09  
SECTION: Pre-Delivery Service  
DATE: October 6, 2009  
MODEL: '10 LS460

3 NUMBER: L-SB- 0141-09  
SECTION: Pre-Delivery Service  
DATE: October 6, 2009  
MODEL: '10 LS460

4 NUMBER: L-SB- 0142-09  
SECTION: Pre-Delivery Service  
DATE: October 6, 2009  
MODEL: '10 LS460

5 NUMBER: L-SB- 0143-09  
SECTION: Pre-Delivery Service  
DATE: October 6, 2009  
MODEL: '10 LS460

6 NUMBER: L-SB- 0144-09  
SECTION: Pre-Delivery Service  
DATE: October 6, 2009  
MODEL: '10 LS460

7 NUMBER: L-SB- 0145-09  
SECTION: Pre-Delivery Service  
DATE: October 6, 2009  
MODEL: '10 LS460

8 NUMBER: L-SB- 0146-09  
SECTION: Pre-Delivery Service  
DATE: October 6, 2009  
MODEL: '10 LS460

9 NUMBER: L-SB- 0147-09  
SECTION: Pre-Delivery Service  
DATE: October 6, 2009  
MODEL: '10 LS460

10 NUMBER: L-SB- 0148-09  
SECTION: Pre-Delivery Service  
DATE: October 7, 2009  
MODEL: '10 LS460

11 NUMBER: L-SB- 0153-08 Rev1  
SECTION: Automatic Transmission/Transaxle  
DATE: October 13, 2009  
MODEL: '06-'10 ES330, ES350, GS300, GS350,  
GS430, GX460, GX470, IS250,  
IS350, LS430, LX470, LX570,  
RX330, RX350, SC430

12 NUMBER: L-SB- 0084-08 Rev1  
SECTION: Automatic Transmission/Transaxle  
DATE: October 14, 2009  
MODEL: '06 ES330, GS300, LS430, RX330  
'07-'10 ES350, GS350, LS460  
'06-'07 GS430, LX470  
'08-'10 GS460, IS F, LX570  
'10 GX460, RX350  
'06-'09 GX470  
'06-'10 IS250, IS350, SC430  
'07-'09 RX350

13 NUMBER: L-SB- 0150-09  
SECTION: Automatic Transmission/Transaxle  
DATE: October 14, 2009  
MODEL: '07-'09 SC430

14 NUMBER: L-SB- 0151-09  
SECTION: Rear Suspension  
DATE: October 14, 2009  
MODEL: '06-'09 IS250, IS350

15 NUMBER: L-SB- 0085-08 Rev1  
 SECTION: Engine Mechanical  
 DATE: October 20, 2009  
 MODEL: '00-'03 ES300, RX300  
 '04-'06 ES330, RX330  
 '07-'10 ES350, GS350, GS450H, LS460,  
 RX350  
 '00-'06 GS300  
 '00 GS400, LS400, SC300, SC400  
 '01-'07 GS430  
 '08-'10 GS460, IS F, LS600H, LX570  
 '10 GX460, RX450H  
 '03-'09 GX470  
 '06-'10 IS250, IS350  
 '01-'05 IS300  
 '01-'06 LS430  
 '00-'07 LX470  
 '06-'08 RX400H  
 '02-'10 SC430

16 NUMBER: L-SB- 0152-09  
 SECTION: Exterior Panels/Trim  
 DATE: October 28, 2009  
 MODEL: '10 RX350, RX450H

### REGION/DISTRIBUTOR LETTER

- 1 LSC 90D - Limited Service Campaign for 2001-2004 Model Year Tacoma's Minnesota Dealer Information Packet for Wisconsin Dealers
- 2 LSC 90D - Limited Service Campaign for 2001-2004 Model Year Tacoma's Wisconsin Dealer Information Packet
- 3 Safety Campaign (Special Service Campaign) - 90L. Owner Notification to Provide *Interim* Information on Potential Floor Mat Interference with Accelerator Pedal
- 4 Safety Recall (Special Service Campaign) - 90H (Phase 2). Certain '09-'10 Corolla, Corolla Matrix and '08-'09 Scion xD Vehicles Equipped with 2ZR-FE (1.8 liter) engine Brake System Vacuum Port.
- 5 Special Service Campaign (Non-Compliance Recall) - 90J. Update to Vehicle Capacity Weight and Gross Vehicles Weight Rating
- 6 Limited Service Campaign (LSC) - 90K. 2005-2006 Avalon and 2006 RAV4 Vehicles Equipped with the V6 (2GR-FE) Engine VVT-I Oil Hose Replacement
- 7 LSC 90D - Limited Service Campaign for 2001-2004 Model Year Tacoma's Maryland Dealer Information Packet
- 8 LSC 90D - Limited Service Campaign for 2001-2004 Model Year Tacoma's Indiana Dealer Information Packet
- 9 LSC 90D - Limited Service Campaign for 2001-2004 Model Year Tacoma's Massachusetts Dealer Information Packet

**DEALER LETTER**

- 1 LSC 90D - Limited Service Campaign for 2001-2004 Model Year Tacoma's Minnesota Dealer Information Packet for Wisconsin Dealers
- 2 LSC 90D - Limited Service Campaign for 2001-2004 Model Year Tacoma's Wisconsin Dealer Information Packet
- 3 Safety Campaign (Special Service Campaign) - 90L. Owner Notification to Provide *Interim* Information on Potential Floor Mat Interference with Accelerator Pedal
- 4 Safety Recall (Special Service Campaign) - 90H (Phase 2). Certain '09-'10 Corolla, Corolla Matrix and '08-'09 Scion xD Vehicles Equipped with 2ZR-FE (1.8 liter) engine Brake System Vacuum Port.
- 5 Special Service Campaign (Non-Compliance Recall) - 90J. Update to Vehicle Capacity Weight and Gross Vehicles Weight Rating
- 6 Limited Service Campaign (LSC) - 90K. 2005-2006 Avalon and 2006 RAV4 Vehicles Equipped with the V6 (2GR-FE) Engine VVT-I Oil Hose Replacement
- 7 LSC 90D - Limited Service Campaign for 2001-2004 Model Year Tacoma's Maryland Dealer Information Packet
- 8 LSC 90D - Limited Service Campaign for 2001-2004 Model Year Tacoma's Indiana Dealer Information Packet
- 9 LSC 90D - Limited Service Campaign for 2001-2004 Model Year Tacoma's Massachusetts Dealer Information Packet

**ELECTRONIC COMMUNICATION**

- 1 Lexus Consumer Safety Advisory. Potential Floor Mat Interference with Accelerator Pedal - Updated 10-02-2009 \*\*\*\*URGENT\*\*\*\*
- 2 Toyota Carpeted Floor Mats New Vehicles. UPDATE (10/20/09)
- 3 Toyota Carpeted Floor Mats New Vehicles. UPDATE (10/21/09)
- 4 Special Service Campaign - 90H -Phase 2. Certain '09-'10 Corolla, Matrix and '08 - '09 Scion xD Vehicles Equipped with 2ZR-FE (1.8 liter) Engines Brake System Vacuum Port.
- 5 Limited Service Campaign - 90K. Certain 2005-2006MY Avalon and 2006MY RAV4 Vehicles Equipped with the V6 (2GR-FE) Engine Variable Valve Timing with Intelligence (VVT-i) Oil Hose Replacement
- 6 Safety Campaign (Special Service Campaign) - 90L. Owner Notification to Provide *Interim* Information on Potential Floor Mat Interference with Accelerator Pedal

7 Toyota-Lexus Consumer Safety Advisory. Potential Floor Mat Interference with Accelerator Pedal.

If you require further copies or information, please contact this office.

Respectfully,

TOYOTA MOTOR SALES, U.S.A., INC.

A handwritten signature in black ink, appearing to read 'G. Morino', with a stylized flourish extending from the end.

George Morino  
National Quality Compliance Manager

/dg

Enclosures