

unknown," he wrote.

"In each case, the vehicle was accelerating at a rate below maximum and went to and stayed at maximum without driver command." told ConsumerAffairs.Com.

"A simple touching of the lever that disengages the <u>cruise control</u> caused the system to immediately go back to a normal condition with the cruise control off," told us.

said he is "a qualified professional engineer and systems analyst." His work "has involved automobiles as well as aircraft and industrial systems."

"I can assure you," told Consumer Affairs. Com, "that the incidences that I had did not involve mechanical sticking or jamming of the <u>accelerator pedal</u> because of a piece of carpet. It was not driver error."

In problem opinion, "the problem may be in the cruise control system itself, either a mechanical, electronic or electrical problem in the cruise control system."

"The problem could easily cause a serious accident if the driver, caught unaware, did not take immediate remedial action," according to our reader in New Mexico.

Toyota did not respond to requests for comment.

Report Your Experience

If you've had a bad experience with a consumer product or service, we'd like to hear about it. All complaints are reviewed by class action attorneys and are considered for publication on our site. Knowledge is power! Help spread the word. File your consumer report now.

0 diggs 460

bookmark this on del.icio.us be the first to bookmark this page!

Back to the top

· Ads by Google

**Hybrid Battery** 

Diesel Hybrid

**Hybrid Motor** 

GM Hybrid

Home | Rogues Gallery | Good Guys | Complaint Form | News | Recalls | Search | Video | FAQ |
Consumer Resources | Small Claims Guide | Lemon Law | Newsletter | Contact Us
Advertise With Us | Testimonials | Newsroom | RSS Feeds | Radio | Job Postings

Advertisement

Privacy by BY Safe!

Print, Email & More

**€**⇔ SAVE THIS

€ A PRINT THIS

MOST POPULA

RSS FEEDS

TEST BRO

with the PURCHA
Purchase a 60 mi
and get a second
card FREE!!

120 MINUTES +
A FREE MOTOROL
ALL FOR ONLY \$
ONLY \$19.94