Best regards, ************************************
USECI
000CA000000000000000000000000000000000

TMC CADD Engineering Administration Dept Tel 0561-74-4665 Ext. 8-41-4665 Fax 0561-74-4966 Ext. 8-41-4966 IIIE-Maill Fukunori_ito@mail.toyota.co.jp
2007/03/26 18:04
Hello Michael-san
I was informed the captioned issue by CQE person and Tomizuka-san last Friday. If you have a detail action of this issue, please let us know. I heard TMS PQSS discussed to make some campaign letter to customer.
Have those problem vehicle genuine accessory rubber floor mat? I would like to confirm that ES350 genuine rubber mat has two clip holes and with clips or not.
When you will implement a customer campaign for this issue, youlshould ask CADD a request of it.
Best Regards,
************ Followed by Japanese ***********************************
Tomozuta-san IISECI
D0000000000000000000000000000000000000
000000000000000000000000000000000000000

Frank <fukunori> Ito Quality Group TMC CADD Engineering Administration Dept Tel 0561-74-4665 Ext. 8-41-4665 Fax 0561-74-4966 Ext. 8-41-4966</fukunori>

ENTIRE PAGE CONFIDENTIAL BUSINESS INFORMATION

IIE-Maill Fukunori_ito@mail.toyota.co.jp