

retention hole.

Thank you,

Tony Meneses

-----Original Message-----

From: Chris\_Noshad@Toyota.com [mailto:Chris\_Noshad@Toyota.com]  
Sent: Friday, March 16, 2007 3:41 PM  
To: tony@thermoflexcorp.com  
Cc: Michael\_Collinsworth@Toyota.com  
Subject: Tundra All Weather Mat Missing Clip PQR, Ref #50873

Tony,

Here is the Tundra All Weather Mat with missing clips report. This PQR is rated as a QPI. Per our discussion, please make sure the root cause is identified and the process is fool proof as the issue severity rating may elevate if the issue continue to reoccur. Please refer to the cover sheet for replacement clip quantity & shipment direction.

(See attached file: Tundra All weather Mat PQR, Ref #50873.doc) (See attached file: Tundra all weather Mat PQR Cover Letter, Ref #50873.pdf)

Chris Noshad

Sr. Field Quality Assurance Engineer

(310) 468-2562

(310) 468-4075 FaxS

[attachment "DSC\_0005.JPG" deleted by Cyd Miyamoto/TMS/Toyota] [attachment "DSC\_0006.JPG" deleted by Cyd Miyamoto/TMS/Toyota]