Subject: Lexus IS250 AWD Recall.

On Friday we submitted a recall with NHTSA regarding the 2006 MY Lexus IS250 AWD. On only the AWD models, there is a possibility that a section of a pad on the carpet may interfere with the accelerator pedal, which could prevent the pedal from returning to the idle position. 3,567 vehicles are affected.

Chris Santucci - Safety Engineer Technical and Regulatory Affairs Toyota Motor North America, Inc. Phone (202) 463-6856 Fax: (202) 463-8513 email: Chris Santucci@tma.toyota.com