



ORIGINAL

01-22-N11B-4053

RECEIVED

1990 NOV -6 AM 10: 23

OFFICE DEFECTS INVESTIGATION

B 11/7/90 pdy

CB

3pgs

November 5, 1990

Administrator
National Highway Traffic
Safety Administration
400 Seventh Street, S.W.
Washington, D.C. 20590

Attention: V.I.N. Co-ordinator

Please find attached updated listing of information encoded in MCI V.I.N's. New information for models that will be introduced during the 1991 model year are denoted as "NEW"

Should you require further information please do not hesitate to contact us.

Yours truly,

MOTOR COACH INDUSTRIES INC.

R.L. Capstick, P. Eng.
Director of Engineering

RLC:cmf

Attached.

31 APR 2 AIO: 42
RECEIVED
NHTSA BOOKET

POSITION	INFORMATION REQUIRED	CHARACTER	INFORMATION ENCODED
1 - 3	Manufacturer Identifier	1M8	Motor Coach Industries Inc.
4	Model	9 D E F G H L M 2	MC-9 Intercity 96A3 Intercity 102A2 Intercity 102A3 Intercity 102C3 Intercity 102AW3 Intercity 96B3 Intercity 102B3 Intercity 40' 102" Transit
5	Series	C D	Crusader II/Classic MCI
6	Body Type	M T	Intercity Coach Transit Coach
7	Engine Type	6 7 9 J	Diesel, Detroit Diesel 6V-92TA, 551.9 CID 277 BHP Diesel, Detroit Diesel 6V-92TA, 551.9 CID 300 BHP Diesel, Detroit Diesel 8V-92TA, 736 CID, 400 BHP Diesel, Detroit Diesel 6V-92TA, 551.9 CID 277 BHP Transit

New
New

POSITION	INFORMATION REQUIRED	CHARACTER	INFORMATION ENCODED	
		K	Diesel, Detroit Diesel 8V-92 TA 475 HP	New
		L	Diesel, LTA10-300 300 HP	
		M	Diesel, Caterpillar 3176 325 HP	
8	Brake System	A Y	Air Brake Intercity Air Brakes Transit	
9	Check Digit	0-9 or X		
10	Current Model Year	L	1990	
11	Plant of Manufacture	P	Pembina, N.D.	
12-17	Production Sequence	-	-	