



BUS SALES, INC.

10 East Golf Road • Des Plaines, Illinois 60016-2291 • (708) 299-9900 • TWX 910-233-1645 • FAX (708) 299-0375

5052

01-22-N11B-6056

November 7, 1995

ORIGINAL

Ms. Peggy Proctor
National Highway Traffic Safety Administration
U.S. Dept. of Transportation
400 7th Street S.W.
Washington, DC 30590
NSA-01

96 MAY 10 49 21

RECEIVED
NHTSA DOCKET

2 pg

Re: VIN Errors: Docket No. 1-22-11-E

Dear Ms. Proctor:

This is to advise the Department of Transportation of a Vehicle Identification Number matter.

Hausman Bus Sales, Inc. ("Hausman") is the importer of Viaggio motor coaches manufactured by Dina Autobuses, S.A. de C.V. in Sahgun, Mexico. We have learned that 25 units imported and sold by Hausman bear an incorrect check digit in their Vehicle Identification Numbers on the certificate of origin, manufacturer's plate, chassis and invoice.

The errors are as follows:

VIN ON COACH AND DOCUMENTATION AS SOLD

- 3ABBBFGA4SS000905
- 3ABBBFGA6SS000906
- 3ABBBFGA8SS000907
- 3ABBBFGAXSS000908
- 3ABBBFGA1SS000909
- 3ABBBFGA8SS000910
- 3ABBBFGAXSS000911
- 3ABBBFGA1SS000912
- 3ABBBFGA3SS000913

VIN THAT SHOULD HAVE BEEN ON COACH AND DOCUMENTATION AS SOLD

- 3ABBBFGA7SS000905
- 3ABBBFGA9SS000906
- 3ABBBFGA0SS000907
- 3ABBBFGA2SS000908
- 3ABBBFGA4SS000909
- 3ABBBFGA0SS000910
- 3ABBBFGA2SS000911
- 3ABBBFGA4SS000912
- 3ABBBFGA6SS000913

001

Regional Offices

South Gate, CA Blackwood, NJ

VIN ON COACH AND
DOCUMENTATION AS SOLD


3ABBBFGA5SS000914
3ABBBFGA7SS000915
3ABBBFGA0SS000917
3ABBBFGA2SS000921
3ABBBFGA4SS000922
3ABBBFGA6SS000923
3ABBBFGAXSS000925
3ABBBFGA3SS000927
3ABBBFGA5SS000928
3ABBBFGA7SS000929
3ABBBFGA3SS000930
3ABBBFGA7SS000932
3ABBBFGA0SS000934
3ABBBFGA4SS000936
3ABBBFGAXSS000939
3ABBBFHA9SS000947

VIN THAT SHOULD HAVE
BEEN ON COACH AND
DOCUMENTATION AS SOLD

3ABBBFGA8SS000914
3ABBBFGAXSS000915
3ABBBFGA3SS000917
3ABBBFGA5SS000921
3ABBBFGA7SS000922
3ABBBFGA9SS000923
3ABBBFGA2SS000925
3ABBBFGA6SS000927
3ABBBFGA8SS000928
3ABBBFGAXSS000929
3ABBBFGA6SS000930
3ABBBFGAXSS000932
3ABBBFGA3SS000934
3ABBBFGA7SS000936
3ABBBFGA2SS000939
3ABBBFHA3SS000947

We understand that this letter will be filed in the National Highway Traffic Safety Administration Docket, Room 5111, Docket Number 1-22-11-E. We understand further that neither we, nor our customers, should change the original VIN numbers. We will advise our customers of the error and of this correcting submission.

If you have any questions, please feel free to call me at (602) 207-5801.

Sincerely,


Kristin S. Schloemer
Vice President-General Counsel