



ERR1001



James P. Vondale, Director
Automotive Safety Office
Environmental & Safety Engineering

Fairlane Plaza South
330 Town Center Drive
Dearborn, MI 48126-2738 USA

March 16, 2011

Mr. David Strickland
Administrator
National Highway Traffic Safety Administration
1200 New Jersey Avenue, SE/W42-308
Washington, DC 20590

Attention: VIN Coordinator

Subject: Vehicle Identification Number Code Deviations for certain 2011 Model Year Ford Expedition vehicles.

Reference: Ford Motor Company's September 30, 2010 letter regarding 2011 Model Year Vehicle Identification Number Codes

This is to notify the National Highway Safety Administration that Ford Motor Company (Ford) is deviating from the VIN code information submitted in our September 30, 2010 letter for three 2011 model year Ford Expedition vehicles.

The 1st and 2nd position of the vehicle identification number (VIN) for the affected 2011 model year Expedition vehicles (1FDJK1H52BEF28130, 1FDJK1H54BEF28131, and 1FDJK1H59BEF36614) differ from that stated in the 2011 VIN report submitted by Ford pursuant to Part 565.6 of title 49 of the Code of Federal Regulations (CFR). Specifically, the vehicles, which are "incomplete vehicle – limousine" vehicles, have a "1F" in the 1st and 2nd positions of the VIN rather than a "5L".

If there are any questions regarding this matter, please contact me.

Sincerely,

James P. Vondale

