



ORG5314

Oilfield Repair Specialists Ltd.
27 Wire Rd
Huntsville, Texas 77320

8-31-09

Administrator
National Highway Traffic Safety Administration
1200 New Jersey Avenue SE W43-488
Washington, DC 20590
Attention: Vin Coordinator

RE: Vin Decoding Information for Oilfield Repair Specialists Ltd.

In accordance with 49 CFR Part 565, Oilfield Repair Specialists Ltd. Hereby submits information necessary to decipher the characters contained in its Vehicle Identification Numbers.

VIN POSITION	DESCRIPTION	CODES
1, 2, &3	WMI	1-Z-9
4	Trailer Type	F=Flat D=Drop
5	Body Type	S=Single D=Double F=Flat
6&7	Length of Trailer (all lengths rounded to nearest foot)	16=16 Feet Long 53=53 Feet Long
9	Check Digit	See 49 CFR 565.4
10	Model Year	9=2009 A=2010 B=2011 C=2012
11	Plant Location	H=Huntsville
12, 13,&14	WMI	3-6-8
15, 16,&17	Sequential Production Number	001 002

Oilfield Repair Specialists Ltd
27 Wire Rd
Huntsville, Texas 77320
936-291-7795
936-291-7734 Fax

RE: 49 CFR Part 566

Partners: Roy Walton
Pam Walton
Irvin Harvey
Melvin Outlaw

Huntsville, Texas

Oilfield Repair Specialists builds trailers from products purchased at local supply companies. Some trailers are fitted with oilfield service equipment.

The gross vehicle weight ratings (GVWR) of our products range from 6000 to 50,000 lbs.

A handwritten signature in black ink, appearing to read "Roy Walton". The signature is fluid and cursive, with a long horizontal stroke at the end.

Roy Walton
Partner
8-31-09