

Lexus ES 350 All Weather Mat

CAD provided information

**1- Information on subject vehicles**

- 1) Number of vehicles manufactured for sale in the US and detailed information
  - b- Whether the vehicle was supplied with the subject component

**Response:** Total of 25,165 All weather mat sets sold  
PPO - 15,851  
DIO - 9,307

- See attached document

Note: Of the 4 reported vehicles experiencing this concern, 1 vehicle was equipped with an all weather mat as a PIO

Salba

Thermoflex Sales to TMS		
ES350 4PC AW MAT BLK	PT908-33070-02	9675
ES350 4PC AW MAT GRY	PT908-33070-11	7095
ES350 4PC AW MAT BRN	PT908-33070-14	12180
		Total
		<b>28950</b>

Parts Center and PDC Inventory on 5/3/07		
ES350 4PC AW MAT BLK	ES350 4PC AW MAT GRY	ES350 4PC AW MAT BRN
PT908-33070-02	PT908-33070-11	PT908-33070-14
787	733	2095
82	24	64
869	757	2159
		Total
		<b>3785</b>

<b>Total possible population of units either PPO or DIO</b>	<b>25165</b>
<b>Units placed in service PPO</b>	<b>15851</b>
<b>Warranty</b>	<b>7</b>
<b>Units placed in service DIO or other</b>	<b>9307</b>

mileage	vin	part_no	part_desc	Cond Cause Remedy
46171	JTHBA30G945 [REDACTED]	PT9083307002	ES350 4PC AW MAT BLK	BOTH FLOORMAT ANCHORS INOP   FLOORMAT ANCHOR O-RINGS WARPED   INSTALLED NEW FLOORMAT ANCHOR O-RINGS
5846	JTHBJ46G072 [REDACTED]	PT9083307002	ES350 4PC AW MAT BLK	RUBBER MAT POOR APPEARANCE, DEFORMED   WARPED, DOES NOT FIT WELL   REPLACE THE DRIVERS MAT
16412	JTHBJ46G172 [REDACTED]	PT9083307002	ES350 4PC AW MAT BLK	DR FLOOR MAT HAS SPLIT IN IT   FOUND SPLIT AND LOOSE FLOOR MAT SEAM   REPL FLOOR MATS
6485	JTHBJ46G672 [REDACTED]	PT9083307002	ES350 4PC AW MAT BLK	ORDERED FLOOR MATS---WEARING HOLE IN MAT ---SOP   POOR APPEARANCE--DISCOLORED   REPLACED A/W MATS WR
11000	JTHBA30G265 [REDACTED]	PT9083307002	ES350 4PC AW MAT BLK	CUSTOMER STATES FLOOR MAT HAS HOLE IN MATERIAL DUE   PREMATURE MATERIAL FAILURE   FLOOR MATS
1412	JTHBJ46G772 [REDACTED]	PT9083307011	ES350 4PC AW MAT GRY	RIGHT FRONT FLOOR MAT IS SPILTTING ON THE BOTTOM E   CRACKED, SPLITTING ON BOTTOM EDGE   TECH REPLACED FLOOR MATS AND VERIFIED THAT THEY AR
14	JTHBJ46G872 [REDACTED]	PT9083307014	ES350 4PC AW MAT BRN	LEXUS LOGO ON FLOOR MAT IS DEFORMED   LOGO DEFORMED   REPLACED FLOOR MAT