

From: Chris Santucci/=WDC/Toyota_NY.

Sent: 5/8/2007 8:38 AM.

To: [-] <Scott.Yon@dot.gov>.

Cc: [-] Bill.Collins@dot.gov; Jeff.Quandt@dot.gov.

Bcc: [-]

Subject: Re: PE07016 VOQs.

Message received, thanks!

Regards,

Chris Santucci - Assistant Manager
Technical and Regulatory Affairs
Toyota Motor North America, Inc.
Ofc (202) 463-6856 Cell (202) 651-1581 Fax (202) 463-8513
email: Chris_Santucci@tma.toyota.com

Note: We cannot receive attachment extensions listed below.
.exe, .com, .pif, .scr, .cmd, .bat, .vbs, .lnk, .htm, .html, .shs, or .zip

<Scott.Yon@dot.gov>
05/08/2007 11:21 AM
To <CSantucci@tma.toyota.com>
cc <Jeff.Quandt@dot.gov>, <Bill.Collins@dot.gov>
Subject PE07016 VOQs

Chris,

Can you confirm you have received this message and the 9 attachments please?

Per our discussion this morning here is the current status of VOQs for PE07-016.

Opened on: 10180658, 10182245, 10182749, 10183821, and 10186045. Copies of VOQs provided previously.

Now considering/reviewing: 10174071, 10174732/10176450 (two VOQs, same incident), 10186045, 10189487, 10189528, and 10189655

Note: 10189655 resulted in airbag deployment which we assume means there may be some EDR/CDR data stored. ODI may want to discuss this further with Toyota.

Also, ODI 10188471 is a duplicate for 10182749 (counted in open, same incident).

I have provided un-redacted copies of each of the 'new' reports (and any related documents) for your review.

There are a few 2007 Camry VOQs and a 2007 Avalon VOQ which may be related to all weather mats although these are currently out of scope.

Regards,
Scott

D. Scott Yon
U.S. Department of Transportation
National Highway Traffic Safety Administration

TOY-TQ001-00008287

Office of Defects Investigation
Room 5326-I
400 7th Street S.W.
Washington, DC
20590
202-366-0139
fax-202-366-1767

The information contained in this e-mail message has been sent from a federal agency of the United States Government. It may be privileged, confidential, and/or protected from disclosure. If you are not the intended recipient, any further disclosure or use, dissemination, distribution, or copying this message or any attachment is strictly prohibited. If you think that you have received this e-mail message in error, please delete it and notify the sender.

=====
[attachment "CL-10176450-1922.pdf" deleted by Chris Santucci/WDC/Toyota_NY] [attachment "10174071.pdf" deleted by Chris Santucci/WDC/Toyota_NY] [attachment "10174732.pdf" deleted by Chris Santucci/WDC/Toyota_NY] [attachment "10176450.pdf" deleted by Chris Santucci/WDC/Toyota_NY] [attachment "10186045.pdf" deleted by Chris Santucci/WDC/Toyota_NY] [attachment "10188471.pdf" deleted by Chris Santucci/WDC/Toyota_NY] [attachment "10189487.pdf" deleted by Chris Santucci/WDC/Toyota_NY] [attachment "10189528.pdf" deleted by Chris Santucci/WDC/Toyota_NY] [attachment "10189655.pdf" deleted by Chris Santucci/WDC/Toyota_NY]