

From: "Enzweiler, Julie" <Julie.Enzweiler@nielsen.com>.

Sent: 11/1/2007 2:37 PM.

To: [-] <greg_bryan@toyota.com>; <gordon_rush@toyota.com>.

Cc: [-] <Ray_Shinozaki@toyota.com>; <Randy_Wagner@toyota.com>; <Jeff_Northrup@toyota.com>; "Stephenson, Bill" <Bill.Stephenson@nielsen.com>; "Hamm, Scott" <Scott.Hamm@nielsen.com>; <craig_erickson@toyota.com>; <matt_allen@toyota.com>; <brian_lyons@toyota.com>; <Randy_Reida@toyota.com>; <Howard_Abrahams@toyota.com>; <Russell_Suzuki@toyota.com>; <Bill_Zlaket@toyota.com>; <Mike_Robinson@toyota.com>; <Gary_Heine@toyota.com>; <Bob_Nagai@toyota.com>; <Tom_Krembs@toyota.com>; "Colacurcio, Joe" <Joe.Colacurcio@nielsen.com>.

Bcc: [-] .

Subject: Nielsen: Toyota PQSS Executive Summary through 10-27-2007.

Hi Guys,

Attached you will find the Toyota Quality Executive Summary report reflecting data from October 14 – October 27, 2007. The reporting site (<http://toyota.reports.buzzmetrics.com/main.asp>) has also been updated with the latest information. This report contains several High Priority quality issues. Below you will find an Executive Summary of what is contained in this bi-weekly report.

Toyota

4Runner Current Generation

- TSBs on Sulfur Smells and Driveline Issues
- Dunlop OEM Tires Issues.
- Stereo Head Unit – Auxiliary Port Issues

4Runner Previous Generation

- Engine Threw a Rod

Camry Current Generation

- 4-cylinder Hesitation when Accelerating
- Steering Vibrations
- Issues with Cruise Control

Corolla Current Generation

- Erratic Cruise Control
- Starting Problems

MR2 Spyder Overall

- Oxygen Sensor

Prius Current Generation

- Brake Issues
- Intermittent Jerking
- Loss of Power

Prius Previous Generation

- High Pitched Whine

RAV4 Current Generation

- Starting Problems
- Erratic Cruise Control

Sienna Current Generation

- Transmission Failure

Poor Welding on Doors/Sliding Door Issues

Tacoma Current Generation

- Frame Rust

Tacoma Previous Generation

- Electrical Issues:

Tundra Current Generation

- Tailgate Issue
- Floor Mats and Stuck Accelerator

Lexus

Lexus ES 300 Previous Generation

- Issues with Starting/

Lexus ES 350 Current Generation

- Various Issues with 2008 ES 350
- Shaking/Vibrations while Driving

Lexus GS 300

- Steering Shakes

Lexus GS 400

- Transmission RPM Flares

Lexus LS 460

- Front Spring Noise Bulletin
- Wind Noise TSB
- Rattle and Transmission Bulletins

Lexus RX 300

Transmission Issues

Thanks,

Julie

Julie A. Enzweiler

Research Director

Nielsen Online

The Nielsen Company

50 West RiverCenter Blvd.

Third Floor

Covington, KY41011

859.905.4940 voice

859.653.3040 mobile

julie.enzweiler@nielsen.com

www.nielsen-online.com