

From: Gary Heine/=TMS/Toyota.

Sent:1/25/2008 1:29 PM.

To: [ - ] Tom Steger/=TMS/Toyota@Toyota; Clayton Meyer/=TMS/Toyota@Toyota; Cole Stutz/=TMS/Toyota@Toyota; Andrew Curtin/=TMS/Toyota@Toyota; Mike Robinson/=Mobile/Toyota@Toyota; Jaime Angulo/=TMS/Toyota@Toyota; Craig Parker/=TMS/Toyota@Toyota; John Stover/=TMS/Toyota@Toyota; Tim Davis/=TMS/Toyota; Nobu Takeda/=TMS/Toyota@Toyota; Scott Stewart/=TMS/Toyota.

Cc: [ - ] .

Bcc: [ - ] .

Subject: Fw: Toyota PQSS Executive Summary through January 19, 2008.

Regards,

Gary Heine

Quality Assurance Powertrain Manager

Toyota Customer Services Division

O- 310 468 2521

C- 310 977 0860

F- 310 381 7783

----- Forwarded by Gary Heine/TMS/Toyota on 01/25/2008 01:28 PM -----

"Hamm, Scott" <Scott.Hamm@nielsen.com>

01/25/2008 01:19 PM

To <Greg\_Bryan@toyota.com>, <Gordon\_Rush@toyota.com>

cc <Ray\_Shinozaki@toyota.com>, <Randy\_Wagner@toyota.com>, <Jeff\_Northrup@Toyota.com>, "Stephenson, Bill" <Bill.Stephenson@nielsen.com>, <craig\_erickson@toyota.com>, <matt\_allen@toyota.com>,

<brian\_lyons@toyota.com>, <Randy\_Reida@toyota.com>, <Howard\_Abrahams@toyota.com>,

<Russell\_Suzuki@toyota.com>, <Mike\_Robinson@toyota.com>, <Gary\_Heine@toyota.com>,

<Bob\_Nagai@toyota.com>, <Tom\_Krembs@toyota.com>, "Enzweiler, Julie" <Julie.Enzweiler@nielsen.com>,

"Colacurcio, Joe" <Joe.Colacurcio@nielsen.com>

Subject Toyota PQSS Executive Summary through January 19, 2008

Hello,

Attached please find the Toyota Quality Executive Summary report reflecting data from January 6, 2008 – January 19, 2008. The reporting site (<http://toyota.reports.buzzmetrics.com/main.asp>) has also been updated with the latest information. This report contains multiple High Priority quality issues. Below you will find an Executive Summary of what is contained in this bi-weekly report.

Toyota

4Runner Current Generation

- Driveline Clunk/Jerk
- Right-Rear Popping Noise and Chemical Smell
- Rattle/Clunk On Right Turns and Over Bumps
- Cannot switch to 4LO Mode
- Rusting Alloy Wheels

Camry Current Generation

- V6 Transmission Flares, Rough Shifting
- 4-Cylinder Transmission Hesitation
- Dashboard Rattles
- Abnormal RPM Behavior

Camry Hybrid

- Dashboard Rattles
- Strange Vibrations

Camry Solara Current Generation

- Engine Noise Upon Start Up
- Battery Drain

#### Corolla Current Generation

- Difficulty Starting
- Grinding Shift
- Noises at Highway Speeds

#### Highlander Current Generation

- Rattles and Droning

#### Land Cruiser Previous Generation

- NAV System Failure

#### Prius Current Generation

- Traction Control In Snow
- Multi-function Display Problems
- Battery Drain

#### RAV4 Current Generation

- Cruise Control Problems
- Steering Clunk

#### Sienna Current Generation

- Cruise Control Problems
- Sliding Door Problems
- Power Liftgate Struts
- Oil Sludge

#### Tacoma Current Generation

- Brake-Acceleration or Sudden Acceleration Issue
- ECU Ringing Noise
- Frame Rust
- Clutch Problems

#### Tundra Current Generation

- Paint Chipping
- Bed Bounce
- Rodent Burrowed Into Tundra
- Transmission Clunk
- Mirror Opens and Closes Independently
- Shudder During Acceleration

#### Yaris Current Generation

- Excessive Rattles
- Clutch Problems

#### Lexus

##### Lexus IS300

- Abnormal Shifting Pattern
- Noisy Engine

##### Lexus LS460

- Excessive Wind Noise
- Paint Chips
- Rear Bumper Fell Off

Scion  
Scion xB Current Generation  
· Engine "Popping" Sound  
Scion xD Current Generation  
Rear Tire Locks Up

Please feel free to contact us if you have any questions.

Thanks,

Scott Hamm  
Analyst  
Nielsen Online

The Nielsen Company  
50 West RiverCenter Blvd.  
Third Floor  
Covington, KY 41011  
859.905.4946 (phone)  
859.905.5030 (fax)  
scott.hamm@nielsen.com

[www.nielsen-online.com](http://www.nielsen-online.com)