

front differential drone/vibration between 20-40 mph (howling noise)

takeoff shudder /vibration(0-20 mph) commonly called 1-2 shift shudder by customers

rear differential vibration (most are between 20-40 mph)

we have been waiting since before launch for the TI for takeoff shudder related to driveline angles

Tom Steger
Sr. Product Engineer
Quality Assurance Powertrain
Product Quality & Service Support
Toyota Motor Sales USA Inc
Phone # 310-468-2529
Fax # 310-381-7427

Ryan Wills/TMS/Toyota
02/11/2008 09:56 AM
To Tom Steger/TMS/Toyota@Toyota
cc Shinji Kasuga/TEMA/Toyota@Toyota
Subject Fw: Toyota PQSS Executive Summary through February 2, 2008

Tom,

Are you, or is anyone in your group currently tracking any harmonic vibration issues on the current Tundra?

Harmonic Vibration (Document ID 1165363) The owner of a 2007 Tundra 4x4 DoubleCab 5.7L V8 reports a harmonic vibration sound/feeling while in four-wheel-drive and carrying a load or accelerating uphill.

Thanks,

Ryan Wills
Specialist
Customer Quality Engineering (CQE)
Toyota Motor Engineering And Manufacturing North America
Torrance, CA
Ph: (310) 468-3762
Cell: (310) 480-2897
Fax: (310) 468-3181

----- Forwarded by Ryan Wills/TMS/Toyota on 02/11/2008 09:51 AM -----

Shinji Kasuga/TEMA/Toyota
02/11/2008 08:30 AM
To Ryan Wills/TMS/Toyota@Toyota
cc
Subject Fw: Toyota PQSS Executive Summary through February 2, 2008

Good morning Ryan-san,

Do you know "Harmonic vibration" ?

· Anti-Lock Brake System Computer

4Runner Previous Generation

· Engine/Drivability Problems

· Starting Problem

Avalon Current Generation

· Interior Rattles

· Hesitation/Acceleration Problems

Camry Current Generation

· Excessive Vehicle Vibrations

· 4-cylinder Transmission Issues

· CD Player Becomes Inoperable

Camry Previous Generation

· Steering "Clunk"

Celica Most Recent Generation

· Transmission Problems

Corolla Current ('03-'08) Generation

· Error Code P0133

· Poor Fuel Economy

Highlander Current Generation

· Cold Start Engine Noise and Steering Pop

Prius Current Generation

· Battery Drainage

· No Start/Difficulty Starting

· Shifter Knob Stuck

Prius Previous Generation

· Difficulty Starting

RAV4 Current Generation

· Cruise Control Issue

· Steering Clunk

· Aftermarket NAV Interference

Sequoia Previous Generation

· Electrical Issues

Sienna Current Generation

· Sliding Door Issues

· Brakes Make Groaning Sound

Tacoma Current Generation

· Rear Suspension TSB

Tundra Current Generation

· Engine Noises/Drivetrain Problems

· Poor Paint Quality/Bumper Rust

· Bed Bounce

· Harmonic Vibration

Lexus

Lexus GS 430

· Inner Tire Wear

Lexus IS 250

· Dashboard Rattles

Lexus LS 460

· Excessive Wind Noise

Lexus RX 350

· Distorted Windshield

Scion

Scion xB Previous Generation

· Automatic Transmission Shifting Issue

Scion xD Current Generation

Rear Driver's Side Seatbelt in Wrong Place

Please feel free to contact us if you have any questions.

Thanks,

Joe Colacurcio
Automotive Industry Analyst
Nielsen Online

The Nielsen Company
50 West RiverCenter Blvd.
Third Floor
Covington, KY 41011

859.905.4936 voice
610.462.3048 mobile
joe.colacurcio@nielsen.com
www.nielsen-online.com