

From: Michiteru Kato/=HINPO/TMC0.

Sent: 6/16/2008 1:43 AM.

To: [-] George Morino/=TMS/Toyota@TOYOTA.

Cc: [-]

Bcc: [-]

Subject: NHTSA Consumer Complaints - All Weather Mat concern.

George,

Just FYI, but maybe TMS CAD will contact you, so.....

It seems this customer is saying that the dealer didn't secure a new designed AWFM by clips when they did a recall work. But strangely this customer said that the pedal seems to stick by the new mat which we don't believe can catch the pedal.

Mitch

----- 転送者: Michiteru Kato/HINPO/TMC0 転送日: 2008/06/16 17:37 -----

宛先: William de Manincor/TMS/Toyota@Toyota@TMCE

cc: Jim Wimmer/TMS/Toyota@Toyota@TMCE, Michael Collinsworth/TMS/Toyota@TOYOTA@TMCE, Makoto Hanada/TMS/Toyota@Toyota@TMCE, Kenzo_Nishiwaki@toyota.com, Shingo Sasaki/TMS/Toyota@Toyota@TMCE, Alok Vaish/TCS/Toyota@Toyota@TMCE, Yutaka Atsumi/E/TMC0@TMC0, Koji Hosoi/E/TMC0, Madoka Kawai/O/TMC0@TMC0, Kota Funato/E/TMC0@TMC0, Masaaki Murata/E/TMC0, Yuji Kimura/E/TMC0@TMC0, Masashi Wada/E/TMC0, Michiteru Kato/HINPO/TMC0@TMC0

件名: NHTSA Consumer Complaints - All Weather Mat concern

Hi, Bill-san,

We received a "NHTSA Consumer Complaint" as you can find the below attached file.

According to this "Complaints",
It seems that this customer knew the recall and he came to a dealer to exchange his all weather mat.
Besides, he said that clips were not installed.

Our questions about this reports are;
1. Was the all weather mat in this report after C/M?
2. Did this customer lay the all weather mat on a textile mat doubly?

We can't find details of VIN or dealer on this NHTSA report,
but please investigate and check this case.
Also, we'd like you to reply for the above questions.

If necessary, please give your consideration to a recurrence test.

Best Regards,

Frank <Fukunori> Ito Quality Group
TMC CADD Engineering Administration Dept
Tel 0561-74-4665 Ext. 8-41-4665
Fax 0561-74-4966 Ext. 8-41-4966
E-Mail ; Fukunori_ito@mail.toyota.co.jp

「秘」, 「転送禁止」 - [Secret], [Don't forward]