

Id	Vin	Buybacknumber	Conditionsall
CATKMAH-6URGKJ	4T1BK36BX5U [REDACTED]		Oil Leaks;Power Steering;Engine Noise
CATKMAH-6WAPJF	4T1BK36B15U [REDACTED]		Oil Leaks;Head Lights;Engine Noise;D/S window doesn't lower correctly.
CATKMAH-753ND6	4T1BK36B45U [REDACTED]		Oil Leaks;Engine Stalling
CATKMAH-7BCJZP	4T1BK36B55U [REDACTED]		Engine;Seat-Electrical;Navigational System;Oil Leaks
CATKMAH-7DTR7L	4T1BK36B55U [REDACTED]		Oil Leaks;Coolant Leak;Steering Column Shake/Shimmy;Axle;Check Engine Light On;Brake Vibration/Pulsation
CATLBEK-7GLL5T	4T1BK36B07U [REDACTED]	T0880178	Oil Leaks;Engine Noise
DVRDROE-74KTLF	4T1BK36B85U [REDACTED]		Spoiler;Paint - Mismatch;Bumper;Oil Leaks;Speakers;Timing Belt/Chain
LALCOL-7K8SXM	4T1BK36B46U [REDACTED]		Oil Leaks;Battery;Air Conditioner Not Cooling;Parts Back Order-Air Bag;Trunk;Seat-Front Seat
SETTKOH-6YWJHS	4T1BK36B45U [REDACTED]	T0750035	Power Steering Leak;Oil Leaks
SFEDON-77ZRET	4T1BK36B85U [REDACTED]	T0712056	Oil Leaks
SFMHOD-6Z766N	4T1BK36B25U [REDACTED]		Oil Leaks

Model	Modelyear	Modelcode	Fundingdate	Ncdscasenum
Avalon	2005	3554		8006181
Avalon	2005	3544		8006228
Avalon	2005	3554		8007126
Avalon	2005	3554		8008023
Avalon	2005	3538		8008077
Avalon	2007	3544	10/14/2008	
Avalon	2005	3544		1507068
Avalon	2006	3554		1108254
Avalon	2005	3538	3/13/2007	
Avalon	2005	3544	10/25/2007	
Avalon	2005	3534		1207038

Condition

Bank 1 VVT, oil line leaking.

P/S pump leaking fluid.

Seat button not clipped in door panel properly and became loose.

1)Certified diagnostic Technician analyzed vehicle electronic control systems using factory computerized diagnostic tool. Performed engine diagnostic test checked for codes P0446 in history. Scan check system with smoke machine-passed test. 2)Road tested

parts have been special ordered 2. performed factory 15,000

Instrument panel lid malfunction.

1)Leaks from oil line. 2) Loose cable.

Condition1D	Condition2D	Condition3D	Condition4D	Condition5D	Condition6D
Oil Leaks	Power Steering	Engine Noise			
Oil Leaks	Head Lights	Engine Noise	D/S window doesn't lower correctly.		
Oil Leaks	Engine Stalling				
Engine	Seat-Electrical	Navigational System	Oil Leaks		
Oil Leaks	Coolant Leak	Steering Column Shake/Shimmy	Axle	Check Engine Light On	Brake Vibration/Pulsation
Oil Leaks	Battery	Air Conditioner Not Cooling	Parts Back Order-Air Bag	Trunk	Seat-Front Seat
Power Steering Leak	Oil Leaks				
Oil Leaks					

Condition 1

Oil leak.

Oil cooler line is leaking.

VVT oil pipe leaking.

Road tested car, duplicate concern, found pedal getting stuck under floor mat.

Diagnosed, found l/front outer cv joint binding/sticking.

cargo hook falls off

Instrument panel lid malfunction.

1) Oil leak coming from timing chain cover. 2) Missing bolt. Power steering pump leaking.

Condition 10 Condition 11 Condition 12 Condition 13 Condition 14

Condition 2

Serp belt broke, causing damage to p/s pump, pulleys, crank shaft.

Order new control assembly.

1)No info on repair order. 2)Front rotors warped. Right front runout .012. Left front runout .014.

could not duplicate concern at this time, seat performing as designed 2. performed factory scheduled 5,000 maintainance

Unable to duplicate concern.

Hub bearing (SOP)

Condition 3

Sticking VVT valve.

Shredded drive belt. Ck pulleys and tensioner-OK. Lots of oil residue.

Improper install from factory.

1)Steering shaft knocks, loss of tension of the bearing. 2)Align out of specs. 3)Poor machining of cv joint inside right front axle.

remove engine crank, main bearings, rod bearings, cams, front of engine timing cover found main bearings scored metal shavings 2. found battery leaking acid 3. AC stop blowing cold air & ac button light flashing

Verified leak.

Condition 4

No codes present, check data normal. Could not duplicated.

1)Working properly. 2)No info on repair order.

VVTI oil feed line leaking.

1)Technician test drove vehicle found no vibration while driving. 2)No noise heard while braking. Pads and shims all in place. 3)Vehicle will drift until the parking pole engages. This is normal operation.

Power steering hose and clamp need to be replaced.

Condition 5

VVTI oil line deformed.

SOP. Part on back order. (till January)

Power steering hose is leaking fluid.

Condition 6

1)Abnormal wear on switch. 2)Verified cond with Toyota Field Technical Specialist, found bolt loose. 3)Window regulator has play which may be normal.

1)Found rubber line for VVTI oil line has pin hole causing leak. 2)Hinge for navigation unit cracked/weak plastic.

Leak at bank one cylinder & engine block.

Oil cover on right bank is leaking.

Condition 7

1)Lack of FIPG on front cover. 2)Deformed navigation door and keypad.

Coolant leaking from gasket of water pump onto pulley.

VVTI oil line leaking.

Condition 8

Porous seal in front pump of water pump.

Condition 9

Porous rear engine seal.

Conditions

Oil Leaks;Power Steering;Engine Noise

Oil Leaks;Head Lights;Engine Noise;D/S window doesn't lower correctly.

Oil Leaks,Engine Stalling

Engine,Seat-Electrical,Navigational System,Oil Leaks

Oil Leaks,Coolant Leak,Steering Column Shake/Shimmy,Axle,Check Engine Light On,Brake Vibration/Pulsation

Oil Leaks,Battery,Air Conditioner Not Cooling,Parts Back Order-Air Bag,Trunk,Seat-Front Seat

Power Steering Leak;Oil Leaks

Oil Leaks

Action 9

Remove engine & replace rear main engine oil seal, water pump gasket.

Action 8

Replace water pump and fill cooling system and replace belt-saturated in coolant.

Action 7

Done.

1)Reseal timing cover as per TSB EG019-07. Serpentine belt replaced due to oil contamination. 2)Replaced navigation door and keypad.

Ordered water pump gasket.

Performed TSB # EG064-05.

Action 6

1)R&R headlight switch-See details from FTS notes. 2)Tighten bolt in left eng mount. 3)Part on order. See details from FTS notes.

1)Replaced VVTI oil line. 2)Replaced navigation control holder.

Remove front cover & reseal pan oil pipe.

Remove oil cover, clean and reseal.

Action 5

Waiting for Field Rep to come in, have replaced twice.

Replaced VVTI oil line.

Part on order.

Replaced low pressure hose.

Action 4

No repairs performed.

1)No repairs performed. 2)Lube and adjust regulator track.

Replaced oil line and clean. Recheck.

1)No repairs performed. 2)No repairs performed. 3)No repairs performed.

Parts are on order.

Action 3

Called Tech Assistance. Replaced VVT valves per Tech Assistance.

R&R combo switch assembly. (Parts warranty)

Cleaned and added dye to oil. Replaced drivebelt. Road tested for 10 minutes and rechecked to see if there was an oil leak. None present at this time. Loaner vehicle provided.

Replace door assembly.

1) Replaced steering shaft. 2) Adjust alignment to within spec. 3) Replaced right front axle shaft.

replace engine main bearings, cams, VVTI cam gears timing chain cover assy, seals, gaskets, replace engine drive belt soak w/oil assisted customer rental 2. replace battery assy, battery hold down 3. see line 53

FTS inspected at dealership with Sho

Replaced hose and clamp.

Action 2

Replace p/s pump, crank seal, frt idler pulley and tensioner and serp belt. Also replaced l/f wheel.

R&R headlight switch assembly.

Changed oil and filter w/cleaning engine from previous repair.

Part on order.

1)Part ordered. 2)Resurface both front brake rotors.

could not duplicate concern at this time, seat performing as designed 2. performed factory scheduled 5,000 maintainance - vehicle recommendations: tire pressure before was at 30 psi now at 32 psi

No repairs performed.

Installed new hub and bearing. After finish, reinspected, still found some play at wheel. Need to replace new axle shaft and nut; replaced

Action 14 Action 13 Action 12 Action 11 Action 10

Action 1

Replaced VVT oil line per TSB EG064-05

R&R oil line that goes from valve cover to side of engine.

Replace oil pipe per TSB EG064-05.

Remove rubber floor mat.

Replaced l/side axle assembly.

installed new cargo hook

1) Replaced instrument panel

1) Removed timing chain cover for reseal per TSB; no more leak at this time. 2) Found power steering pump leak; replaced.

Action

Ordered parts per TSB EG064-05.

R&R vane pump.

Special ordered part.

R&R door panel to reinstall seat memory switch.

1)Cleared code retest vehicle operation OK at this time. 2)Re-balanced both front tires. Set air pressure in tires. Re-road tested vehicle-OK at this time. 3)Ordered l/front axle shaft assembly. Appt for 8/16/06.

parts have been special ordered 2. performed factory 15,000

Part is on order.

1) Replaced new oil line. VVTI per TSB. 2) Checked charging system; good. Checked battery, good. Inspected battery, found negative cable loose.