

From: Craig Parker/=TMS/Toyota.

Sent:5/14/2009 7:48 AM.

To: [-] Cole Stutz/=TMS/Toyota@Toyota.

Cc: [-]

Bcc: [-]

Subject: Fw: LEXUS OF NEW ORLEANS, JTHBK262962012716: 2006 IS250, DTC: None. TA Case # TA091330254.

This looks like the same concern as ES350. A/C compressor.

Craig Parker  
Product Engineer - QA Powertrain  
Product Quality & Service Support  
Toyota Motor Sales U.S.A., Inc.  
Office: (310) 468-3781

----- Forwarded by Craig Parker/TMS/Toyota on 05/14/2009 07:47 AM -----

Craig Parker <craig\_parker@toyota.com>  
05/14/2009 06:38 AM  
Please respond to

To craig\_parker@toyota.com

cc

Subject LEXUS OF NEW ORLEANS, JTHBK262962 [REDACTED] 2006 IS250, DTC: None. TA Case # TA091330254.

TAS Case TA091330254 has been forwarded to you for information and reference purposes. For further details please log into the T3 system.

JTHBK262962 [REDACTED]: 2006 IS250  
61702: LEXUS OF NEW ORLEANS  
DTC: None  
Symptom Descriptions: Engine/Hybrid System, Engine Control, Driveability, Surge

[http://t3.tms.toyota.com/t3Portal/portlets/tas/caseEditor/viewonly/TasCaseViewOnlyController.portlet?tasCaseNumber=TA091330254&\\_portlet.skin=t3&\\_portlet.skinPath=/framework/skins/&\\_portlet.theme=wht3d&\\_portlet.title=TA091330254&viewcase=true](http://t3.tms.toyota.com/t3Portal/portlets/tas/caseEditor/viewonly/TasCaseViewOnlyController.portlet?tasCaseNumber=TA091330254&_portlet.skin=t3&_portlet.skinPath=/framework/skins/&_portlet.theme=wht3d&_portlet.title=TA091330254&viewcase=true)