



REVISION HISTORY				
ZONE	REV	DESCRIPTION	DATE	BY
G11	A	ADDED BALLOONS FOR ITEMS 13, 14 & 15	12/5/2013	DW
C8	B	DRWAING NUMBER WAS 2921-004; ADDED ITEM #2 PART #2921-340 - TOP TETHER ANCHOR, ITEM #17, ITEM #18 & SECTION A-A	12/12/2013	DW

B	18	1	9000695V	BOLT, HEX HD. 1/4-20 x 2"
	17	1	9000105	NUT, HEX 1/4-20
	16	10	9000490	SCREW, SHCS 3/8-16 x 3/4
	15	11	9009270V	WASHER, FLAT 3/8"
	14	12	9000110	HEX NUT 1/4-28
	13	4	9000174	WASHER, FLAT 1/2"
	12	27	9000244	WASHER, FLAT 1/4"
	11	4	9000274	NUT, HEX 1/2-13
	10	4	9000010V	SCREW, SHCS 1/2-13 x 1 1/2"
	9	14	9001318V	SCREW, BHCS 1/4-20 x 3/8"
	8	1	2921-395	BEARING MOUNT PLATE ASS'Y.
	7	1	2921-390	SEAT BACK CUSHION ASS'Y.
	6	1	2921-380	BENCH SEAT BACK PANEL
	5	1	2921-370	BOTTOM SEAT CUSHION ASS'Y.
	4	1	2921-360	BENCH SEAT PANEL
	3	1	2921-350	LOWER ANCHOR ASSEMBLY
B	2	1	2921-340	TOP TETHER ANCHOR
	1	1	2921-310	BENCH FRAME ASSEMBLY

ITEM	QTY	PART NUMBER	DESCRIPTION
VEHICLE RESEARCH and TEST CENTER			
NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION			
BENCH ASSEMBLY			
CHILD SIDE IMPACT SLED			
2921-300 B			