

Recall Detail

Recall Num: 10 V 025 000 573 Date: 22-JAN-2010 573 Date Rcvd: 28-JAN-2010 Potentially Affected: 210 Potentially Defective: 210

Mfr Recall Num:

Subject: BONDING OF THE WINDSHIELD Remedy Type: Inspect and Replace RP Num: FMVSS Num:
 Recall Type: Defect Recall Effect: Crash Avoidance NHTSA Inv Num: Influenced by: MFR
 Problem Exp: Complaints Manufacturer: BMW OF NORTH AMERICA, LLC Recall Status: CONDUCTING RECALL

Problem Descr: BMW IS RECALLING CERTAIN MODEL YEAR 2010 X5 AND X6 SPORT ACTIVITY VEHICLES MANUFACTURED BETWEEN DECEMBER 14, 2009 AND DECEMBER 16, 2009. IN THE UPPER RIGHT AREA OF THE WINDSHIELD, BONDING MAY BE INSUFFICIENT OVER A LENGTH OF APPROXIMATELY 50CM.

Consequence: IN THE CASE OF A ROLLOVER, THE STABILITY OF THE ROOF COULD BE AFFECTED INCREASING THE RISK OF INJURIES.

Remedy Type: BMW WILL NOTIFY OWNERS AND AUTHORIZED DEALERS WILL REMOVE THE WINDSHIELD AND THEN REINSTALL WITH THE PROPER BONDING FREE OF CHARGE. THE SAFETY RECALL BEGAN ON MARCH 30, 2010. OWNERS MAY CONTACT BMW AT 1-800-525-7417.

Notes: OWNERS MAY ALSO CONTACT THE NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION'S VEHICLE SAFETY HOTLINE AT 1-888-327-4236 (TTY 1-800-424-9153), OR GO TO HTTP://WWW.SAFERCAR.GOV .

MFR Knowl Dt: Prod Change Dt: Mfr Press Release Dt: NHTSA Press Release Dt:
 Stop Sales: Regional:
 Supplier: Mfr Toll Free Num: 800-525-7417

Products	Vehicle Usage	Beginning Mfg Date	Ending Mfg Date
Product Type :VEHICLE Product Category :LIGHT VEHICLES Manufacturer :BMW OF NORTH AMERICA, LLC Make :BMW Model :X5 Model Year :2010 Type :PASSENGER CAR	Passenger	14-DEC-2009	16-DEC-2009
Product Type :VEHICLE Product Category :LIGHT VEHICLES Manufacturer :BMW OF NORTH AMERICA, LLC Make :BMW Model :X6 Model Year :2010 Type :PASSENGER CAR	Passenger	14-DEC-2009	16-DEC-2009

Component Name
 VISIBILITY:WINDSHIELD

Influencing Investigation(s)

Investigation Num	Subject	Investigator	Relationship
-------------------	---------	--------------	--------------

Related Recalls

Yr	Type	Major Sub	Relationship
----	------	-----------	--------------

Recall Characteristics

Unique Recall	Unique Descr
---------------	--------------

Recall Communications

Fax Ack: 10-MAR-2010	Letter Ack: 03-FEB-2010
Draft 577 Received: 10-MAR-2010	Draft 577 Approved: 11-MAR-2010
Final 577 Received: 01-APR-2010	Owner Notification: 30-MAR-2010
Phased: N	577 End:
Renotification:	Envelope Approved:
Dealer Notification Received: 01-APR-2010	Dealer Notification:

Recall Detail

Recall Num: 10 V 047 000 573 Date: 29-JAN-2010 573 Date Rcvd: 18-FEB-2010 Potentially Affected: 1,040 Potentially Defective: 1,040

Mfr Recall Num:

Subject: TIRE PRESSURE LABEL Remedy Type: Mail Labels RP Num: 571 FMVSS Num: 110
 Recall Type: Compliance Recall Effect: Crash Avoidance NHTSA Inv Num: Influenced by: MFR
 Problem Exp: Complaints Manufacturer: BMW OF NORTH AMERICA, LLC Recall Status: CONDUCTING RECALL

Problem Descr: BMW IS RECALLING CERTAIN MODEL YEAR 2009-2010 7-SERIES AND MODEL YEAR 2010 550i GRAND TURISMO VEHICLES FOR FAILING TO COMPLY WITH THE REQUIREMENTS OF FEDERAL MOTOR VEHICLE SAFETY STANDARD NO. 110 "TIRE SELECTION AND RIMS." THESE VEHICLE'S ARE EQUIPPED WITH A TIRE PRESSURE LABEL INDICATING THAT THE VEHICLE'S SEATING CAPACITY IS FIVE (5) PASSENGERS. THE ACTUAL SEATING CAPACITY IS FOUR (4) PASSENGERS. THE TIRE SIZE, TIRE PRESSURE, AND VEHICLE CAPACITY WEIGHT ON THE LABEL ARE CORRECT.

Consequence: THE TIRE LABEL DOES NOT CONFORM TO FMVSS 110.

Remedy Type: BMW WILL NOTIFY OWNERS AND AUTHORIZED BMW DEALERS WILL REPLACE THE TIRE LABEL FREE OF CHARGE. THE SAFETY RECALL BEGAN ON APRIL 16, 2010. OWNERS MAY CONTACT BMW AT 1-800-831-1117.

Notes: OWNERS MAY ALSO CONTACT THE NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION'S VEHICLE SAFETY HOTLINE AT 1-888-327-4236 (TTY 1-800-424-9153), OR GO TO HTTP://WWW.SAFERCAR.GOV .

MFR Knowl Dt: Prod Change Dt: Mfr Press Release Dt: NHTSA Press Release Dt:
 Stop Sales: Regional:
 Supplier: Mfr Toll Free Num: 800-831-1117

Products	Vehicle Usage	Beginning Mfg Date	Ending Mfg Date
----------	---------------	--------------------	-----------------

Product Type :VEHICLE Product Category :LIGHT VEHICLES Manufacturer :BMW OF NORTH AMERICA, LLC Make :BMW Model :7-SERIES Model Year :2010 Type :PASSENGER CAR	Passenger	10-NOV-2008	26-NOV-2009
Product Type :VEHICLE Product Category :LIGHT VEHICLES Manufacturer :BMW OF NORTH AMERICA, LLC Make :BMW Model :7-SERIES Model Year :2009 Type :PASSENGER CAR	Passenger	10-NOV-2008	26-NOV-2009
Product Type :VEHICLE Product Category :LIGHT VEHICLES Manufacturer :BMW OF NORTH AMERICA, LLC Make :BMW Model :550I GRAN TURISMO Model Year :2010 Type :PASSENGER CAR	Passenger	24-JUL-2009	26-NOV-2009

Component Name

EQUIPMENT:OTHER:LABELS

Influencing Investigation(s)

Investigation Num	Subject	Investigator	Relationship
-------------------	---------	--------------	--------------

Related Recalls

Yr	Type	Major Sub	Relationship
----	------	-----------	--------------

Recall Characteristics

Unique Recall

Unique Descr

Recall Communications

Fax Ack: 26-FEB-2010

Letter Ack: 19-FEB-2010

Draft 577 Received: 26-FEB-2010

Draft 577 Approved:

Final 577 Received: 19-APR-2010

Owner Notification: 16-APR-2010

Phased: N

577 End:

Renotification:

Envelope Approved:

Dealer Notification

Received: 19-APR-2010

Dealer Notification:

Recall Detail

Recall Num: 10 V 152 000 573 Date: 08-APR-2010 573 Date Rcvd: 15-APR-2010 Potentially Affected: 735 Potentially Defective: 735

Mfr Recall Num:

Subject: SIDE MARKER LAMPS

Remedy Type: Inspect and Replace

RP Num: 571

FMVSS Num: 108

Recall Type: Compliance

Recall Effect: Crash Avoidance

NHTSA Inv Num:

Influenced by: MFR

Problem Exp: Complaints

Manufacturer: BMW OF NORTH AMERICA, LLC

Recall Status: CONDUCTING RECALL

Problem Descr: BMW IS RECALLING CERTAIN MODEL YEAR 2010 X5 M SAV VEHICLES FOR FAILING TO COMPLY WITH THE REQUIREMENTS OF FEDERAL MOTOR VEHICLE SAFETY STANDARD NO. 108, "LAMPS, REFLECTIVE DEVICES, AND ASSOCIATED EQUIPMENT," THESE VEHICLE'S WERE EQUIPPED WITH SIDE MARKER LAMPS, BUT NOT THE POWER SUPPLY CABLES LEADING TO THE LAMPS. AS A RESULT, THE SIDE MARKER LAMPS DO NOT ILLUMINATE.

Consequence: THESE VEHICLES DO NOT COMPLY WITH REQUIREMENTS OF FMVSS NO. 108.

Remedy Type: BMW WILL INSTALL POWER SUPPLY CABLES FOR THE FRONT SIDE MARKER LAMPS. THIS SERVICE WILL BE PERFORMED FREE OF CHARGE. THE SAFETY RECALL IS EXPECTED TO BEGIN DURING MAY 2010. OWNERS MAY CONTACT BMW AT 800-525-7417.

Notes: OWNERS MAY ALSO CONTACT THE NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION'S VEHICLE SAFETY HOTLINE AT 1-888-327-4236 (TTY 1-800-424-9153), OR GO TO HTTP://WWW.SAFERCAR.GOV .

MFR Knowl Dt:

Prod Change Dt:

Mfr Press Release Dt:

NHTSA Press Release Dt:

Stop Sales:

Regional:

Supplier:

Mfr Toll Free Num:

Products	Vehicle Usage	Beginning Mfg Date	Ending Mfg Date
----------	---------------	--------------------	-----------------

Product Type :VEHICLE Product Category :LIGHT VEHICLES Manufacturer :BMW OF NORTH AMERICA, LLC Make :BMW Model :X5 Model Year :2010 Type :MULTIPURPOSE PASSENGER VEHICLE

Passenger

01-JUL-2009

25-JAN-2010

Component Name

EXTERIOR LIGHTING

Influencing Investigation(s)

Investigation Num	Subject	Investigator	Relationship
-------------------	---------	--------------	--------------

Related Recalls

Yr	Type	Major Sub	Relationship
----	------	-----------	--------------

Recall Characteristics

Unique Recall	Unique Descr
---------------	--------------

Recall Communications

Fax Ack: 12-MAY-2010	Letter Ack: 20-APR-2010
Draft 577 Received: 12-MAY-2010	Draft 577 Approved: 12-MAY-2010
Final 577 Received: 04-JUN-2010	Owner Notification: 31-MAY-2010
Phased: N	577 End:
Renotification:	Envelope Approved:
Dealer Notification Received: 04-JUN-2010	Dealer Notification:

Recall Detail

10-FEB-2012

Recall Num: 10 V 233 000 573 Date: 28-MAY-2010 573 Date Rcvd: 02-JUN-2010 Potentially Affected: 296 Potentially Defective: 296

Mfr Recall Num:

Subject: INCORRECT TIRE PRESSURE LABEL Remedy Type: Mail Labels RP Num: 571 FMVSS Num: 110
 Recall Type: Compliance Recall Effect: Crash Avoidance NHTSA Inv Num: Influenced by: MFR
 Problem Exp: Other Manufacturer: BMW OF NORTH AMERICA, LLC Recall Status: CONDUCTING RECALL

Problem Descr: BMW IS RECALLING CERTAIN MODEL YEAR 2011 X5 SAV AND X6 SAV PASSENGER VEHICLES MANUFACTURED FROM APRIL 1 THROUGH MAY 8, 2010. THE TIRE LABEL DOES NOT CONFORM TO THE REQUIREMENTS OF FEDERAL MOTOR VEHICLE SAFETY STANDARD NO. 110, "TIRE SELECTION AND RIMS." THE VEHICLES ARE EQUIPPED WITH 20-INCH WHEELS, BUT THE LABEL STATES THAT THE VEHICLES WERE EQUIPPED WITH 19-INCH WHEELS AND THE STATED TIRE PRESSURE IS INCORRECT FOR THE EQUIPPED WHEELS.

Consequence: IMPROPER TIRE INFLATION CAN RESULT IN PREMATURE TIRE FAILURE OR REDUCED VEHICLE HANDLING PERFORMANCE, EITHER OF WHICH CAN INCREASE THE RISK OF A CRASH.

Remedy Type: BMW WILL NOTIFY OWNERS AND PROVIDE CORRECT LABELS FREE OF CHARGE. THE OWNER WILL HAVE THE OPTION TO AFFIX THE LABEL THEMSELVES OR THEY MAY TAKE THEIR VEHICLE TO A BMW DEALER WHO WILL AFFIX THE LABEL FOR THEM AT NO COST. THE SAFETY RECALL BEGAN ON OCTOBER 8, 2010. OWNERS MAY CONTACT BMW AT 1-800-525-7417.

Notes: OWNERS MAY ALSO CONTACT THE NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION'S VEHICLE SAFETY HOTLINE AT 1-888-327-4236 (TTY 1-800-424-9153), OR GO TO HTTP://WWW.SAFERCAR.GOV .

MFR Knowl Dt: Prod Change Dt: Mfr Press Release Dt: NHTSA Press Release Dt:
 Stop Sales: Regional:
 Supplier: Mfr Toll Free Num: 1-800-525-7417

Products	Vehicle Usage	Beginning Mfg Date	Ending Mfg Date
Product Type :VEHICLE Product Category :LIGHT VEHICLES Manufacturer :BMW OF NORTH AMERICA, LLC Make :BMW Model :X6 Model Year :2011 Type :PASSENGER CAR	Passenger	01-APR-2010	08-MAY-2010
Product Type :VEHICLE Product Category :LIGHT VEHICLES Manufacturer :BMW OF NORTH AMERICA, LLC Make :BMW Model :X5 Model Year :2011 Type :PASSENGER CAR	Passenger	01-APR-2010	08-MAY-2010

Component Name

EQUIPMENT:OTHER:LABELS

Influencing Investigation(s)

Investigation Num	Subject	Investigator	Relationship

Related Recalls

Yr	Type	Major Sub	Relationship

Recall Characteristics

Unique Recall	Unique Descr

Recall Communications

Fax Ack: 15-JUL-2010	Letter Ack: 03-JUN-2010
Draft 577 Received: 15-JUL-2010	Draft 577 Approved: 15-JUL-2010
Final 577 Received: 08-OCT-2010	Owner Notification: 08-OCT-2010
Phased: N	577 End:
Renotification:	Envelope Approved:
Dealer Notification Received:	Dealer Notification:

Recall Detail

Recall Num: 10 V 254 000 573 Date: 08-JUN-2010 573 Date Rcvd: 10-JUN-2010 Potentially Affected: 31,935 Potentially Defective: 31,935

Mfr Recall Num:

Subject: SOUND INSULATION BELT RETRACTOR UNIT Remedy Type: Inspect and Replace RP Num: FMVSS Num:
 Recall Type: Defect Recall Effect: Crash Avoidance NHTSA Inv Num: Influenced by: MFR
 Problem Exp: Complaints Manufacturer: BMW OF NORTH AMERICA, LLC Recall Status: CONDUCTING RECALL

Problem Descr: BMW IS RECALLING CERTAIN MODEL YEAR 2008-2011 1-SERIES VEHICLES. IN A CRASH OF SUFFICIENT SEVERITY, DEPLOYMENT OF THE FRONT PRE-TENSIONER AND LOAD-LIMITER OCCURS.

Consequence: THE INSULATION AROUND THE PRE-TENSIONER COULD IGNITE.

Remedy Type: VEHICLES PRODUCED UP THROUGH DECEMBER 2009 WILL RECEIVE NEW FRONT SAFETY BELT RETRACTOR UNITS AND A MODIFICATION TO THE SOUND INSULATION NEAR THE UNITS, WHILE VEHICLES PRODUCED BETWEEN JANUARY 2010 AND MAY 2010 WILL RECEIVE A MODIFICATION TO THE SOUND INSULATION NEAR THE UNITS. THIS SERVICE WILL BE PERFORMED FREE OF CHARGE. THE SAFETY RECALL BEGAN ON AUGUST 23, 2010. OWNERS MAY CONTACT BMW AT 1-800-525-7417.

Notes: OWNERS MAY ALSO CONTACT THE NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION'S VEHICLE SAFETY HOTLINE AT 1-888-327-4236 (TTY 1-800-424-9153), OR GO TO HTTP://WWW.SAFERCAR.GOV .

MFR Knowl Dt: Prod Change Dt: Mfr Press Release Dt: NHTSA Press Release Dt:
 Stop Sales: Y Regional:
 Supplier: MR. SCOTT GILKEY Mfr Toll Free Num:

Products	Vehicle Usage	Beginning Mfg Date	Ending Mfg Date
Product Type :VEHICLE Product Category :LIGHT VEHICLES Manufacturer :BMW OF NORTH AMERICA, LLC Make :BMW Model :1 SERIES Model Year :2010 Type :PASSENGER CAR	Passenger	01-DEC-2007	27-MAY-2010
Product Type :VEHICLE Product Category :LIGHT VEHICLES Manufacturer :BMW OF NORTH AMERICA, LLC Make :BMW Model :1 SERIES Model Year :2008 Type :PASSENGER CAR	Passenger	01-DEC-2007	27-MAY-2010
Product Type :VEHICLE Product Category :LIGHT VEHICLES Manufacturer :BMW OF NORTH AMERICA, LLC Make :BMW Model :1 SERIES Model Year :2011 Type :PASSENGER CAR	Passenger	01-DEC-2007	27-MAY-2010
Product Type :VEHICLE Product Category :LIGHT VEHICLES Manufacturer :BMW OF NORTH AMERICA, LLC Make :BMW Model :1 SERIES Model Year :2009 Type :PASSENGER CAR	Passenger	01-DEC-2007	27-MAY-2010

Component Name

SEAT BELTS:FRONT:RETRACTOR

Influencing Investigation(s)

Investigation Num	Subject	Investigator	Relationship
-------------------	---------	--------------	--------------

Related Recalls

Yr	Type	Major Sub	Relationship
----	------	-----------	--------------

Recall Characteristics

Unique Recall	Unique Descr
Stopped Sales	

Recall Communications

Fax Ack: 04-AUG-2010	Letter Ack:
Draft 577 Received: 04-AUG-2010	Draft 577 Approved: 04-AUG-2010
Final 577 Received: 03-SEP-2010	Owner Notification: 23-AUG-2010
Phased: N	577 End:
Renotification:	Envelope Approved:
Dealer Notification Received:	Dealer Notification:

Recall Detail

Recall Num: 10 V 273 000 573 Date: 15-JUN-2010 573 Date Rcvd: 16-JUN-2010 Potentially Affected: 1,807 Potentially Defective: 1,807

Mfr Recall Num:

Subject: ROLL GEAR PIN MOUNTING ATTACHMENT Remedy Type: Fix/Repair RP Num: FMVSS Num:
 Recall Type: Defect Recall Effect: Crash Avoidance NHTSA Inv Num: Influenced by: MFR
 Problem Exp: Complaints Manufacturer: BMW OF NORTH AMERICA, LLC Recall Status: CONDUCTING RECALL

Problem Descr: BMW IS RECALLING CERTAIN MODEL YEAR 2007 AND 2008 G 650 X COUNTRY, G 650 X CHALLENGE, AND G650 X MOTO MOTORCYCLES MANUFACTURED FROM NOVEMBER 29, 2006 THROUGH MAY 19, 2008. OVER TIME, THE ROLL GEAR PIN'S MOUNTING ATTACHMENT COULD BREAK.

Consequence: IF THIS OCCURS, IT WOULD BE POSSIBLE FOR FRAGMENTS OF THE ATTACHMENT TO BECOME TRAPPED BETWEEN THE DRIVE CHAIN AND THE REAR SPROCKET. THE REAR WHEEL COULD LOCK UP, POSSIBLY RESULTING IN A CRASH.

Remedy Type: DEALERS WILL REPLACE THE ROLL GEAR PIN'S MOUNTING ATTACHMENTS FREE OF CHARGE. THE SAFETY RECALL BEGAN ON AUGUST 30, 2010. OWNERS MAY CONTACT BMW AT 1-800-525-7417.

Notes: OWNERS MAY ALSO CONTACT THE NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION'S VEHICLE SAFETY HOTLINE AT 1-888-327-4236 (TTY 1-800-424-9153), OR GO TO HTTP://WWW.SAFERCAR.GOV .

MFR Knowl Dt: Prod Change Dt: Mfr Press Release Dt: NHTSA Press Release Dt:

Stop Sales: Regional:

Supplier: Mfr Toll Free Num: 800-525-7417

Products	Vehicle Usage	Beginning Mfg Date	Ending Mfg Date
Product Type :VEHICLE Product Category :MOTORCYCLES Manufacturer :BMW OF NORTH AMERICA, LLC Make :BMW Model :G 650 X US MOTO Model Year :2007	Passenger	22-DEC-2006	28-MAY-2007
Product Type :VEHICLE Product Category :MOTORCYCLES Manufacturer :BMW OF NORTH AMERICA, LLC Make :BMW Model :G 650 X US COUNTRY Model Year :2008	Passenger	22-DEC-2006	19-MAY-2008
Product Type :VEHICLE Product Category :MOTORCYCLES Manufacturer :BMW OF NORTH AMERICA, LLC Make :BMW Model :G 650 X US CHALLENGE Model Year :2007	Passenger	29-NOV-2006	31-MAY-2007
Product Type :VEHICLE Product Category :MOTORCYCLES Manufacturer :BMW OF NORTH AMERICA, LLC Make :BMW Model :G 650 X US COUNTRY Model Year :2007	Passenger	22-DEC-2006	19-MAY-2008

Component Name

POWER TRAIN

Influencing Investigation(s)

Investigation Num	Subject	Investigator	Relationship
-------------------	---------	--------------	--------------

Related Recalls

Yr	Type	Major Sub	Relationship
----	------	-----------	--------------

Recall Characteristics

Unique Recall

Unique Descr

Recall Communications

Fax Ack: 04-AUG-2010

Letter Ack: 18-JUN-2010

Draft 577 Received: 04-AUG-2010

Draft 577 Approved: 04-AUG-2010

Final 577 Received: 03-SEP-2010

Owner Notification: 30-AUG-2010

Phased: N

577 End:

Renotification:

Envelope Approved:

Dealer Notification

Received:

Dealer Notification:

Recall Detail

Recall Num: 10 V 274 000 573 Date: 15-JUN-2010 573 Date Rcvd: 16-JUN-2010 Potentially Affected: 1,916 Potentially Defective: 1,916

Mfr Recall Num:

Subject: DRIVE CHAIN CAN BREAK Remedy Type: Fix/Repair RP Num: FMVSS Num:
 Recall Type: Defect Recall Effect: Crash Avoidance NHTSA Inv Num: Influenced by: MFR
 Problem Exp: Complaints Manufacturer: BMW OF NORTH AMERICA, LLC Recall Status: CONDUCTING RECALL

Problem Descr: BMW IS RECALLING CERTAIN MODEL YEAR 2008 AND 2009 F650 GS AND F 800 GS MOTORCYCLES MANUFACTURED FROM SEPTEMBER 27, 2007 THROUGH MARCH 30, 2009. THE DRIVE CHAINS MAY NOT HAVE BEEN PRODUCED TO SPECIFICATION. AS A RESULT, OVER TIME THE DRIVE CHAIN COULD BREAK.

Consequence: IF THE BROKEN CHAIN BECOMES TRAPPED BETWEEN THE REAR WHEEL AND THE FRAME, THE REAR WHEEL COULD LOCK UP, POSSIBLY RESULTING IN A CRASH.

Remedy Type: BMW WILL NOTIFY OWNERS AND DEALERS WILL REPLACE THE DRIVE CHAIN AND SPROCKETS ON THE AFFECTED MOTORCYCLES FREE OF CHARGE. THE SAFETY RECALL BEGAN ON AUGUST 30, 2010. OWNERS MAY CONTACT BMW AT 1-800-525-7417.

Notes: OWNERS MAY ALSO CONTACT THE NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION'S VEHICLE SAFETY HOTLINE AT 1-888-327-4236 (TTY 1-800-424-9153), OR GO TO HTTP://WWW.SAFERCAR.GOV .

MFR Knowl Dt: Prod Change Dt: Mfr Press Release Dt: NHTSA Press Release Dt:
 Stop Sales: Regional:
 Supplier: Mfr Toll Free Num: 800-525-7417

Products	Vehicle Usage	Beginning Mfg Date	Ending Mfg Date
Product Type :VEHICLE Product Category :MOTORCYCLES Manufacturer :BMW OF NORTH AMERICA, LLC Make :BMW Model :F 650 GS Model Year :2009		11-JAN-2008	24-MAR-2009
Product Type :VEHICLE Product Category :MOTORCYCLES Manufacturer :BMW OF NORTH AMERICA, LLC Make :BMW Model :F 800 GS Model Year :2009		27-SEP-2007	30-MAR-2009
Product Type :VEHICLE Product Category :MOTORCYCLES Manufacturer :BMW OF NORTH AMERICA, LLC Make :BMW Model :F 800 GS Model Year :2008		27-SEP-2007	30-MAR-2009
Product Type :VEHICLE Product Category :MOTORCYCLES Manufacturer :BMW OF NORTH AMERICA, LLC Make :BMW Model :F 650 GS Model Year :2008		11-JAN-2008	24-MAR-2009

Component Name

POWER TRAIN

Influencing Investigation(s)

Investigation Num	Subject	Investigator	Relationship
-------------------	---------	--------------	--------------

Related Recalls

Yr	Type	Major Sub	Relationship
----	------	-----------	--------------

Recall Characteristics

Unique Recall

Unique Descr

Recall Communications

Fax Ack: 04-AUG-2010

Letter Ack: 18-JUN-2010

Draft 577 Received: 04-AUG-2010

Draft 577 Approved: 04-AUG-2010

Final 577 Received: 03-SEP-2010

Owner Notification: 30-AUG-2010

Phased: N

577 End:

Renotification:

Envelope Approved:

Dealer Notification

Received: 15-JUL-2010

Dealer Notification:

Recall Detail

Recall Num: 10 V 275 000 573 Date: 15-JUN-2010 573 Date Rcvd: 16-JUN-2010 Potentially Affected: 2,070 Potentially Defective: 2,070

Mfr Recall Num:

Subject: FUEL TANK ATTACHMENT BOLTS Remedy Type: Fix/Repair RP Num: FMVSS Num:
 Recall Type: Defect Recall Effect: Crash Avoidance NHTSA Inv Num: Influenced by: MFR
 Problem Exp: Complaints Manufacturer: BMW OF NORTH AMERICA, LLC Recall Status: CONDUCTING RECALL

Problem Descr: BMW IS RECALLING CERTAIN 2005 THROUGH 2007 R 1200 GS ADVENTURE MOTORCYCLES MANUFACTURED FROM DECEMBER 7, 2005 THROUGH SEPTEMBER 26, 2007. THE FUEL TANK FRONT ATTACHMENT BOLTS CAN WORK LOOSE ALLOWING THE BOLTS TO COME INTO CONTACT WITH THE FORK LEG IF THE HANDLEBAR IS TURNED A SIGNIFICANT AMOUNT.

Consequence: THIS COULD LIMIT THE TRAVEL RANGE OF THE HANDLEBARS WHICH COULD AFFECT HANDLING AND MANEUVERABILITY OF THE MOTORCYCLE, INCREASING THE RISK OF A CRASH.

Remedy Type: BMW WILL NOTIFY OWNERS AND DEALERS WILL REPAIR MOTORCYCLES BY FURTHER SECURING THE BOLTS USING LOCTITE. THE REPAIR WILL BE PERFORMED FREE OF CHARGE. THE SAFETY RECALL BEGAN ON AUGUST 30, 2010. OWNERS MAY CONTACT BMW AT 1-800-525-7417.

Notes: OWNERS MAY ALSO CONTACT THE NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION'S VEHICLE SAFETY HOTLINE AT 1-888-327-4236 (TTY 1-800-424-9153), OR GO TO HTTP://WWW.SAFERCAR.GOV .

MFR Knowl Dt: Prod Change Dt: Mfr Press Release Dt: NHTSA Press Release Dt:
 Stop Sales: Regional:
 Supplier: Mfr Toll Free Num: 800-525-7417

Products	Vehicle Usage	Beginning Mfg Date	Ending Mfg Date
Product Type :VEHICLE Product Category :MOTORCYCLES Manufacturer :BMW OF NORTH AMERICA, LLC Make :BMW Model :R 1200 GS ADVENTURE Model Year :2007	Passenger	07-DEC-2005	26-SEP-2007
Product Type :VEHICLE Product Category :MOTORCYCLES Manufacturer :BMW OF NORTH AMERICA, LLC Make :BMW Model :R 1200 GS ADVENTURE Model Year :2005	Passenger	05-DEC-2005	26-DEC-2007
Product Type :VEHICLE Product Category :MOTORCYCLES Manufacturer :BMW OF NORTH AMERICA, LLC Make :BMW Model :R 1200 GS ADVENTURE Model Year :2006	Passenger	05-DEC-2005	26-SEP-2007

Component Name
 FUEL SYSTEM, GASOLINE:STORAGE:TANK ASSEMBLY

Influencing Investigation(s)

Investigation Num	Subject	Investigator	Relationship
-------------------	---------	--------------	--------------

Related Recalls

Yr	Type	Major Sub	Relationship
----	------	-----------	--------------

Recall Characteristics

Unique Recall

Unique Descr

Recall Communications

Fax Ack: 04-AUG-2010	Letter Ack: 22-JUN-2010
Draft 577 Received: 04-AUG-2010	Draft 577 Approved: 04-AUG-2010
Final 577 Received: 03-SEP-2010	Owner Notification: 30-AUG-2010
Phased: N	577 End:
Renotification:	Envelope Approved:
Dealer Notification Received: 15-JUL-2010	Dealer Notification:

Recall Detail

Recall Num: 10 V 276 000	573 Date: 15-JUN-2010	573 Date Rcvd: 18-JUN-2010	Potentially Affected: 15,532	Potentially Defective: 15,532
Mfr Recall Num:				
Subject: FRONT BRAKE LINES		Remedy Type: Fix/Repair	RP Num:	FMVSS Num:
Recall Type: Defect	Recall Effect: Crash Avoidance	NHTSA Inv Num:	Influenced by: MFR	
Problem Exp: Complaints		Manufacturer: BMW OF NORTH AMERICA, LLC	Recall Status: CONDUCTING RECALL	
Problem Descr: BMW IS RECALLING CERTAIN MODEL YEAR 2007 THROUGH 2009 R 1200 AND K 1200 SERIES MOTORCYCLES MANUFACTURED FROM AUGUST 2006 THROUGH MAY 2009. DUE TO THE CURRENT ROUTING OF THE FRONT BRAKE LINES, IT IS POSSIBLE THAT DURING RIDING, AND THEREFORE ASSOCIATED VIBRATION. THE BRAKE LINES COULD BE UNDER STRAIN. IF THE VIBRATION/STRAIN IS SIGNIFICANT, THE BRAKE LINE COULD SPLIT AND START TO DEVELOP A LEAK.				
Consequence: IF THIS GOES UNNOTICED, AND THE BRAKE FLUID RESERVOIR RUNS EMPTY, THE FRONT BRAKES COULD FAIL, INCREASING THE RISK OF A CRASH.				
Remedy Type: BMW WILL NOTIFY OWNERS AND DEALERS WILL INSTALL NEW BRAKE LINES, CONTAINING A "SLEEVE" ALONG A PORTION OF THE LINES FREE OF CHARGE. THE SAFETY RECALL BEGAN ON SEPTEMBER 20, 2010. OWNERS MAY CONTACT BMW AT 1-800-525-7417.				
Notes: OWNERS MAY ALSO CONTACT THE NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION'S VEHICLE SAFETY HOTLINE AT 1-888-327-4236 (TTY 1-800-424-9153), OR GO TO HTTP://WWW.SAFERCAR.GOV .				
MFR Knowl Dt:	Prod Change Dt:	Mfr Press Release Dt:	NHTSA Press Release Dt:	
Stop Sales:	Regional:			
Supplier:	Mfr Toll Free Num: 800-525-7417			

Products	Vehicle Usage	Beginning Mfg Date	Ending Mfg Date
----------	---------------	--------------------	-----------------

Product Type :VEHICLE Product Category
:MOTORCYCLES Manufacturer :BMW OF NORTH
AMERICA, LLC Make :BMW Model :R 1200 GS
ADVENTURE Model Year :2008

Product Type :VEHICLE Product Category
:MOTORCYCLES Manufacturer :BMW OF NORTH
AMERICA, LLC Make :BMW Model :R 1200 RT Model
Year :2009

Product Type :VEHICLE Product Category
:MOTORCYCLES Manufacturer :BMW OF NORTH
AMERICA, LLC Make :BMW Model :K 1200 GT Model
Year :2007

Product Type :VEHICLE Product Category
:MOTORCYCLES Manufacturer :BMW OF NORTH
AMERICA, LLC Make :BMW Model :R 1200 GS
ADVENTURE Model Year :2009

Product Type :VEHICLE Product Category
:MOTORCYCLES Manufacturer :BMW OF NORTH
AMERICA, LLC Make :BMW Model :R 1200 RT Model
Year :2007

Product Type :VEHICLE Product Category
:MOTORCYCLES Manufacturer :BMW OF NORTH
AMERICA, LLC Make :BMW Model :K 1200 GT Model
Year :2008

Product Type :VEHICLE Product Category
:MOTORCYCLES Manufacturer :BMW OF NORTH
AMERICA, LLC Make :BMW Model :R 1200 GS
ADVENTURE Model Year :2007

Product Type :VEHICLE Product Category
:MOTORCYCLES Manufacturer :BMW OF NORTH
AMERICA, LLC Make :BMW Model :R 1200 R Model
Year :2007

Product Type :VEHICLE Product Category
:MOTORCYCLES Manufacturer :BMW OF NORTH
AMERICA, LLC Make :BMW Model :R 1200 GS Model
Year :2007

Product Type :VEHICLE Product Category
:MOTORCYCLES Manufacturer :BMW OF NORTH
AMERICA, LLC Make :BMW Model :R 1200 R Model
Year :2009

Product Type :VEHICLE Product Category
:MOTORCYCLES Manufacturer :BMW OF NORTH
AMERICA, LLC Make :BMW Model :R 1200 GS Model
Year :2009

Component Name

SERVICE BRAKES, HYDRAULIC

Products	Vehicle Usage	Beginning Mfg Date	Ending Mfg Date
----------	---------------	--------------------	-----------------

Product Type :VEHICLE Product Category :MOTORCYCLES
 Manufacturer :BMW OF NORTH AMERICA, LLC Make :BMW Model :R 1200 RT Model Year :2008

Product Type :VEHICLE Product Category :MOTORCYCLES
 Manufacturer :BMW OF NORTH AMERICA, LLC Make :BMW Model :R 1200 GS Model Year :2008

Product Type :VEHICLE Product Category :MOTORCYCLES
 Manufacturer :BMW OF NORTH AMERICA, LLC Make :BMW Model :R 1200 R Model Year :2008

Product Type :VEHICLE Product Category :MOTORCYCLES
 Manufacturer :BMW OF NORTH AMERICA, LLC Make :BMW Model :R 1200 ST Model Year :2007

Component Name

Influencing Investigation(s)

Investigation Num	Subject	Investigator	Relationship
-------------------	---------	--------------	--------------

Related Recalls

Yr	Type	Major Sub	Relationship
----	------	-----------	--------------

Recall Characteristics

Unique Recall	Unique Descr
---------------	--------------

Recall Communications

Fax Ack: 26-JUL-2010	Letter Ack: 22-JUN-2010
Draft 577 Received: 26-JUL-2010	Draft 577 Approved: 26-JUL-2010
Final 577 Received:	Owner Notification: 20-SEP-2010
Phased: N	577 End:
Renotification:	Envelope Approved:
Dealer Notification Received:	Dealer Notification:

Recall Detail

Recall Num: 10 V 328 000 573 Date: 19-JUL-2010 573 Date Rcvd: 20-JUL-2010 Potentially Affected: 1,900 Potentially Defective: 1,900
 Mfr Recall Num:
 Subject: AUDIBLE SIGNALING DEVICE BRACKET Remedy Type: Fix/Repair RP Num: FMVSS Num:
 Recall Type: Defect Recall Effect: Crash Avoidance NHTSA Inv Num: Influenced by: MFR
 Problem Exp: Other Manufacturer: BMW OF NORTH AMERICA, LLC Recall Status: CONDUCTING RECALL
 Problem Descr: BMW IS RECALLING CERTAIN 2005 THROUGH 2009 R 1200 RT POLICE MOTORCYCLES MANUFACTURED FROM APRIL 2005 THROUGH SEPTEMBER 2009. THE BRACKET WHICH SUPPORTS THE AUDIBLE SIGNALING DEVICE CAN BREAK, POSSIBLY ALLOWING THE SIGNALING DEVICE TO FALL FROM THE VEHICLE AND ONTO THE ROADWAY.
 Consequence: SHOULD THE SIGNALING DEVICE FALL FROM THE MOTORCYCLE WHILE BEING DRIVEN ON THE ROADWAYS, IT COULD BECOME AN OBSTACLE FOR OTHER DRIVERS WHICH MAY RESULT IN A CRASH.
 Remedy Type: DEALERS WILL ATTACH TWO TETHER CABLES TO THE DEVICE IN ORDER TO SECURE IT TO THE MOTORCYCLE IN THE EVENT THE MOUNTING BRACKET BECOMES LOOSE. THIS SERVICE WILL BE PERFORMED FREE OF CHARGE. THE SAFETY RECALL BEGAN ON NOVEMBER 2, 2010. OWNERS MAY CONTACT BMW AT 1-800-525-7417.
 Notes: OWNERS MAY ALSO CONTACT THE NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION'S VEHICLE SAFETY HOTLINE AT 1-888-327-4236 (TTY 1-800-424-9153), OR GO TO HTTP://WWW.SAFERCAR.GOV .
 MFR Knowl Dt: Prod Change Dt: Mfr Press Release Dt: NHTSA Press Release Dt:
 Stop Sales: Regional:
 Supplier: Mfr Toll Free Num: 800-525-7417

Products	Vehicle Usage	Beginning Mfg Date	Ending Mfg Date
Product Type :VEHICLE Product Category :MOTORCYCLES Manufacturer :BMW OF NORTH AMERICA, LLC Make :BMW Model :R 1200 RT (AUTHORITY) Model Year :2007		01-APR-2005	30-SEP-2009
Product Type :VEHICLE Product Category :MOTORCYCLES Manufacturer :BMW OF NORTH AMERICA, LLC Make :BMW Model :R 1200 RT (AUTHORITY) Model Year :2005		01-APR-2005	30-SEP-2009
Product Type :VEHICLE Product Category :MOTORCYCLES Manufacturer :BMW OF NORTH AMERICA, LLC Make :BMW Model :R 1200 RT (AUTHORITY) Model Year :2009		01-APR-2005	30-SEP-2009
Product Type :VEHICLE Product Category :MOTORCYCLES Manufacturer :BMW OF NORTH AMERICA, LLC Make :BMW Model :R 1200 RT (AUTHORITY) Model Year :2006		01-APR-2005	30-SEP-2009
Product Type :VEHICLE Product Category :MOTORCYCLES Manufacturer :BMW OF NORTH AMERICA, LLC Make :BMW Model :R 1200 RT (AUTHORITY) Model Year :2008		01-APR-2005	30-SEP-2009

Component Name
EQUIPMENT

Influencing Investigation(s)

Investigation Num	Subject	Investigator	Relationship
-------------------	---------	--------------	--------------

Related Recalls

Yr	Type	Major Sub	Relationship
----	------	-----------	--------------

Recall Characteristics

Unique Recall	Unique Descr
---------------	--------------

Recall Communications

Fax Ack: 05-OCT-2010	Letter Ack: 20-JUL-2010
Draft 577 Received: 05-OCT-2010	Draft 577 Approved: 05-OCT-2010
Final 577 Received: 10-NOV-2010	Owner Notification: 02-NOV-2010
Phased: N	577 End:
Renotification:	Envelope Approved:
Dealer Notification Received: 16-SEP-2010	Dealer Notification:

Recall Detail

Recall Num: 10 V 331 000 573 Date: 21-JUL-2010 573 Date Rcvd: 22-JUL-2010 Potentially Affected: 6,080 Potentially Defective: 6,080

Mfr Recall Num:

Subject: FUEL LEVEL SENSOR Remedy Type: Fix/Repair RP Num: FMVSS Num:
 Recall Type: Defect Recall Effect: Crash Avoidance NHTSA Inv Num: Influenced by: MFR
 Problem Exp: Other Manufacturer: BMW OF NORTH AMERICA, LLC Recall Status: CONDUCTING RECALL

Problem Descr: BMW IS RECALLING CERTAIN 2010 AND 2011 5-SERIES AND 5-SERIES GRAN TURISMO PASSENGER VEHICLES MANUFACTURED FROM JANUARY 12 THROUGH JULY 1, 2010. THE VEHICLE'S FUEL LEVEL SENSOR WITHIN THE FUEL TANK CAN BECOME WEDGED AGAINST THE TANK.

Consequence: IF THIS OCCURS, THE FUEL GAUGE IN THE INSTRUMENT CLUSTER WOULD DISPLAY A LARGER AMOUNT OF FUEL THAN WAS ACTUALLY IN THE TANK. AS A RESULT, IF THE TANK BECAME EMPTY, THE VEHICLE COULD STALL INCREASING THE RISK OF A CRASH.

Remedy Type: BMW WILL NOTIFY OWNERS AND DEALERS WILL REPAIR THE VEHICLES FREE OF CHARGE. THE SAFETY RECALL BEGAN ON OCTOBER 18, 2010. OWNERS MAY CONTACT BMW AT 1-800-525-7417.

Notes: OWNERS MAY ALSO CONTACT THE NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION'S VEHICLE SAFETY HOTLINE AT 1-888-327-4236 (TTY 1-800-424-9153), OR GO TO HTTP://WWW.SAFERCAR.GOV .

MFR Knowl Dt: Prod Change Dt: Mfr Press Release Dt: NHTSA Press Release Dt:
 Stop Sales: Regional:
 Supplier: Mfr Toll Free Num: 800-525-7417

Products	Vehicle Usage	Beginning Mfg Date	Ending Mfg Date
Product Type :VEHICLE Product Category :LIGHT VEHICLES Manufacturer :BMW OF NORTH AMERICA, LLC Make :BMW Model :5-SERIES GRAN TURISMO Model Year :2010 Type :PASSENGER CAR		12-JAN-2010	01-JUL-2010
Product Type :VEHICLE Product Category :LIGHT VEHICLES Manufacturer :BMW OF NORTH AMERICA, LLC Make :BMW Model :5-SERIES GRAN TURISMO Model Year :2011 Type :PASSENGER CAR		12-JAN-2010	01-JUL-2010
Product Type :VEHICLE Product Category :LIGHT VEHICLES Manufacturer :BMW OF NORTH AMERICA, LLC Make :BMW Model :5-SERIES Model Year :2011 Type :PASSENGER CAR		12-JAN-2010	01-JUL-2010
Product Type :VEHICLE Product Category :LIGHT VEHICLES Manufacturer :BMW OF NORTH AMERICA, LLC Make :BMW Model :5-SERIES Model Year :2010 Type :PASSENGER CAR		12-JAN-2010	01-JUL-2010

Component Name
 FUEL SYSTEM, OTHER:STORAGE:FUEL GAUGE SYSTEM

Influencing Investigation(s)

Investigation Num	Subject	Investigator	Relationship

Related Recalls

Yr	Type	Major Sub	Relationship

Recall Characteristics

Unique Recall

Unique Descr

Recall Communications

Fax Ack: 14-SEP-2010

Letter Ack: 22-JUL-2010

Draft 577 Received: 14-SEP-2010

Draft 577 Approved: 14-SEP-2010

Final 577 Received: 19-OCT-2010

Owner Notification: 18-OCT-2010

Phased: N

577 End:

Renotification:

Envelope Approved:

Dealer Notification

Received:

Dealer Notification:

Recall Detail

Recall Num: 10 V 446 000 573 Date: 30-SEP-2010 573 Date Rcvd: 01-OCT-2010 Potentially Affected: 198,352 Potentially Defective: 198

Mfr Recall Num:

Subject: BRAKE VACUUM PUMP Remedy Type: Inspect and Replace RP Num: FMVSS Num:
Recall Type: Defect Recall Effect: Crash Avoidance NHTSA Inv Num: Influenced by: MFR
Problem Exp: Complaints Manufacturer: BMW OF NORTH AMERICA, LLC Recall Status: CONDUCTING RECALL

Problem Descr: BMW IS RECALLING CERTAIN MODEL YEAR 2004-2010 5-SERIES, 6-SERIES, AND MODEL YEAR 2002-2008 7-SERIES VEHICLES. A CHECK VALVE OF THE BRAKE VACUUM PUMP MAY LEAK A SMALL AMOUNT OF LUBRICATING OIL. OVER TIME THIS COULD RESULT IN CONTAMINATION OF THE BRAKE BOOSTER.

Consequence: POWER ASSIST BRAKING PERFORMANCE COULD BE ADVERSELY AFFECTED. IN EXTREME CASES THERE COULD BE A COMPLETE LOSS OF POWER ASSIST BRAKING. AN UNEXPECTED REDUCTION OR LOSS IN POWER BRAKING ASSIST MAY INCREASE THE RISK OF A CRASH.

Remedy Type: BMW WILL NOTIFY OWNERS AND DEALERS WILL REPAIR THE VEHICLES FREE OF CHARGE. THE SAFETY RECALL BEGAN ON NOVEMBER 24, 2010. OWNERS MAY CONTACT BMW AT 1-800-525-7417.

Notes: OWNERS MAY ALSO CONTACT THE NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION'S VEHICLE SAFETY HOTLINE AT 1-888-327-4236 (TTY 1-800-424-9153), OR GO TO HTTP://WWW.SAFERCAR.GOV .

MFR Knowl Dt: Prod Change Dt: Mfr Press Release Dt: NHTSA Press Release Dt:

Stop Sales: Regional:

Supplier: Mfr Toll Free Num: 800-332-4269

Products	Vehicle Usage	Beginning Mfg Date	Ending Mfg Date
Product Type :VEHICLE Product Category :LIGHT VEHICLES Manufacturer :BMW OF NORTH AMERICA, LLC Make :BMW Model :5 SERIES Model Year :2009 Type :PASSENGER CAR	Passenger		
Product Type :VEHICLE Product Category :LIGHT VEHICLES Manufacturer :BMW OF NORTH AMERICA, LLC Make :BMW Model :5 SERIES Model Year :2008 Type :PASSENGER CAR	Passenger		
Product Type :VEHICLE Product Category :LIGHT VEHICLES Manufacturer :BMW OF NORTH AMERICA, LLC Make :BMW Model :5-SERIES Model Year :2010 Type :PASSENGER CAR	Passenger		
Product Type :VEHICLE Product Category :LIGHT VEHICLES Manufacturer :BMW OF NORTH AMERICA, LLC Make :BMW Model :6 SERIES Model Year :2006 Type :PASSENGER CAR	Passenger		
Product Type :VEHICLE Product Category :LIGHT VEHICLES Manufacturer :BMW OF NORTH AMERICA, LLC Make :BMW Model :7 SERIES Model Year :2003 Type :PASSENGER CAR	Passenger		
Product Type :VEHICLE Product Category :LIGHT VEHICLES Manufacturer :BMW OF NORTH AMERICA, LLC Make :BMW Model :5 SERIES Model Year :2005 Type :PASSENGER CAR	Passenger		
Product Type :VEHICLE Product Category :LIGHT VEHICLES Manufacturer :BMW OF NORTH AMERICA, LLC Make :BMW Model :6 SERIES Model Year :2007 Type :PASSENGER CAR	Passenger		
Product Type :VEHICLE Product Category :LIGHT VEHICLES Manufacturer :BMW OF NORTH AMERICA, LLC Make :BMW Model :6 SERIES Model Year :2005 Type :PASSENGER CAR	Passenger		
Product Type :VEHICLE Product Category :LIGHT VEHICLES Manufacturer :BMW OF NORTH AMERICA, LLC Make :BMW Model :7 SERIES Model Year :2007 Type :PASSENGER CAR	Passenger		
Product Type :VEHICLE Product Category :LIGHT VEHICLES Manufacturer :BMW OF NORTH AMERICA, LLC Make :BMW Model :7 SERIES Model Year :2006 Type :PASSENGER CAR	Passenger		
Product Type :VEHICLE Product Category :LIGHT VEHICLES Manufacturer :BMW OF NORTH AMERICA, LLC Make :BMW Model :7 SERIES Model Year :2004 Type :PASSENGER CAR	Passenger		

Component Name

SERVICE BRAKES, HYDRAULIC:POWER ASSIST:VACUUM

Recall Detail

Products	Vehicle Usage	Beginning Mfg Date	Ending Mfg Date
----------	---------------	--------------------	-----------------

Product Type :VEHICLE Product Category :LIGHT VEHICLES Manufacturer :BMW OF NORTH AMERICA, LLC Make :BMW Model :7 SERIES Model Year :2002 Type :PASSENGER CAR

Passenger

Product Type :VEHICLE Product Category :LIGHT VEHICLES Manufacturer :BMW OF NORTH AMERICA, LLC Make :BMW Model :6 SERIES Model Year :2009 Type :PASSENGER CAR

Passenger

Product Type :VEHICLE Product Category :LIGHT VEHICLES Manufacturer :BMW OF NORTH AMERICA, LLC Make :BMW Model :5 SERIES Model Year :2004 Type :PASSENGER CAR

Passenger

Product Type :VEHICLE Product Category :LIGHT VEHICLES Manufacturer :BMW OF NORTH AMERICA, LLC Make :BMW Model :6 SERIES Model Year :2004 Type :PASSENGER CAR

Passenger

Product Type :VEHICLE Product Category :LIGHT VEHICLES Manufacturer :BMW OF NORTH AMERICA, LLC Make :BMW Model :7 SERIES Model Year :2008 Type :PASSENGER CAR

Passenger

Product Type :VEHICLE Product Category :LIGHT VEHICLES Manufacturer :BMW OF NORTH AMERICA, LLC Make :BMW Model :6 SERIES Model Year :2010 Type :PASSENGER CAR

Passenger

Product Type :VEHICLE Product Category :LIGHT VEHICLES Manufacturer :BMW OF NORTH AMERICA, LLC Make :BMW Model :5 SERIES Model Year :2007 Type :PASSENGER CAR

Passenger

Product Type :VEHICLE Product Category :LIGHT VEHICLES Manufacturer :BMW OF NORTH AMERICA, LLC Make :BMW Model :5 SERIES Model Year :2006 Type :PASSENGER CAR

Passenger

Product Type :VEHICLE Product Category :LIGHT VEHICLES Manufacturer :BMW OF NORTH AMERICA, LLC Make :BMW Model :6 SERIES Model Year :2008 Type :PASSENGER CAR

Passenger

Product Type :VEHICLE Product Category :LIGHT VEHICLES Manufacturer :BMW OF NORTH AMERICA, LLC Make :BMW Model :7 SERIES Model Year :2005 Type :PASSENGER CAR

Passenger

Component Name

Influencing Investigation(s)

Investigation Num	Subject	Investigator	Relationship
-------------------	---------	--------------	--------------

Related Recalls

Yr	Type	Major Sub	Relationship
----	------	-----------	--------------

Recall Characteristics

Unique Recall	Unique Descr
---------------	--------------

Recall Communications

Fax Ack: 12-NOV-2010	Letter Ack: 01-OCT-2010
Draft 577 Received: 12-NOV-2010	Draft 577 Approved: 12-NOV-2010
Final 577 Received: 06-DEC-2010	Owner Notification: 24-NOV-2010
Phased: N	577 End:
Renotification:	Envelope Approved:
Dealer Notification Received: 06-APR-2011	Dealer Notification:

Recall Num: 10 V 488 000	573 Date: 08-OCT-2010	573 Date Rcvd: 08-OCT-2010	Potentially Affected: 11,826	Potentially Defective: 11,826
Mfr Recall Num:				
Subject: REAR WHEEL LINKAGE		Remedy Type: Inspect and Replace	RP Num:	FMVSS Num:
Recall Type: Defect	Recall Effect: Crash Avoidance	NHTSA Inv Num:	Influenced by: MFR	
Problem Exp: Complaints		Manufacturer: BMW OF NORTH AMERICA, LLC	Recall Status: CONDUCTING RECALL	
Problem Descr: BMW IS RECALLING CERTAIN MODEL YEAR 2005-2011 MOTORCYCLES. THE BEARINGS COULD BE SUBJECT TO CORROSION. THIS COULD LEAD TO REDUCED MOVEMENT OF THE LINK LEVER.				
Consequence: THIS COULD AFFECT THE HANDLING OF THE MOTORCYCLE INCREASING THE RISK A DRIVER MAY LOSE CONTROL OF THE VEHICLE RESULTING IN A CRASH.				
Remedy Type: BMW WILL NOTIFY OWNERS AND DEALERS WILL REPAIR THE VEHICLES FREE OF CHARGE. THE SAFETY RECALL IS EXPECTED TO BEGIN DURING MARCH 2011. OWNERS MAY CONTACT BMW AT 1-800-525-7417.				
Notes: OWNERS MAY ALSO CONTACT THE NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION'S VEHICLE SAFETY HOTLINE AT 1-888-327-4236 (TTY 1-800-424-9153), OR GO TO HTTP://WWW.SAFERCAR.GOV .				
MFR Knowl Dt:	Prod Change Dt:	Mfr Press Release Dt:	NHTSA Press Release Dt:	
Stop Sales:	Regional:			
Supplier:	Mfr Toll Free Num:			

Recall Detail

Products	Vehicle Usage	Beginning Mfg Date	Ending Mfg Date
Product Type :VEHICLE Product Category :MOTORCYCLES Manufacturer :BMW OF NORTH AMERICA, LLC Make :BMW Model :K1300 S Model Year :2010		01-SEP-2008	30-SEP-2010
Product Type :VEHICLE Product Category :MOTORCYCLES Manufacturer :BMW OF NORTH AMERICA, LLC Make :BMW Model :K1200 S Model Year :2007	Passenger	01-MAY-2004	31-AUG-2008
Product Type :VEHICLE Product Category :MOTORCYCLES Manufacturer :BMW OF NORTH AMERICA, LLC Make :BMW Model :K1200 S Model Year :2005	Passenger	01-MAY-2004	31-AUG-2008
Product Type :VEHICLE Product Category :MOTORCYCLES Manufacturer :BMW OF NORTH AMERICA, LLC Make :BMW Model :K1200 GT Model Year :2005	Passenger	01-MAY-2004	31-AUG-2008
Product Type :VEHICLE Product Category :MOTORCYCLES Manufacturer :BMW OF NORTH AMERICA, LLC Make :BMW Model :K1300 GT Model Year :2011		01-SEP-2008	30-SEP-2010
Product Type :VEHICLE Product Category :MOTORCYCLES Manufacturer :BMW OF NORTH AMERICA, LLC Make :BMW Model :K1300 S Model Year :2011		01-SEP-2008	30-SEP-2010
Product Type :VEHICLE Product Category :MOTORCYCLES Manufacturer :BMW OF NORTH AMERICA, LLC Make :BMW Model :K1200 R Model Year :2008	Passenger	01-MAY-2004	31-AUG-2008
Product Type :VEHICLE Product Category :MOTORCYCLES Manufacturer :BMW OF NORTH AMERICA, LLC Make :BMW Model :K1300 GT Model Year :2009		01-SEP-2008	30-SEP-2010
Product Type :VEHICLE Product Category :MOTORCYCLES Manufacturer :BMW OF NORTH AMERICA, LLC Make :BMW Model :K1300 R Model Year :2009		01-SEP-2008	30-SEP-2010
Product Type :VEHICLE Product Category :MOTORCYCLES Manufacturer :BMW OF NORTH AMERICA, LLC Make :BMW Model :K1200 R Model Year :2005	Passenger	01-MAY-2004	31-AUG-2008
Product Type :VEHICLE Product Category :MOTORCYCLES Manufacturer :BMW OF NORTH AMERICA, LLC Make :BMW Model :K1300 R Model Year :2011		01-SEP-2008	30-SEP-2010

Component Name

SUSPENSION:REAR

Recall Detail

Products	Vehicle Usage	Beginning Mfg Date	Ending Mfg Date
Product Type :VEHICLE Product Category :MOTORCYCLES Manufacturer :BMW OF NORTH AMERICA, LLC Make :BMW Model :K1200 S Model Year :2006	Passenger	01-MAY-2004	31-AUG-2008
Product Type :VEHICLE Product Category :MOTORCYCLES Manufacturer :BMW OF NORTH AMERICA, LLC Make :BMW Model :K1200 R Model Year :2006	Passenger	01-MAY-2004	31-AUG-2008
Product Type :VEHICLE Product Category :MOTORCYCLES Manufacturer :BMW OF NORTH AMERICA, LLC Make :BMW Model :K1300 R Model Year :2010		01-SEP-2008	30-SEP-2010
Product Type :VEHICLE Product Category :MOTORCYCLES Manufacturer :BMW OF NORTH AMERICA, LLC Make :BMW Model :K1200 S Model Year :2008	Passenger	01-MAY-2004	31-AUG-2008
Product Type :VEHICLE Product Category :MOTORCYCLES Manufacturer :BMW OF NORTH AMERICA, LLC Make :BMW Model :K1200 GT Model Year :2008	Passenger	01-MAY-2004	31-AUG-2008
Product Type :VEHICLE Product Category :MOTORCYCLES Manufacturer :BMW OF NORTH AMERICA, LLC Make :BMW Model :K1200 GT Model Year :2006	Passenger	01-MAY-2004	31-AUG-2008
Product Type :VEHICLE Product Category :MOTORCYCLES Manufacturer :BMW OF NORTH AMERICA, LLC Make :BMW Model :K1300 GT Model Year :2010		01-SEP-2008	30-SEP-2010
Product Type :VEHICLE Product Category :MOTORCYCLES Manufacturer :BMW OF NORTH AMERICA, LLC Make :BMW Model :K1300 S Model Year :2009		01-SEP-2008	30-SEP-2010
Product Type :VEHICLE Product Category :MOTORCYCLES Manufacturer :BMW OF NORTH AMERICA, LLC Make :BMW Model :K1200 GT Model Year :2007	Passenger	01-MAY-2004	31-AUG-2008
Product Type :VEHICLE Product Category :MOTORCYCLES Manufacturer :BMW OF NORTH AMERICA, LLC Make :BMW Model :K1200 R Model Year :2007	Passenger	01-MAY-2004	31-AUG-2008

Component Name

Influencing Investigation(s)

Investigation Num	Subject	Investigator	Relationship
-------------------	---------	--------------	--------------

Related Recalls

Yr	Type	Major Sub	Relationship
----	------	-----------	--------------

Recall Characteristics

Unique Recall	Unique Descr
---------------	--------------

Recall Communications

Fax Ack: 28-DEC-2010	Letter Ack: 14-OCT-2010
Draft 577 Received: 28-DEC-2010	Draft 577 Approved: 28-DEC-2010
Final 577 Received:	Owner Notification: 30-MAR-2011
Phased: N	577 End:
Renotification:	Envelope Approved:
Dealer Notification Received:	Dealer Notification:

Recall Detail

Recall Num: 10 V 496 000 573 Date: 14-OCT-2010 573 Date Rcvd: 18-OCT-2010 Potentially Affected: 1,780 Potentially Defective: 1,780

Mfr Recall Num:

Subject: FRONT DISC BRAKE FASTENERS Remedy Type: Fix/Repair RP Num: FMVSS Num:

Recall Type: Defect Recall Effect: Crash Avoidance NHTSA Inv Num: Influenced by: MFR

Problem Exp: Manufacturer: BMW OF NORTH AMERICA, LLC Recall Status: CONDUCTING RECALL

Problem Descr: BMW IS RECALLING CERTAIN 2008 THROUGH 2010 F 650 GS MOTORCYCLES MANUFACTURED FROM JANUARY 11, 2008, THROUGH DECEMBER 8, 2009. A WASHER MAY INTERFERE WITH THE FRONT DISC BRAKE FASTENERS' TORQUE. AS A RESULT, OVER TIME, A FASTENER OR MUTIPLE FASTENERS COULD BECOME LOOSE, ALLOWING THE BRAKE DISC TO BECOME LOOSE.

Consequence: A LOOSE BRAKE DISC MAY INTERFERE WITH PROPER BRAKING PERFORMANCE AND MAY INCREASE THE RISK OF A CRASH.

Remedy Type: BMW WILL NOTIFY OWNERS AND DEALERS WILL REPAIR THE VEHICLES FREE OF CHARGE. THE SAFETY RECALL BEGAN ON JANUARY 13, 2011. OWNERS MAY CONTACT BMW AT 1-800-525-7417.

Notes: OWNERS MAY ALSO CONTACT THE NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION'S VEHICLE SAFETY HOTLINE AT 1-888-327-4236 (TTY 1-800-424-9153), OR GO TO HTTP://WWW.SAFERCAR.GOV .

MFR Knowl Dt: Prod Change Dt: Mfr Press Release Dt: NHTSA Press Release Dt:

Stop Sales: Regional:

Supplier: Mfr Toll Free Num: 1-800-525-7417

Products	Vehicle Usage	Beginning Mfg Date	Ending Mfg Date
----------	---------------	--------------------	-----------------

Product Type :VEHICLE Product Category :MOTORCYCLES Manufacturer :BMW OF NORTH AMERICA, LLC Make :BMW Model :F 650 GS Model Year :2008

11-JAN-2008 08-DEC-2009

Product Type :VEHICLE Product Category :MOTORCYCLES Manufacturer :BMW OF NORTH AMERICA, LLC Make :BMW Model :F 650 GS Model Year :2010

11-JAN-2008 08-DEC-2009

Product Type :VEHICLE Product Category :MOTORCYCLES Manufacturer :BMW OF NORTH AMERICA, LLC Make :BMW Model :F 650 GS Model Year :2009

11-JAN-2008 08-DEC-2009

Component Name

SERVICE BRAKES, HYDRAULIC:FOUNDATION COMPONENTS:DISC

Influencing Investigation(s)

Investigation Num	Subject	Investigator	Relationship
-------------------	---------	--------------	--------------

Related Recalls

Yr	Type	Major Sub	Relationship
----	------	-----------	--------------

Recall Characteristics

Unique Recall

Unique Descr

Recall Communications

Fax Ack: 28-DEC-2010

Letter Ack: 19-OCT-2010

Draft 577 Received: 28-DEC-2010

Draft 577 Approved: 28-DEC-2010

Final 577 Received: 14-JAN-2011

Owner Notification: 13-JAN-2011

Phased: N

577 End:

Renotification:

Envelope Approved:

Dealer Notification

Received:

Dealer Notification:

Recall Detail

Recall Num: 10 V 518 000 573 Date: 26-OCT-2010 573 Date Rcvd: 26-OCT-2010 Potentially Affected: 20,750 Potentially Defective: 20,750

Mfr Recall Num:

Subject: MALFUNCTION FUEL PUMP Remedy Type: Inspect and Replace RP Num: FMVSS Num:
 Recall Type: Defect Recall Effect: Crash Avoidance NHTSA Inv Num: Influenced by: MFR
 Problem Exp: Complaints Manufacturer: BMW OF NORTH AMERICA, LLC Recall Status: CONDUCTING RECALL

Problem Descr: BMW IS RECALLING CERTAIN MODEL YEAR 2008 X5 SAVs VEHICLES WITH 6-CYLINDER ENGINES MANUFACTURED FROM NOVEMBER 1, 2007 THROUGH AUGUST 31, 2008. DUE TO A MANUFACTURING PROCESS FAULT, THE FUEL PUMP WAS NOT PRODUCED TO SPECIFICATIONS. UNDER SPECIFIC VEHICLE OPERATING CONDITIONS, THE FUEL PUMP'S COMMUTATOR COULD EXPERIENCE AN INCREASE IN WEAR.

Consequence: THIS WEAR COULD LEAD TO FUEL PUMP MALFUNCTION AND ENGINE STALLING. ENGINE STALLING COULD CREATE A POTENTIAL FOR A CRASH RESULTING IN INJURY OR DEATH.

Remedy Type: DEALERS WILL REPLACE THE IN-TANK FUEL PUMP FREE OF CHARGE. THE SAFETY RECALL BEGAN ON JANUARY 11, 2011. OWNERS MAY CONTACT BMW AT 1-800-525-7417.

Notes: OWNERS MAY ALSO CONTACT THE NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION'S VEHICLE SAFETY HOTLINE AT 1-888-327-4236 (TTY 1-800-424-9153), OR GO TO HTTP://WWW.SAFERCAR.GOV .

MFR Knowl Dt: Prod Change Dt: Mfr Press Release Dt: NHTSA Press Release Dt:
 Stop Sales: Regional:
 Supplier: Mfr Toll Free Num: 800-525-7417

Products	Vehicle Usage	Beginning Mfg Date	Ending Mfg Date
----------	---------------	--------------------	-----------------

Product Type :VEHICLE Product Category :LIGHT VEHICLES
 Manufacturer :BMW OF NORTH AMERICA, LLC
 Make :BMW Model :X5 Model Year :2008 Type :PASSENGER CAR

Passenger 01-NOV-2007 31-AUG-2008

Component Name

FUEL SYSTEM, GASOLINE:DELIVERY:FUEL PUMP

Influencing Investigation(s)

Investigation Num	Subject	Investigator	Relationship
-------------------	---------	--------------	--------------

Related Recalls

Yr	Type	Major Sub	Relationship
----	------	-----------	--------------

Recall Characteristics

Unique Recall	Unique Descr
---------------	--------------

Recall Communications

Fax Ack: 17-DEC-2010	Letter Ack: 29-OCT-2010
Draft 577 Received: 17-DEC-2010	Draft 577 Approved: 17-DEC-2010
Final 577 Received: 20-JAN-2011	Owner Notification: 11-JAN-2011
Phased: N	577 End:
Renotification:	Envelope Approved:
Dealer Notification Received:	Dealer Notification:

Recall Detail

Recall Num: 10 V 542 000	573 Date: 02-NOV-2010	573 Date Rcvd: 02-NOV-2010	Potentially Affected: 54,200	Potentially Defective: 54,200
Mfr Recall Num:				
Subject: TIRE PRESSURE LABEL/FMVSS 110/PETITION		Remedy Type: Mail Labels	RP Num: 571	FMVSS Num: 110
Recall Type: Compliance	Recall Effect: Crash Avoidance	NHTSA Inv Num:	Influenced by: MFR	
Problem Exp: Complaints		Manufacturer: BMW OF NORTH AMERICA, LLC	Recall Status: PETITION PENDING	
Problem Descr: BMW HAS NOTIFIED NHTSA THAT CERTAIN MODEL YEAR 2008-2011 X5 SAV, X6 SAC, AND MODEL YEAR 2011 5-SERIES, 5-SERIES GRAN TURISMO, AND 7-SERIES VEHICLES FOR FAILING TO COMPLY WITH THE REQUIREMENTS OF FEDERAL MOTOR VEHICLES SAFETY STANDARD NO. 110, "TIRE SELECTION AND RIMS FOR MOTOR VEHICLES." THE TIRE LABEL INCLUDES A RECOMMENDED COLD TIRE INFLATION PRESSURE AND TIRE SIZE DESIGNATION FOR A SPARE TIRE. THESE VEHICLES ARE EQUIPPED WITH "RUN-FLAT" TIRES AND THEREFORE THESE VEHICLES DO NOT NEED AND ARE NOT EQUIPPED WITH A SPARE TIRE.				
Consequence: SEE NOTES:				
Remedy Type: SEE NOTES:				
Notes: THE MANUFACTURER IS PETITIONING NHTSA FOR A DETERMINATION THAT THIS MATTER IS INCONSEQUENTIAL TO MOTOR VEHICLE SAFETY. THE MANUFACTURER IS NOT OBLIGATED TO CONDUCT AN OWNER NOTIFICATION AND REMEDY CAMPAIGN UNTIL NHTSA HAS RESOLVED THIS PETITION. IF THE PETITION IS DENIED, THE MANUFACTURER WILL BE NOTIFIED AND MUST THEN UNDERTAKE ITS NOTIFICATION AND REMEDY CAMPAIGN OBLIGATIONS.				
MFR Knowl Dt:	Prod Change Dt:	Mfr Press Release Dt:	NHTSA Press Release Dt:	
Stop Sales:	Regional:			
Supplier:	Mfr Toll Free Num:			

Products	Vehicle Usage	Beginning Mfg Date	Ending Mfg Date
Product Type :VEHICLE Product Category :LIGHT VEHICLES Manufacturer :BMW OF NORTH AMERICA, LLC Make :BMW Model :X6 Model Year :2010 Type :PASSENGER CAR	Passenger	19-SEP-2008	26-OCT-2010
Product Type :VEHICLE Product Category :LIGHT VEHICLES Manufacturer :BMW OF NORTH AMERICA, LLC Make :BMW Model :7-SERIES Model Year :2011 Type :PASSENGER CAR	Passenger	01-SEP-2010	26-OCT-2010
Product Type :VEHICLE Product Category :LIGHT VEHICLES Manufacturer :BMW OF NORTH AMERICA, LLC Make :BMW Model :X5 Model Year :2010 Type :PASSENGER CAR	Passenger	02-FEB-2008	26-OCT-2010
Product Type :VEHICLE Product Category :LIGHT VEHICLES Manufacturer :BMW OF NORTH AMERICA, LLC Make :BMW Model :X5 Model Year :2009 Type :PASSENGER CAR	Passenger	02-FEB-2008	26-OCT-2010
Product Type :VEHICLE Product Category :LIGHT VEHICLES Manufacturer :BMW OF NORTH AMERICA, LLC Make :BMW Model :X6 Model Year :2009 Type :PASSENGER CAR	Passenger	19-SEP-2008	26-OCT-2010
Product Type :VEHICLE Product Category :LIGHT VEHICLES Manufacturer :BMW OF NORTH AMERICA, LLC Make :BMW Model :5-SERIES Model Year :2011 Type :PASSENGER CAR	Passenger	01-SEP-2010	26-OCT-2010
Product Type :VEHICLE Product Category :LIGHT VEHICLES Manufacturer :BMW OF NORTH AMERICA, LLC Make :BMW Model :X5 Model Year :2011 Type :PASSENGER CAR	Passenger	02-FEB-2008	26-OCT-2010
Product Type :VEHICLE Product Category :LIGHT VEHICLES Manufacturer :BMW OF NORTH AMERICA, LLC Make :BMW Model :X6 Model Year :2011 Type :PASSENGER CAR	Passenger	19-SEP-2008	26-OCT-2010
Product Type :VEHICLE Product Category :LIGHT VEHICLES Manufacturer :BMW OF NORTH AMERICA, LLC Make :BMW Model :X6 Model Year :2008 Type :PASSENGER CAR	Passenger	19-SEP-2008	26-OCT-2010
Product Type :VEHICLE Product Category :LIGHT VEHICLES Manufacturer :BMW OF NORTH AMERICA, LLC Make :BMW Model :5-SERIES GRAN TURISMO Model Year :2011 Type :PASSENGER CAR	Passenger	01-SEP-2010	26-OCT-2010
Product Type :VEHICLE Product Category :LIGHT VEHICLES Manufacturer :BMW OF NORTH AMERICA, LLC Make :BMW Model :X5 Model Year :2008 Type :PASSENGER CAR	Passenger	02-FEB-2008	26-OCT-2010

Component Name

EQUIPMENT:OTHER:LABELS

Influencing Investigation(s)

Investigation Num	Subject	Investigator	Relationship
-------------------	---------	--------------	--------------

Related Recalls

Yr	Type	Major Sub	Relationship
----	------	-----------	--------------

Recall Characteristics

Unique Recall	Unique Descr
---------------	--------------

Recall Communications

Fax Ack:	Letter Ack: 05-NOV-2010
Draft 577 Received:	Draft 577 Approved:
Final 577 Received:	Owner Notification:
Phased: N	577 End:
Renotification:	Envelope Approved:
Dealer Notification Received:	Dealer Notification: