Part 573 Safety Recall Report

Manufacturer Name :Ride The Ducks International LLCSubmission Date :NOV 22, 2016NHTSA Recall No. :16V-859Manufacturer Recall No. :NR



16V-859

Manufacturer Information :

Manufacturer Name : Ride The Ducks International LLC Address : 2320 W Highway 76 PO BOX 1837 BRANSON MO 65616 Company phone : 417 266 7600

Population :

Number of potentially involved : 57 Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1:	1996-2005 RTDI "Stretch" Amphibious Passenger Vehicles
Vehicle Type :	
Body Style :	
Power Train :	NR
Descriptive Information :	Amphibious Passenger Vehicle
Production Dates :	JAN 01, 1996 - DEC 31, 2005
VIN Range 1:	Begin :NREnd :NRNot sequential

Description of Defect :

Description of the Defect :	The axle housing can fracture at the connection point between the knuckle ball and the housing due to excessive fatigue.
FMVSS 1 :	NR
FMVSS 2 :	NR
Description of the Safety Risk :	If the axle housing fractures, the driver may lose control of the vehicle and increase the risk of a crash.
Description of the Cause :	The axle housing can fracture due to excessive fatigue.
Identification of Any Warning that can Occur :	

The information contained in this report was submitted pursuant to 49 CFR §573

Supplier Identification : Component Manufacturer Name: NR Address : NR NR Country: NR **Chronology:** See attached document **Description of Remedy :** Description of Remedy Program : The remedy program applied was set forth in the Service Bulletin issued on October 1, 2013. The remedy involved strengthening the connection where the knuckle housing ball connects to the axle housing. How Remedy Component Differs NR from Recalled Component : Identify How/When Recall Condition RTDI is not currently building or having built new amphibious passenger was Corrected in Production : vehicles. **Recall Schedule :** Description of Recall Schedule : RTDI will send formal customer notification letters to its companyowned operators and licensors as set forth in the Consent Order with NHTSA. To the extent that Ride the Ducks Seattle requests parts to conduct the repair, they are available. Ride the Ducks International will offer reimbursement to any licensor that has already conducted the repairs. Planned Dealer Notification Date : NR - NR Planned Owner Notification Date : NR - NR

* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR §573