

- To Michael Collinsworth/TMS/Toyota@TOYOTA@TMCE, Shigeyuki Tomizuka/TMS/Toyota@Toyota@TMCE
- cc William de Manincor/TMS/Toyota@Toyota@TMCE, Jim Wimmer/TMS/Toyota@Toyota@TMCE, Kenzo_Nishiwaki@toyota.com, Yutaka

bcc

Subject ES350 Rubber floor mat issue

Hello Tomizuka-san

Thank you for your information of captioned issue by telephone. I have reported outline of this issue for our Monthly quality meeting today. Yoshie-san said "Is F/Fix only ES350?" Yoshie-san worries other vehicle is ok or not. You should study it using extensive knowledge.

My memory, there were same situation for Prius last year too.

Best regards,			
******	Followed by Japanese	*****	***

TMC CADD Engineering Administration Dept Tel 0561-74-4665 Ext. 8-41-4665 Fax 0561-74-4966 Ext. 8-41-4966 IIE-Maill Fukunori_ito@mail.toyota.co.jp

2007/03/26 18:04

Hello Michael-san

I was informed the captioned issue by CQE person and Tomizuka-san last Friday. If you have a detail action of this issue, please let us know. I heard TMS PQSS discussed to make some campaign letter to customer.

Have those problem vehicle genuine accessory rubber floor mat? I would like to confirm that ES350 genuine rubber mat has two clip holes and with clips or not.

When you will implement a customer campaign for this issue, you should ask CADD a request of it.

Best Regard	ls,	
*****	Followed by Japanese	******
Tomozuta-s	an 🛮 SEC 🛮	
0000000000000000?		

JCQE 01GM0000000 0001Letter 000000000TMS000000 00000TMC000000000000 TMC 000000000000000000CADD00JCQE0000000000

Frank <Fukunori> Ito Quality Group
TMC CADD Engineering Administration Dept
Tel 0561-74-4665 Ext. 8-41-4665
Fax 0561-74-4966 Ext. 8-41-4966

@E-Maill Fukunori_ito@mail.toyota.co.jp