

01-022-N11B-8058 NSA

RMC

REMCO MOTOR COMPANY, INC.
4142 SOUTH 89TH STREET, OMAHA, NE 68127
PHONE (402) 339-6666

September 11, 1998

Administrator
National Highway Traffic
Safety Administration
400 Seventh Street, S. W.
Washington, D.C. 20590

ORIGINAL

2 pp

03 SEP 23 09:45

RECEIVED NSA-30

Attention: VIN Coordinator

Dear Sir:

A letter was originally submitted on December 16, 1992 as required by Title 49, Part 565.5 of the Code of Federal Regulations together with a chart for deciphering the remaining characters. A revision of the chart was also sent on November 10, 1994.

We would now like to ammend the chart effective with the 1999 model year.

Enclosed is the new chart. If this information is not satisfactory please notify me.

Sincerely,



Herbert C. Glesmann
President
enc:

EXECUTIVE SECRETARIAT
1998 SEP 21 PM 1:21
NATIONAL HIGHWAY
TRAFFIC SAFETY ADMIN.

1000

1999 REMCO MOTOR COMPANY, INC.

VEHICLE IDENTIFICATION NUMBERING (VIN) SYSTEM
17 Characters

