

IPY
Crown COACH CORPORATION

B
7/12/84 EW

RECEIVED

1984 JUL 12 PM 12:40

WYDGE DEFECTS INVESTIGATION

Engineers & Manufacturers

CROWN SCHOOL COACHES, PUBLIC CARRIER AND SPECIAL COACHES, CROWN-IKARUS ARTICULATED COACHES



For Over 75 Years

DISTRIBUTORS OF PREVOST COACHES AND PIERCE AUTO BODIES.

01-22-N11B-1725

July 6, 1984

ORIGINAL

Administrator
National Highway Traffic Safety Admin.
400 Seventh Street, S.W.
Washington, D.C. 90590

Attn: VIN Coordinator

Gentlemen:

This is to inform you of a typographical error on our letter of February 8, 1984, which was submitted to your office.

Page 3 of our letter under Engine type line 18, Detroit Diesel 6-V-92-TAC should read 325 HP rather than 253 HP.

If there are any questions regarding the above information, please feel free to contact me at (213) 627-4021.

Thank you for your attention to this matter.

Sincerely,

William R. Long
Director of Engineering

WRL:rtv

84 NOV 29 11:45

RECEIVED
NHTSA DOCKET

EMITICH ALEIWS OLIV
NHTSA
AUTO SAFETY HOTLINE

11 JUL 11 11:52

MAIN EXECUTIVE AND SALES OFFICES 2428 EAST 12TH STREET, LOS ANGELES, CALIFORNIA 90021
PARTS AND SERVICE DIVISION 2441 EAST 12TH STREET, LOS ANGELES, CALIFORNIA 90021

PHONE (213) 627-4021
PHONE (213) 627-4021
PARTS COUNTER: (213) 489-5152
TWX: 1-910-321-2368