

Emol

B 10/16/90
pdf

Burdick Bros. Machine & Repair

111 9TH AVENUE WEST REDFIELD, SOUTH DAKOTA 57469
(605) 472-2038

ORIGINAL

01-22-N11B-3942

March 30, 1990

Administrator
Nat'l Hiway Traffic Safety Admin.
400 7th St. SW
Washington, DC 20590

3 pp

Attn: VIN Coordinator

Enclosed please find the information necessary to decipher the characters contained in our Vehicle Identification Numbers that meet the requirements of Federal Safety Std MVSS-115.

Please see the attached copy of letter dated January 30, 1990 from the Engineering Society for Advancing Mobility Land, Sea, Air and Space, as NHTSA agent, assigning characters 1, 2, 3 and 12, 13, 14 of the VIN.

Sincerely,



James Burdick

Att (1)
Encl (1)

90 OCT 25 AM 12

RECEIVED
NHTSA DOCKET

400 COMMONWEALTH DRIVE, WARRENDALE, PA 15096-0001 U.S.A.
(412) 776-4841 FAX NO. (412) 776-5760

CABLE ADDRESS: SOCAUTOENG. PA
TELEX NO. 866-355

January 30, 1990

Mr. James Burdick
Burdick Bros. Machine & Repair
111 9th Avenue W.
Redfield, SD 57469

Dear Mr. Burdick:

This letter confirms our telephone conversation of January 16, 1990 regarding the assignment of a World Manufacturer (Maker) Identifier (WMI) Code. As the agent of the NHTSA for the assignment of manufacturer identifiers pursuant to CFR 49 Part 565.5C Vehicle Identification Number (VIN), we hereby confirm the following code:

Burdick Bros. Machine & Repair
111 9th Avenue W.
Redfield, SD 57469
United States

1 B 9 with the 3rd, 4th, and 5th
characters of the Vehicle
Indicator Section to be
2 4 0

Trailers

Sincerely,

Betty Lou Schattauer
Betty Lou Schattauer
WMI Coordinator

/bls

Enclosure

cc: A. Burgett
B. P. Hickey

