



Technical Structures Inc.
Commercial Modular Manufacturer

January 8, 2009

National Traffic Safety Administration (NHTSA)
Office of Vehicle Safety & Standards

Re: Incorrectly computed VIN number

This is to inform you that the following VIN number 1T9B22825ZV280397 was incorrectly computed. The corrected VIN number should be 1T9B228252V280397.

Sincerely Yours,

A handwritten signature in black ink, appearing to read 'D. Hulen', written over a horizontal line.

David S. Hulen
General Manager