



ERR195



Automotive Safety Office
Environmental and Safety Engineering

Fairlane Plaza South
330 Town Center Drive
Dearborn, MI 48126-2738 USA

June 16, 2010

Mr. David Strickland
Administrator
National Highway Traffic Safety Administration
1200 New Jersey Avenue
Washington, DC 20590

Attention: VIN Coordinator

Subject: Modification of Certain 2010 Model Year E-350 Econoline cutaways.

This is to inform the agency that due to a dealership ordering error Ford Motor Company (Ford) has recently modified three 2010 model year E-350 Econoline cutaways, revising the GVWR weight class to a level different from that indicated by the character "S" in the VIN.

Ford has revised the GVWR on three vehicles (VINs 1FDSE3FL8ADA54102, 1FDSE3FLXADA54103 and 1FDSE3FL1ADA54104) from 10,000 to 11,500 lbs. The modifications took place at a final stage manufacturer and were witnessed by Ford representatives. The modifications included changing the front springs (from 3900 lbs to 4050 lbs capacity) and revising the Ford Incomplete Vehicle Certification Label and the Certificate of Origin for a Vehicle. The modifications were necessary because a dealership ordering error resulted in the vehicle not being suitable for completion in the intended manner without modifications.

If there are any questions regarding this VIN information, please contact me.

Sincerely,

A handwritten signature in cursive script that reads "R. A. Nevi".

R. A. Nevi
Assistant Director
Global Automotive Safety Compliance

