



FAX958

Bob Johnson
Sr. Designer 1
Compliance and Regulatory Affairs

DAIMLER

Daimler Trucks North America LLC
4747 N. Channel
Portland, Oregon 97217-7699
503-745-5076 Phone
503-745-5544 Fax
Bob.Johnson@Daimler.com

January 28, 2011

National Highway Traffic Safety Administration
Attention: Vincent Dileonardi
Via Fax (202) 493-0073

Subject: Amended VIN Coding

In accordance with Part 565.7, Daimler Trucks North America submits the following new VIN deciphering information. Please list these changes under the WMI of 5KK and 5KJ.

VIN position 5 and 6 Model, Cab, GVWR for Western Star

<u>Code</u>	<u>Model</u>	<u>Cab</u>	<u>GVWR</u>
BG	5900 Set back Axle	Conventional	26,001 to 33,000 pounds Class 7
BH	5900 Set back Axle	Conventional	33,001 Pounds and over Class 8
BJ	5900 Set back Axle Glider	Conventional	Glider

You may call me at (503) 745-5076 or fax at (503) 745-5544 if more information is needed.

Please note that as of January 7, 2008, Freightliner LLC changed their name to Daimler Trucks North America LLC.

Sincerely,



Bob Johnson
Sr. Designer 1