

From: Ryan Black/=TMS/Toyota. Sent:9/28/2007 5:00 PM.
To: [-] Andrew Curtin/=TMS/Toyota@Toyota.
Cc: [-] Gary Heine/=TMS/Toyota@Toyota.
Bcc: [-]
Subject: Fw: GRESHAM TOYOTA-SCION, 4T1BE46K77U [REDACTED] 2007 Camry, DTC: None. TA Case # TA072710338..

07 camry unintentional acceleration
aftermarket floor mats installed

Ryan Black
Quality Assurance Powertrain
Product Quality & Service Support
Toyota Motor Sales, U.S.A. Inc.
Office: 310.468.1355
Fax: 310.974.5745

----- Forwarded by Ryan Black/TMS/Toyota on 09/28/2007 04:57 PM -----

Ryan M Black <ryan_black@toyota.com>
09/28/2007 04:56 PM
Please respond to

To ryan_black@toyota.com

cc

Subject GRESHAM TOYOTA-SCION, 4T1BE46K77U [REDACTED] 2007 Camry, DTC: None. TA Case # TA072710338.

TAS Case TA072710338 has been forwarded to you for information and reference purposes. For further details please log into the T3 system.

4T1BE46K77U [REDACTED] 2007 Camry
36045: GRESHAM TOYOTA-SCION
DTC: None
Symptom Descriptions: None

[http://t3.tmsnet.toyota.com/t3Portal/portlets/tas/caseEditor/viewonly/TasCaseViewOnlyController.portlet?
tasCaseNumber=TA072710338&_portlet.skin=t3&_portlet.skinPath=/framework/skins/&_portlet.theme=wht3d&_portlet.title=TA072710338&viewcase=true](http://t3.tmsnet.toyota.com/t3Portal/portlets/tas/caseEditor/viewonly/TasCaseViewOnlyController.portlet?tasCaseNumber=TA072710338&_portlet.skin=t3&_portlet.skinPath=/framework/skins/&_portlet.theme=wht3d&_portlet.title=TA072710338&viewcase=true)