

[Redacted]

No	MY	Model	VIN	List date	Complain data
1	2005	Tacoma	5TELU42N45Z [Redacted]	10/22/2007	10/22/2007
2	2007	Tacoma	5TEKU72N77Z [Redacted]	10/19/2007	10/19/2007
3	2007	Tacoma	3TMJU62N97M [Redacted]	10/19/2007	7/25/2007
4	2007	Tacoma	5TETU62N07Z [Redacted]	10/19/2007	6/29/2007
5	2006	Tacoma	5TEMU52N86Z [Redacted]	10/24/2007	10/24/2007
6	2007	Tacoma	5TEMU52N06Z [Redacted]	10/25/2007	
7	2007	Tacoma	5TENX22N07Z [Redacted]	10/26/2007	10/26/2007

Condition (TAS Call)	Mile	Purchase date	Incident date	Engine
The comment on the repair order, "Customer states when hitting the brakes the engine will accelerate. Customer states has had this happen three times. Has happened twice in reverse and once in fourth gear (automatic transaxle)." The technician is unable to duplicate this concern. TRD carpeted floor mats and were retained when the vehicle was received. The dealer has the truck for the day.	33845	4/12/2005	10/22/2007	1GR
throttle stuck wide open while passing another vehicle	16200	10/31/2006	6/8/2007	1GR
Gas pedal got stuck. 07/22/07 Cust driving on highway in slow lane, went to pass someone, accelerated like normal but gas pedal pushed itself to the floor (like when c/c takes over) & got stuck. C/C button was on but cruise control not activated. RPM was redlining @ 7000 & veh was trying to go 120 mph but cust pushed both feet on brakes & was burning rubber @ 60 mph. Cust tried to pump brakes but veh began accelerating again so		4/30/2007	7/22/2007	1GR
07 tacoma. when shifting gears at highway speed engine rpm does not lower the same as other vehicles customer has owned.	3660	6/29/2007	7/14/2007	1GR
The customer has experienced high idle.	46642	1/7/2006	10/24/2007	1GR
07 Tacoma and advised was pulling out of parking and vehicle just took off it accelerated. He advised the accelerated stuck.		3/30/2006	7/14/2007	1GR
cust states the engine rpm does not drop from 2500rpm 15 sec when shifting 4th to 5th.(speed range is 55-60 mph) condition has been changed after clean the throttle and disconnect battery.but problem came back after few test drive. the condition doesn't related the engin temperature. only it does 4 th and 5th gear and have to be drive.other 2007 tacome (2TR -MT) did not have this issue. 車速50mph以上のシフト4速→5速時 ニュートラル状態でエンジン回転が長時間保持し落ちてこない。	601	10/1/2007	10/26/2007	2TR

T/M	fail speed	State	accident	Warranty
A	0	MD	none	none
A	passing	TX	none	none
A	60	GA	none	none
M	60	CA	none	none
A	0	CA	none	none
A	take off	MD	none	none
M	50-60 mph	NJ	none	none