

ORG6824

ORG6824

Bob Johnson
Sr. Designer 1
Compliance and Regulatory Affairs

Daimler Trucks North America LLC
4747 N. Channel
Portland, Oregon 97217-7699
503-745-5076 Phone
503-745-5544 Fax
BobJohnson@freightliner.com

DAIMLER

June 30, 2011

National Highway Traffic Safety Administration
Attention: VIN coordinator

Via Fax (202) 493-0073

Subject: Amended VIN Coding

In accordance with Part 565.7, Daimler Trucks North America submits the following new VIN deciphering information. Please list these changes under the WMI of 1FV and 1FU.

VIN position 5 and 6 Model, Cab, GVWR for Freightliner

| Code | Engine | Fuel | Displacement | config. | brakes |
|------|---------|--------|--------------|---------|--------|
| D5 | DD15 AT | Diesel | 14.8 Liter | I-6 | Air |

You may call me at (503) 745-5076 or fax at (503) 745-5544 if more information is needed.

Please note that as of January 7, 2008, Freightliner LLC changed their name to Daimler Trucks North America LLC.

Sincerely,



Bob Johnson
Sr. Designer 1