

ORG 7805

Bob Johnson
Sr. Designer
Product Compliance

DAIMLER

Daimler Trucks North America LLC
4747 N. Channel
Portland, Oregon 97217-7699
503-745-5076 Phone
503-745-5544 Fax
Bob.johnson@Daimler.com

June 5, 2012

National Highway Traffic Safety Administration
Attention: VIN Coordinator

Via Fax (202) 493-0073

Subject: Amended VIN Coding

In accordance with Part 565.7, Daimler Trucks North America submits the following new VIN deciphering information.. Please list these changes under the WMI of 1FV and 1FU.

VIN position 5 and 6 Model, Cab, GVWR for Freightliner

| Code | Model | Cab | GVWR |
|------|---------|--------------|--------|
| HE | M2 112V | Conventional | Glider |

You may call me at (503) 745-5076 or fax at (503) 745-5544 if more information is needed.

Please note that as of January 7, 2008, Freightliner LLC changed their name to Daimler Trucks North America LLC.

Sincerely,



Bob Johnson
Sr. Designer

Bob Johnson
Sr. Designer 1
Compliance and Regulatory Affairs

DAIMLER

Daimler Trucks North America LLC
4747 N. Channel
Portland, Oregon 97217-7699
503-745-5076 Phone
503-745-5544 Fax
Bob.johnson@Daimler.com

June 5, 2012

National Highway Traffic Safety Administration
Attention: Coleman Sachs

Via Fax (202) 493-0073

Subject: Amended VIN Coding

In accordance with Part 565.7, Daimler submits the following new VIN deciphering information for Freightliner Custom Chassis Corp. Please list these changes under the WMI of 4UZ.

VIN position 5 and 6 Model, Cab, GVWR for Freightliner Custom Chassis

| Code | Description | cab | GVWR |
|------|---|------|-------------------------|
| EH | XBS Straight Rail Rear Engine Shuttle Bus Chassis | None | 33,001 and over Class 8 |

You may call me at (503) 745-5076 or fax at (503) 745-5544 if more information is needed.

Please note that as of January 7, 2008, Freightliner LLC changed their name to Daimler Trucks North America LLC and currently markets vehicles under the Freightliner Custom Chassis Brand.

Sincerely,



Bob Johnson
Sr. Designer 1