

Bob Johnson
Sr. Designer 1
Compliance and Regulatory Affairs

Daimler Trucks North America LLC
4747 N. Channel
Portland, Oregon 97217-7699
503-745-5076 Phone
503-745-5544 Fax
Bob.johnson@daimler.com

DAIMLER

December 10, 2013

National Highway Traffic Safety Administration
Attention: VIN Coordinator
Via Fax (202) 493-0073

Subject: Amended VIN Coding

In accordance with Part 565.7, Daimler submits the following new VIN deciphering information for Freightliner Custom Chassis Corp. Please list these changes under the WMI of 4UZ.

VIN position 7 and 8 Engine, Brakes

Code	Engine	Fuel	Displacement	Configuration	Brakes
E6	Cummins ISB G	CNG	6.7 Liter	I-6	Air
E7	Cummins ISB G	CNG	6.7 Liter	I-6	Hydraulic

You may call me at (503) 745-5076 or fax at (503) 745-5544 if more information is needed.

Sincerely,



Bob Johnson
Sr. Designer 1