

# Fit Up Issue/Results

**Base Information (Required):**

(Note: All Information is required)

<b>Issue ID:</b>	<b>06-0042</b>	<b>Critical Issue:</b> False	<b>Open Date:</b>	<b>02/28/2006 06:00:05 PM</b>
<b>Issue Category:</b>	<b>No Issue</b>		<b>Accessory Level:</b>	<b>Production</b>
<b>Subject:</b>	<b>AW Mats ISIR Fit-Check</b>			
<b>Location:</b>	<b>TMS - Torrance</b>			








**Detail Information (Required):**

(Note: All information (apart from "Comment") is required to close the issue.)

<b>Vehicle Build Level:</b>	1A	<b>Fit Up Date:</b>	02/28/2006
<b>Concern:</b>	<b>Overall fit/function of floor mats</b>		
<b>Vehicle:</b>	ES350	<b>Planned Close Date:</b>	02/28/2006
<b>Vehicle ID:</b>	JTHBJ46G2 [REDACTED]	<b>Fit Up Engineer:</b>	Kiyo Inoue
<b>Accessory:</b>	Floor Mats	<b>Supplier:</b>	Thermoflex
<b>Product Engineer:</b>	Kiyo Inoue		
<b>Proposed Countermeasure:</b>	<b>1. Grommets were added to all passenger locations. Now there will be 2 grommets for each location.</b> <b>2. The shapes changed in all locations, see attached sheets for specifics.</b>		
<b>Comment:</b>	This fit-check was used to kick off the carpeted and all-weather floor mats. The mats were made to the maximum size. K. Ono, Y. Yamaguchi, and Sam Chen participated in the fit-check.		
<b>Actual Countermeasure:</b>	<b>JTHBJ46G8720 [REDACTED] - Fit-checked AW Mat ISIR Samples</b> <b>No issues. All changes were made and the fit was good.</b> <b>Steve Kidani, Dave Molina, Jason Gan, and David James participated in the fit-check.</b>		
<b>NOTE: Actual Countermeasure and Actual Close Date MUST be completed before issue is closed.</b>	<b>Actual Close Date:</b>	02/28/2006	

**Optional Information:**

(Note: All Information is optional)

<b>Attachment(s):</b>	   Rear Right Overall.JPG Accelerator Pedal Depressed.JPG Dead Pedal.JPG    Driver Overall.JPG Driver Pedals.JPG Front Passenger Overall.JPG  Rear Left Overall.JPG	
<b>Concern Description: (Detail)</b>		
<b>Engineer Notes:</b>		
<b>Vehicle Effective Model Year:</b>		
<b>Accessory Launch Date:</b>		
<b>Issue Effect on Launch Date:</b>		



