

01-22-N11B-3481

B 7/18/89
pdy

High View Manufacturing

Randy Ashleson, Owner
Rt. 1 Box 30
Alta Vista, Iowa 50603

ORIGINAL

July 7, 1989

Office of Vehicle Safety Standards, NRM-11
Attention: Ms. Patti Gardner
National Highway Traffic Safety Administration
400 Seventh Street, S.W.
Washington, D.C. 20590

2 pg.

RE: Vehicle Identification Number
New Business

Dear Patti:

To the best of my knowledge I have constructed my first VIN #. 32 foot overall length , flat bed with beaver tail, 2 axles produced in 1989 at Route 1, Alta Vista, IA, 50603, unit # 1. Using the fact sheet sent, I am submitting this number along with High View's coding for vehicle attributes for review; they are as follows:

VIN: 1H9B03220KA162001

Character	1,2,3; 12, 13, 14	WMI#1H9162 SAE Assigned 7/7/89 which contained less than 500 units/yr.
Character	4,	F=Flatbed B=F/with beaver tail U=Utility L=Livestock
Character	5,	As discussed wasn't necessary, 0 has been elected.
Character	11,	A=represents plant location. Rt. 1 Box 30 Alta Vista, IA 50603
Character	15, 16, 17	Being the first unit 001 is placed here

/

Vin Number: 1 H 9 B 0 3 2 2 0 K A 1 6 2 0 0 1

VIN Number Breakdown:

- 1H9= WMI SAE Assigned 7-7-89
- B = F=Flatbed B=F/w/beaver tail U=Utility L=Livestock
- 0 = Series none
- 32 = Overall length in feet
- 2 = Number of axles
- 0 = Check Digit
- K = Model year 1989
- A = Plant location
- 162= WMI < 500 units
- 001= Production sequence

Please notify me of any errors, additions and also what date I can sell the first unit.

Thank you,

Randy Ashleson

Randy Ashleson
Owner

2