

566B
~~Sample Unit~~

11-07-94
JS

DESSCO

Diesel Electric Service & Supply Co., Inc.
Industrial Central Distributors

ORIGINAL


652 West 1700 South
Salt Lake City, Utah 84104
Phone 801-972-1836 FAX 801-975-7316

01-22-N11B-5763

National Highway Traffic Safety Administration
Attn: VIN Coordinator, NRM-15 RM 5307A
400 7th Street, S.W.
Washington, D.C. 20590

3p.

August 9, 1994



Subject : WMI Code

Dear Gentlemen,

Enclosed please find our submitted information on our VIN number makeup. As well as a trailer sketch reflecting the locations of the VIN stampings.

In regards to part 566-5 paragraphs A & B should be answered by above letterhead.

As per paragraph C, vehicles to be manufactured are small trailers. Utility, auto, equipment, generator, and pump trailers. Gross weights to be less than 10,000 Lbs. estimate in any type trailer.

I trust this information meets the requirements of the letter dated July 21, 1994 from Cathy Douds at WMI.

If you have any questions at all, please feel free to contact me.

Best Regards,

Chuck A. Harris
Vice President
Industrial Sales

DESSCO VIN NUMBER MAKEUP

VIN Numbers are made up of 17 Characters

POSITION

1. WMI Assigned Numbers = 1
2. WMI Assigned Numbers = D
3. WMI Assigned Numbers = 9
4. Type of Trailer : A = Auto Trailer
E = Equipment Trailer
G = Generator Trailer
P = Pump Trailer
U = Utility Trailer
5. Series/Body : F = Flat Bed
S = Flat Bed /Side Boards
V = Van Body
6. Length in Feet : Example : 0
7. Length in Feet : 8 = 8 Ft.
8. Number of Axles :
9. Check Digit : Calculated and Different on every
VIN Number
10. Year Model : See Table
11. Plant Location : A
12. WMI Number Assigned = 2
13. WMI Number Assigned = 6
14. WMI Number Assigned = 8
15. Sequence of Production
16. Sequence of Production
17. Sequence of Production

2

FROM

DESSCO

Diesel Electric Service & Supply Co., Inc.

Phone 801-972-1836
652 West 1700 South
Salt Lake City, Utah 84104

FAX NO. (801) 975-7316

TO: *RENEE JOHNSON SERV.*
 ATTN: *RENEE*
 FROM: *CHUCK*

DATE
<i>OCT 26 94</i>
SUBJECT
<i>SAMPLE VIN</i>

NUMBER OF PAGES INCLUDING THIS ONE 1

Message

*Per your fax, YES THERE WAS AN ERROR
 MADE IN THE LETTER CONVERSION. THE
 FOLLOWING VIN I BELIVE IS CORRECT.
 THANKS FOR YOUR HELP.*

1D9GF0610RA268001



SIGNED