Form Approved: O.M.B. No. 2127-0008

U.S. Department of Transportation

National Highway Traffic Safety Administration

DOT Auto Safety Hotline

Vehicle Owner's Questionnaire

To Report Vehicle Safety Defects
1-888-DASH-2-DOT
(1-888-327-4236)
INTERNET:www.nhtsa.dot.gov/hotline

FOR AGENCY USE ONLY 1058

Date Received	Repository ☐
11-DEC-2006	Reference No. 10176450

OWNER INFORMATION (Type or Print)

Name [redacted]		Daytime Telephone Number [redacted]	E-mail Address [redacted]
Address [redacted]		Evening Telephone Number	
City MELVINDALE	**State** MI	**Zip Code** [redacted]	

Do you authorize NHTSA to provide a copy of this report to the manufacturer of your vehicle? ☐ *YES* ☒ *NO*
In the absence of an authorization, NHTSA WILL NOT provide your name or address to the vehicle manufacturer.
Signature of Owner _____ Date ___/___/___

VEHICLE INFORMATION

17 digit Vehicle Identification Number Located at bottom of windshield on driver's side	Make	Model	Model Year
JTHBJ46G372[redacted]	LEXUS	ES350	2007

Date Purchased	Dealer's Name and Telephone Number			Engine: No: Cylinders	Fuel Type:
Original Owner ☐	Dealer's City	State	Zip Code		

Transmission Type	☐ Antilock Brakes ☐ Cruise Control	Powertrain	Vehicle Component Code 180000 VEHICLE SPEED CONTROL
			Multiple Failure: 1

FAILED COMPONENT(S)/PART(S) INFORMATION

Incident Date(s)	Failure Mileage	Failure Speed
02-SEP-2006	4100	55

ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A TIRE FAILURE

Tire Make	Tire Model (Name or Number)	Tire Size (Example P215/65R15)
DOT No. (Example: DOTMAL9ABC036)	☐ Original Equipment ☐ Prior Repair	Failure Location:
Tire Component Code		Tire Failure Type

ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A CHILD SEAT FAILURE

Make:	Date Manufactured:	Model No./Name:
Seat Type:	Installation System:	
Child Seat Component Code:	Failed Part:	

APPLICABLE INCIDENT INFORMATION
(Please describe in detail the incident(s), Failure(s), Crash(es), and injury(ies).)

Crash	Fire	Number of Persons Iniured	Number of Deaths	Reported to Police
☒ Yes ☐ No	☐ Yes ☒ No	1		Y

Narrative Description of Incident(S), Crash(es), and Injury(ies).
Please describe (1) events leading up to the failure, (2) failure and its consequences, and (3) what was done to correct the failure; i.e, parts repaired or replaced (and if old part is available).

CONSUMER REQUEST FOR INVESTIGATION ON THE 2007 ES350 SPEED CONTROL. *TS☐
THE CONSUMER STATED THE VEHICLE SUDDENLY ACCELERATED, AFTER ATTEMPTING TO APPLY THE BRAKES. THE UNWANTED ACCELERATION CAUSED THE VEHICLE TO CRASH INTO THE HIGHWAY GUARD RAIL AND CONSEQUENTLY THE VEHICLE ROLLED OVER. THE CONSUMER SUFFERED SERIOUS BACK, NECK AND PELVIC INJURIES. *JB☐
☐
UPDATE (FEBRUARY 21, 2007): [redacted] SAID THAT SHE WAS TRAVELING ON I-75 FOR 15 MINUTES AND THE CRUISE CONTROL WAS NOT TURNED ON. SHE WAS MERGING ONTO ROUTE 59 AND APPLIED THE BRAKES. HOWEVER, THE VEHICLE NOT ONLY NOT SLOWED DOWN BUT ACTUALLY ACCELERATED TO WHAT SHE BELIEVE WAS 75-80 MPH. TO AVOID CRASHING THE VEHICLES AHEAD, SHE MOVED FROM THE RIGHT LANE TO THE LEFT LANE AND HIT THE GUARD RAIL. THE VEHICLE ROLLED OVER AND TOTALED. SHE WAS CITED BY THE POLICE BUT THE CITATION WAS LATER DISMISSED. TOYOTA SENT HER A LETTER SAYING THAT THEIR INVESTIGATION FOUND NOTHING WAS WRONG WITH THE VEHICLE. SEE ALSO 10174732 *DSY.

Include, if available: Police/Fire Department Report, Photos, and Repair Invoice. ATTACH ADDITIONAL SHEETS IF NECESSARY

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond this questionnaire. Your response may be used to assist the NHTSA in determining whether a Manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.