



U.S. Department  
of Transportation

**National Highway  
Traffic Safety  
Administration**

**DOT Auto Safety Hotline**  
**Vehicle Owner's Questionnaire**  
**To Report Vehicle Safety Defects**  
**1-888-DASH-2-DOT**  
**(1-888-327-4236)**  
**INTERNET:www.nhtsa.dot.gov/hotline**

FOR AGENCY USE ONLY 100148

Date Received

24-OCT-2006

Repository

Reference No.  
10171756

**OWNER INFORMATION (Type or Print)**

<b>Name</b> [REDACTED]			<b>Daytime Telephone Number</b> [REDACTED]		<b>E-mail Address</b> [REDACTED]	
<b>Address</b> [REDACTED]			<b>Evening Telephone Number</b> [REDACTED]			
<b>City</b> TOLEDO		<b>State</b> OH	<b>Zip Code</b> [REDACTED]			

Do you authorize NHTSA to provide a copy of this report to the manufacturer of your vehicle?  YES  NO  
In the absence of an authorization, NHTSA WILL NOT provide your name or address to the vehicle manufacturer.

Signature of Owner \_\_\_\_\_ Date \_\_\_\_/\_\_\_\_/\_\_\_\_

**VEHICLE INFORMATION**

17 digit Vehicle Identification Number Located at bottom of windshield on driver's side JTHCK262265 [REDACTED]			<b>Make</b> LEXUS		<b>Model</b> IS250		<b>Model Year</b> 2006		
<b>Date Purchased</b> 16-MAR-06		<b>Dealer's Name and Telephone Number</b> LEXUS OF TOLEDO 419-841-3500				<b>Engine:</b> No: Cylinders 6		<b>Fuel Type:</b> Gas	
<b>Original Owner</b> <input checked="" type="checkbox"/>		<b>Dealer's City</b> TOLEDO		<b>State</b> OH	<b>Zip Code</b> 43517				
<b>Transmission Type</b> AUTOMATIC		<input checked="" type="checkbox"/> Antilock Brakes <input checked="" type="checkbox"/> Cruise Control		<b>Powertrain</b> ALL WHEEL DRIVE		<b>Vehicle Component Code</b> 180000 VEHICLE SPEED CONTROL			
						<b>Multiple Failure:</b> 1			

**FAILED COMPONENT(S)/PART(S) INFORMATION**

<b>Incident Date(s)</b> 20-OCT-2006		<b>Failure Mileage</b> 5310		<b>Failure Speed</b> 65					
--	--	--------------------------------	--	----------------------------	--	--	--	--	--

**ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A TIRE FAILURE**

<b>Tire Make</b>		<b>Tire Model (Name or Number)</b>			<b>Tire Size (Example P215/65R15)</b>		
<b>DOT No. (Example: DOTM19ABC036)</b>		<input type="checkbox"/> Original Equipment <input type="checkbox"/> Prior Repair		<b>Failure Location:</b>			
<b>Tire Component Code</b>					<b>Tire Failure Type</b>		

**ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A CHILD SEAT FAILURE**

<b>Make:</b>		<b>Date Manufactured:</b>		<b>Model No./Name:</b>	
<b>Seat Type:</b>		<b>Installation System:</b>			
<b>Child Seat Component Code:</b>			<b>Failed Part:</b>		

**APPLICABLE INCIDENT INFORMATION**

(Please describe in detail the incident(s), Failure(s), Crash(es), and injury(ies).)

<b>Crash</b> <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		<b>Fire</b> <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		<b>Number of Persons Injured</b>		<b>Number of Deaths</b>		<b>Reported to Police</b> Y	
---	--	--	--	----------------------------------	--	-------------------------	--	--------------------------------	--

**Narrative Description of Incident(S), Crash(es), and Injury(ies).**

Please describe (1) events leading up to the failure, (2) failure and its consequences, and (3) what was done to correct the failure; i.e. parts repaired or replaced (and if old part is available).

WIFE WAS DRIVING ON THE INTERSTATE WITH THE CRUISE ON DOING ABOUT 65 MPH, AND SHE DECIDED TO PASS A TRUCK. SHE ACCELERATED SLIGHTLY, AND THE CAR SUDDENLY "FLOORED" TO OVER 90 MPH AND THE RPM'S WENT ALL THE WAY UP. SHE TRUNED OFF THE CRUISE, BUT IT WOULDN'T SLOW DOWN. SHE TRIED TO BRAKE, BUT THE ENGINE WAS STILL REVING AT THE HIGHEST SPEED. SHE FORCED HERSELF OFF INTO THE GRASSY MEDIAN AND SAT ON THE BRAKE UNTIL SHE COULD JAM THE TRANSMISSION INTO PARK AND TURN OFF THE ENGINE. VEH TOWED TO LEXUS DEALER. TECH COULDN'T FIGURE OUT WHAT WAS CAUSING THIS, BUT AFTER TALKING TO LEXUS HEADQUARTERS, THEY FOUND THAT THE RUBBER CAR MAT AND THE BACK OF THE ACCELERATOR SOMEHOW CONNECTED AND FORCED THE CAR TO BE "FLOORED". YOU COULD NOT TELL BY LOOKING AT THE MAT THAT IT WAS CONNECTED TO THE ACCELERATOR. MY WIFE WOULD OF DIED IF THERE HAD BEEN ANOTHER VEHICLE CLOSE TO HER. NO ACCIDENT OR INJURY. I HAVE NO COMPLAINT WITH THE DEALER. THEY DID EVERYTHING THEY COULD TO HELP. \*NM

Include, if available: Police/Fire Department Report, Photos, and Repair Invoice. ATTACH ADDITIONAL SHEETS IF NECESSARY

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a Manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.